

ASS. REC. BY:

REF: CS/INC 19006305/TI+d302

Special Instruction:

Surveyor:

Tun Bich

ASSIGNMENT (Office)

From (Person):

Annie Koh

of

INC

Date/Time:

9/1/19 @ 9:24am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLC 6230E

Insured:

SGY 33231

at Workshop m/s

Vermogen

Tel.

63583031

of

6 Benoi Road

Policy No:

Claim No:

MT/1039198-002

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A

5/4/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 10:11am @ 9/1/19

Person Contacted:

pila

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLC 6230E-X

SGY 33231 - X ...

30/5/19 - Lump Sum \$4400 cred: 180ab75, 80% confirmed

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 9 April 2019 1:48 PM
To: 'assignments@lkkauto.com'
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Hi LKK,

Please take note of the Olc and claim number for GBE6149R and SLK9014B.

1	FIONA SHEN	MT/0954065-002	GBE6149R	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595	FBB4174X	15/7/17
5	JARED LIU	MT/1033601-002	SLK9014B	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Daniel / 63621776	SLC4150R	25/2/19

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 9 April 2019 10:44 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



Denise Tay (LKKAUTO)

From: Minoko Chan <minoko@vermogen-group.com>
Sent: Thursday, 23 May 2019 11:02 AM
To: Taufikh (LKKAUTO)
Cc: Pila Ng; Tezano Exequiel Dawal; Denise Tay (LKKAUTO); Baldoz Juan Paulo Bongon; Vmg admin; Vermogen Ace; Luis Tan; Glorioso Eric Paul Patambang; Edmond Lim
Subject: Re: SLC6230E FINALISE

Without prejudice

Dear Taufik,

We agreed to accept your revised COR @ Lump Sum \$ 4,400.00 & 5 repair days (excluding PRS/RS/Weekend & PH).

Thank you.

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

On Thu, May 16, 2019 at 5:55 PM Taufikh (LKKAUTO) <Taufikh@lkkauto.com> wrote:

Hi Minoko,

Refer attached.

COR I/s\$4400 , 5 days.

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 9 April 2019 2:20 PM
To: Admin-D (LKKAuto); assignments
Cc: SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Hi LKK,

Please take note of the OIC and claim number for PA8482U**

4	SERENE LIM	MT/1039440-001	PA8482U	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	Winnie Chai / 9850-9666	14:00- 16:00
---	---------------	----------------	---------	-----------	--	----------------------------	-----------------

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 9 April 2019 2:01 PM
To: Annie Koh <annie.koh@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Dear Annie,

Thank you for the assignment.

Please be informed that PA8482U (Connect 3) is not in the workshop, repairer arrange on 10/04/2019.

Best Regards,

G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annie Koh
Sent: Tuesday, 9 April 2019 9:24 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA
1		PENDING ADVISE	GBE6149R	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595		FB84174X	15/7/17
2	AZHARI	MT/1039198-002	SLC6230E	VERMOGEN ACE PTE LTD	6 BENOI ROAD, SINGAPORE 629904	Pila / 6358 3031		SGY3323J	5/4/19
3	DAVID PHUA	MT/1039006-002	SMC166K	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 6266 0555		SLQ4302X	4/4/19
4		PENDING ADVISE	PA8482U	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	Winnie Chai / 9850-9666	14:00-16:00	FBN5354Z	22/3/19
5		PENDING ADVISE	SLK9014B	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Daniel / 63621776		SLC4150R	25/2/19

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
 Senior Admin Assistant, Motor Insurance
 T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SLC6230E		
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	SIENTA 1.5X A		
Chassis No. :	NSP1707024928		
Propellant :	Petrol		
Engine No. :	2NR8592066		
Engine Capacity :	1496 cc		
Maximum Power Output :	80.0 kW (107 bhp)		
Maximum Laden Weight :	1705 kg		
Unladen Weight :	1320 kg		
Year Of Manufacture :	2016		
Original Registration Date :	20 May 2016		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$45,504.00		
COE Expiry Date :	19 May 2026		
Road Tax Expiry Date :	19 May 2019		
PARF Eligibility Expiry Date :	19 May 2026		
Inspection Due Date :	19 May 2021		
Intended Transfer Date :	12 Dec 2019		
CO2 Emission :	119.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$10,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 20 May 2019 to 19 Nov 2019)			
	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	341.00	-	341.00
Total Amount Payable :			366.00
Amount Payable (From 20 May 2019 to 19 May 2020)			
	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	682.00	-	682.00
Total Amount Payable :			707.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2019 13:32
Date Of Accident	05/04/2019 21:10
Exact Location Of Accident	BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC6230E
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	19-MK000197-R00
Cover Note Number	

Driver

Name of Driver	EVAN JAMES TEOH
NRIC No	S9608637G
Date Of Birth	13/03/1996
Occupation	OUTDOOR
Date Of Driving Pass	25/07/2017
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 6 BENOI SECTOR

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO FOLLOWING ATTACHED, THANK YOU.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGY3323J

Vehicle Make/Model/Colour

Details Of Properties VEHICLE B

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Bukit Timah Rd

SKETCH PLAN

A-SLL6230E
B-S6Y3323J



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Bukit Timah Rd, I was driving on the first lane, suddenly vehicle B filtered to my lane as he is trying to filter in to the slip road hence collided on to my vehicle front left portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9608637G



Name
EVAN JAMES TEOH
赵奕文
Race
CHINESE
Date of birth
13-03-1996
Sex
M
Country of birth
SINGAPORE

4707642

VMG USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S9608637G

EVAN JAMES TEOH

Birth Date: 13 Mar 1996
Issue Date: 25 Jul 2017



002707046E

4707642



NRIC No. S9608637G



Date of issue
11-04-2011

APT BLK 61A STRATHMORE AVENUE #17-08
SINGAPORE 142081

NRIC No: S9608637G Date: 01/11/2018

VMG USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg 25 Jul 2017

NP 428A

Licence No: S9608637G





SLC6230E

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : NTUC

OWN INSURER : TMIS

CLAIM TYPE : TP

Date of Accident : 5/4/2019

Vehicle Reg. No. : SLC6230E

Vehicle Reg. Date: 20-May-2016

Make / Model : T.SIENTA 1.5X A

Engine No. : 2NR8592066

Chassis No. : NSP1707024928

COST OF CLAIMS

Parts Cost / List Items :	\$	18,380.00
Plus/Less <u>25%</u>	\$	4,595.00
Total Cost / List :	\$	13,785.00
Special Nett Items :	\$	950.00
Total Parts Amount :	\$	14,735.00
Total Labour Amount :	\$	6,290.00
Gross Total :	\$	21,025.00
GST % : <u>7%</u>	\$	1,471.75
Nett Amount :	\$	22,496.75

Signature 11/4/19

Surveyor Name and Company :

Tan Jiah 97493749

Date of survey : 9/4/19 2:12pm

Part by Part / Lump Sum : 4-5 days

Resurvey Before Paint / After Paint After

Authorize/Not Authorize/Without Prejudice Without

Email : gve@kkauto.com

Fax No : _____

HP No : _____

This claim is handled by : MINOKO

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6230E**

Vehicle Reg. Date: **20/5/2016**

Make / Model : **T.SIENTA 1.5X A**

Engine No. : **2NR8592066**

Chassis No. : **NSP1707024928**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Bonnet	x	\$ 656.00		
2	1	Bonnet lock	x	\$ 91.00		
3	1	Bonnet hinge LH	x	\$ 65.00		
4	1	Bonnet hinge RH	x	\$ 65.00		
5	1	Bonnet heat insulator	x	\$ 271.00		
6	1set	Bonnet heat insulator clips	x	\$ 50.00		
7	1	Headlamp LH	cre	\$ 1,650.00	1287-50	
8	1	Headlamp panel LH	Ry	\$ 77.00		
9	1	Front bumper	de	\$ 340.00		
10	1set	Front bumper clips	de	\$ 50.00		
11	1	Front bumper side retainer LH	de	\$ 46.00		
12	1	Front bumper upper beam	x	\$ 25.00		
13	1	Front bumper sponge	x	\$ 70.00		
14	1	Front bumper reinforcement	x	\$ 347.00		
15	1	Front bumper lower rubber	x	\$ 251.00		
16	1	Front bumper lower cover	x	\$ 125.00		
17	1	Front bumper fog lamp garnish LH	de	\$ 113.00		
18	1	Front fender LH	bt	\$ 551.00		
19	1	Front fender inner shield LH	de	\$ 167.00		
20	1	Front fender inner shield clip LH	de	\$ 50.00		
21	1	Front fender wheel house LH	x	\$ 77.00		
22	1	Front fender apron panel LH	x	\$ 574.00		
23	1	Front fender apron extension LH	x	\$ 43.00		
24	1	Front fender quarter garnish LH	x	\$ 87.00		
25	1	Front windscreen pillar garnish LH	x	\$ 152.00		
26	1	Front door LH	Ry	\$ 1,112.00		
27	1	Front door hinge(top) LH	x	\$ 67.00		
28	1	Front door hinge (bottom) LH	x	\$ 67.00		
29	1	Front door checker LH	x	\$ 127.00		
30	1	Rocker panel LH	x	\$ 364.00		
31	1	Front grille	x ant	\$ 840.00	520.10	
32	1	Front grille retainer	x	\$ 125.00		
33	1	Front grille tow cover	x	\$ 19.00		
34	1	Front griller logo	x	\$ 63.00		
35	1	Support panel	x	\$ 1,097.00		
36	1	Support panel top garnish	x	\$ 125.00		
37	1	Support panel top garnish Clip	x	\$ 50.00		
38	1	Brace panel	x	\$ 128.00		
39	1	Front crossmember	x	\$ 1,618.00		
40	1	Front shock Absorber LH	385	\$ 417.00	btv	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6230E**

Vehicle Reg. Date: **20/5/2016**

Make / Model : **T.SIENTA 1.5X A**

Engine No. : **2NR8592066**

Chassis No. : **NSP1707024928**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Front shock absorber top mount LH	X	\$ 153.00	3X nn	
42	1	Front shock absorber dust cover LH	X	\$ 49.00		
43	1	Front lower arm LH	? 325	\$ 617.00	bt	
44	1	Front wheel bearing LH	X	\$ 125.00	bt	
45	1	Front wheel hub LH	X	\$ 237.00	bt	
46	1	Front knuckle arm LH	? 315	\$ 404.00	bt	
47	1	Drive shaft LH	X	\$ 1,470.00		
48	1	Stabilizer bar	X	\$ 375.00		
49	2	Stabilizer bar bush	X	\$ 164.00	3X nn	
50	1	Stabilizer bar linkage LH	X	\$ 125.00		
51	1	Tie rod end LH	X	\$ 117.00		
52	1	Steering rack & pinion	X	\$ 1,587.00		
53	1	Front ABS sensor LH	X	\$ 157.00		
54	1	Front fender inner protector LH	X	\$ 67.00		
55	1	Front tyre LH	X	\$ 350.00	X nn	
56	1	Front rim LH	new Rep	\$ 60	sn	
57	1	CVT OIL	X	\$ 150.00	X nn	
58	1	FRONT RIM COVER LH	new	\$ 175.00		
59	1	FRONT FOGLAMP COVER LH	? new	\$ 111.00	nn	
60	1	FRONT FOGLAMP LH	new	\$ 235.00		
61	0	0				
62	0	0				
63	0	0		5078.60		
64	0	0		25% - 3808.95		
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6230E**Vehicle Reg. Date: **20/5/2016**Make / Model : **T.SIENTA 1.5X A**Engine No. : **2NR8592066**Chassis No. : **NSP1707024928**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To remove and replace damaged parts and to panel beating accident area.	\$ 2,200.00	600.
2	To putty and respray replaced parts and accident repair area.	\$ 1,800.00	600 700.
3	To check & re-wiring	\$ 150.00	30.
4	To remove & refit front windscreen.	\$ 180.00	X nn
5	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$ 180.00	X nn
6	To remove & refit undercarriage to assist work load.	\$ 280.00	120? ✓
7	To do wheel alignment.	\$ 180.00	60.
8	To do tyre balancing	\$ 150.00	80 X nn
9	To conduct water leakage tests to ensure proper air and sealing	\$ 180.00	X nn
10	To reset fault code	\$ 350.00	100.
11	To spray rust proof	\$ 280.00	30.
12	To remove & install front door RH components	\$ 180.00	X nn
13	To pressure brake test	\$ 180.00	X nn
			1640.

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3808.95

60

1640

5508.95

4584400

5 days #

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM**ATTN TO:**LKK-TAUFIK

Surveyor Name and Company

Date of Accident :

5/4/2019**BILL TO:**NTUC

TP Insurer

VEHICLE REG. NO.**SLC6230E****TYPE OF CLAIM:**TP**Make / Model :**T.SIENTA 1.5X A**COST OF CLAIMS**Parts Cost / List : \$ 6,174.00Supp. Parts : \$ -Special Nett : \$ 60.00Supp. Special Nett : \$ -Total Parts : \$ 4,690.50Total Labour : \$ 1,640.00TOTAL REPAIR COST : \$ - 6,330.50Total Parts Cost/List : \$ 6,174.00Plus / Less : 25% \$ 1,543.50**Total :** \$ 4,630.50Lump Sum Discount : 20% \$ 1,266.10Lump Sum Amount: \$ 5,064.40**Final Lump Sum Amount :** \$ 5,050.00**No. of Repair Days:** 5Submitted by / Date : MINOKO

Confirmed by / Date : _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6230E**

Vehicle Reg. Date: **20/5/2016**

Make / Model : **T.SIENTA 1.5X A**

Engine No. : **2NR8592066**

Chassis No. : **NSP1707024928**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Bonnet		\$ 656.00		
2	1	Bonnet lock		\$ 91.00		
3	1	Bonnet hinge LH		\$ 65.00		
4	1	Bonnet hinge RH		\$ 65.00		
5	1	Bonnet heat insulator		\$ 271.00		
6	1set	Bonnet heat insulator clips		\$ 50.00		
7	1	Headlamp LH		\$ 1,650.00		\$ 1,650.00
8	1	Headlamp panel LH		\$ 77.00		
9	1	Front bumper		\$ 340.00		\$ 340.00
10	1set	Front bumper clips		\$ 50.00		\$ 50.00
11	1	Front bumper side retainer LH		\$ 46.00		\$ 46.00
12	1	Front bumper upper beam		\$ 25.00		
13	1	Front bumper sponge		\$ 70.00		\$ 70.00
14	1	Front bumper reinforcement		\$ 347.00		
15	1	Front bumper lower rubber		\$ 251.00		
16	1	Front bumper lower cover		\$ 125.00		
17	1	Front bumper fog lamp garnish LH		\$ 113.00		\$ 113.00
18	1	Front fender LH		\$ 551.00		\$ 551.00
19	1	Front fender inner shield LH		\$ 167.00		\$ 167.00
20	1	Front fender inner shield clip LH		\$ 50.00		\$ 50.00
21	1	Front fender wheel house LH		\$ 77.00		
22	1	Front fender apron panel LH		\$ 574.00		
23	1	Front fender apron extension LH		\$ 43.00		
24	1	Front fender quarter garnish LH		\$ 87.00		\$ 87.00
25	1	Front windscreen pillar garnish LH		\$ 152.00		
26	1	Front door LH		\$ 1,112.00		
27	1	Front door hinge(top) LH		\$ 67.00		
28	1	Front door hinge (bottom) LH		\$ 67.00		
29	1	Front door checker LH		\$ 127.00		
30	1	Rocker panel LH		\$ 364.00		
31	1	Front grille		\$ 840.00		\$ 840.00
32	1	Front grille retainer		\$ 125.00		
33	1	Front grille tow cover		\$ 19.00		
34	1	Front grille logo		\$ 63.00		
35	1	Support panel		\$ 1,097.00		
36	1	Support panel top garnish		\$ 125.00		
37	1	Support panel top garnish Clip		\$ 50.00		
38	1	Brace panel		\$ 128.00		
39	1	Front crossmember		\$ 1,618.00		
40	1	Front shock Absorber LH		\$ 417.00		\$ 417.00

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6230E**Vehicle Reg. Date: **20/5/2016**Make / Model : **T.SIENTA 1.5X A**Engine No. : **2NR8592066**Chassis No. : **NSP1707024928**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Front shock absorber top mount LH		\$ 153.00		
42	1	Front shock absorber dust cover LH		\$ 49.00		
43	1	Front lower arm LH		\$ 617.00		\$ 617.00
44	1	Front wheel bearing LH		\$ 125.00		\$ 125.00
45	1	Front wheel hub LH		\$ 237.00		\$ 237.00
46	1	Front knuckle arm LH		\$ 404.00		\$ 404.00
47	1	Drive shaft LH		\$ 1,470.00		
48	1	Stabilizer bar		\$ 375.00		
49	2	Stabilizer bar bush		\$ 164.00		
50	1	Stabilizer bar linkage LH		\$ 125.00		
51	1	Tie rod end LH		\$ 117.00		
52	1	Steering rack & pinion		\$ 1,587.00		
53	1	Front ABS sensor LH		\$ 157.00		
54	1	Front fender inner protector LH		\$ 67.00		
55	1	Front tyre LH			\$ -	
56	1	Front rim LH			\$ 60.00	
57	1	CVT OIL			\$ -	
58	1	FRONT RIM COVER LH		\$ 175.00		\$ 175.00
59	1	FRONT FOGLAMP COVER LH		\$ 111.00		
60	1	FRONT FOGLAMP LH		\$ 235.00		\$ 235.00
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6230E**Vehicle Reg. Date: **20/5/2016**Make / Model : **T.SIENTA 1.5X A**Engine No. : **2NR8592066**Chassis No. : **NSP1707024928**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To remove and replace damaged parts and to panel beating accident area.	\$ 2,200.00	\$ 600.00
2	To putty and respray replaced parts and accident repair area.	\$ 1,800.00	\$ 700.00
3	To check & re-wiring	\$ 150.00	\$ 30.00
4	To remove & refit front windscreen.	\$ 180.00	
5	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$ 180.00	
6	To remove & refit undercarriage to assist work load.	\$ 280.00	\$ 120.00
7	To do wheel alignment.	\$ 180.00	\$ 60.00
8	To do tyre balancing	\$ 150.00	
9	To conduct water leakage tests to ensure proper air and sealing	\$ 180.00	
10	To reset fault code	\$ 350.00	\$ 100.00
11	To spray rust proof	\$ 280.00	\$ 30.00
12	To remove & install front door RH components	\$ 180.00	
13	To pressure brake test	\$ 180.00	

Owner:	Date:	09-Apr-19 3:16 PM
Company:	VIN	
Case No:	Technician:	
Printer:	Order No.:	

VEHICLE ALIGNMENT REPORT

TOYOTA, SIENNA, 2015-2016, NSP170G (2WD)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
	Caster	Left	---	4.1°	5.6°	---
		Right	---	4.1°	5.6°	---
	Camber	Left	-0.6°	-0.9°	0.6°	-0.6°
		Right	-0.4°	-0.9°	0.6°	-0.4°
	Toe	Left	3.85°	-0.05°	0.15°	3.85°
		Right	-0.80°	-0.05°	0.15°	-0.80°
		Total	3.05°	-0.10°	0.30°	3.05°
	Camber	Left	-1.5°	-2.2°	-0.7°	-1.5°
		Right	-1.7°	-2.2°	-0.7°	-1.7°
	Toe	Left	0.35°	-0.05°	0.25°	0.35°
		Right	0.10°	-0.05°	0.25°	0.10°
		Total	0.45°	-0.10°	0.50°	0.45°
	Thrust Angle		-0.1°	---	---	-0.1°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
	Left		---	11.4°	11.4°	---
	Right		---	11.4°	11.4°	---
Ack Angle	Left		---	---	---	---
	Right		---	---	---	---
Ack On Turns	Left		---	---	---	---
	Right		---	---	---	---
Ack Turn	Left		---	---	---	---
	Right		---	---	---	---
Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Ack	Front		-0.7"	---	---	-0.7"
	Rear		-0.2"	---	---	-0.2"
Width Diff.			0.2"			0.2"
Base Diff.			-0.5"			-0.5"
Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Ack Angle						---

Customer:
Company:
License No: SL C 6230 E
Meter:

Date: 10-Apr-19 5:23 PM
VIN:
Technician: TEM YONG HOCK
Order No:

VEHICLE ALIGNMENT REPORT

TOYOTA, SIENIA, 2015-2016, NSP170G (2WD)

Primary Angles

		Initial	Specifications		Final
			Min.	Max.	
nt	Caster Left	---	4.1°	5.6°	---
	Right	---	4.1°	5.6°	---
	Camber Left	-0.8°	-0.9°	0.6°	-0.8°
	Right	-0.7°	-0.9°	0.6°	-0.7°
	Toe Left	0.20°	-0.05°	0.15°	0.05°
	Right	-0.25°	-0.05°	0.15°	0.05°
r	Total	-0.05°	-0.10°	0.30°	0.10°
	Camber Left	-1.6°	-2.2°	-0.7°	-1.6°
	Right	-1.8°	-2.2°	-0.7°	-1.8°
	Toe Left	0.30°	-0.05°	0.25°	0.30°
	Right	-0.05°	-0.05°	0.25°	-0.05°
	Total	0.25°	-0.10°	0.50°	0.25°
Thrust Angle		-0.2°	---	---	-0.2°

Secondary Angles

		Initial	Specifications		Final
			Min.	Max.	
aded Angle	Left	---	11.4°	11.4°	---
	Right	---	11.4°	11.4°	---
Out On Turns	Left	---	---	---	---
	Right	---	---	---	---
imum Turns	Left	---	---	---	---
	Right	---	---	---	---
urve Change	Left	---	---	---	---
	Right	---	---	---	---
k	Front	0.1"	---	---	0.1"
	Rear	0.0"	---	---	0.0"
Width Diff.		0.5"			0.5"
Base Diff.		0.1"			0.1"
ide Height	Left	---	---	---	---
	Right	---	---	---	---
de Height	Left	---	---	---	---
	Right	---	---	---	---
ngle					---



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19006305/T1td3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 04-06-2019



ATTN : AZHARI

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGY 3323J	Veh. Inspected	SLC 6230E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1039198-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	09/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA 1.5X A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707024928	Colour	WHITE
Odometer	184603 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	ACHILLES	6 mm
L/H Front Tyre	185/60 R15	ACHILLES	6 mm
R/H Rear Tyre	185/60 R15	ACHILLES	6 mm
L/H Rear Tyre	185/60 R15	ACHILLES	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND UNDERCARRIAGE PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/04/2019	Inspect Date / Time	09/04/2019 (12:00 PM)
Survey held at	6 BENOI ROAD		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 6230E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	NOT NECESSARY	656.00	-
1	BONNET LOCK	NOT NECESSARY	91.00	-
1	BONNET HINGE LH	NOT NECESSARY	65.00	-
1	BONNET HINGE RH	NOT NECESSARY	65.00	-
1	BONNET HEAT INSULATOR	NOT NECESSARY	271.00	-
1	SET BONNET HEAT INSULATOR CLIPS	NOT NECESSARY	50.00	-
1	HEADLAMP LH	CRACKED	1,650.00	1,287.50
1	HEADLAMP PANEL LH	TO REPAIR SEE LABOUR	77.00	-
1	FRONT BUMPER	DEFORMED	340.00	340.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	46.00	46.00
1	FRONT BUMPER UPPER BEAM	NOT NECESSARY	25.00	-
1	FRONT BUMPER SPONGE	DEFORMED	70.00	70.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	347.00	-
1	FRONT BUMPER LOWER RUBBER	NOT NECESSARY	251.00	-
1	FRONT BUMPER LOWER COVER	NOT NECESSARY	125.00	-
1	FRONT BUMPER FOG LAMP GARNISH LH	CUT	113.00	113.00
1	FRONT FENDER LH	BENT	551.00	551.00
1	FRONT FENDER INNER SHIELD LH	DEFORMED	167.00	167.00
1	FRONT FENDER INNER SHIELD CLIP LH	NECESSARY	50.00	50.00
1	FRONT FENDER WHEEL HOUSE LH	NOT NECESSARY	77.00	-
1	FRONT FENDER APRON PANEL LH	NOT NECESSARY	574.00	-
1	FRONT FENDER APRON EXTENSION LH	NOT NECESSARY	43.00	-
1	FRONT FENDER QUARTER GARNISH LH	DEFORMED	87.00	87.00
1	FRONT WINDSCREEN PILLAR GARNISH LH	NOT NECESSARY	152.00	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,112.00	-
1	FRONT DOOR HINGE (TOP) LH	NOT NECESSARY	67.00	-
1	FRONT DOOR HINGE (BOTTOM) LH	NOT NECESSARY	67.00	-
1	FRONT DOOR CHECKER LH	NOT NECESSARY	127.00	-

Report Ref No. CS/INC19006305/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL LH	NOT NECESSARY	364.00	-
1	FRONT GRILLE	CUT	840.00	520.10
1	FRONT GRILLE RETAINER	NOT NECESSARY	125.00	-
1	FRONT GRILLE TOW COVER	NOT NECESSARY	19.00	-
1	FRONT GRILLER LOGO	NOT NECESSARY	63.00	-
1	SUPPORT PANEL	NOT NECESSARY	1,097.00	-
1	SUPPORT PANEL TOP GARNISH	NOT NECESSARY	125.00	-
1	SUPPORT PANEL TOP GARNISH CLIP	NOT NECESSARY	50.00	-
1	BRACE PANEL	NOT NECESSARY	128.00	-
1	FRONT CROSSMEMBER	NOT NECESSARY	1,618.00	-
1	FRONT SHOCK ABSORBER LH	BENT	417.00	385.00
1	FRONT SHOCK ABSORBER TOP MOUNT LH	NOT NECESSARY	153.00	-
1	FRONT SHOCK ABSORBER DUST COVER LH	NOT NECESSARY	49.00	-
1	FRONT LOWER ARM LH	BENT	617.00	325.00
1	FRONT WHEEL BEARING LH	BENT	125.00	125.00
1	FRONT WHEEL HUB LH	BENT	237.00	237.00
1	FRONT KNUCKLE ARM LH	BENT	404.00	315.00
1	DRIVE SHAFT LH	NOT NECESSARY	1,470.00	-
1	STABILIZER BAR	NOT NECESSARY	375.00	-
2	STABILIZER BAR BUSH	NOT NECESSARY	164.00	-
1	STABILIZER BAR LINKAGE LH	NOT NECESSARY	125.00	-
1	TIE ROD END LH	NOT NECESSARY	117.00	-
1	STEERING RACK & PINION	NOT NECESSARY	1,587.00	-
1	FRONT ABS SENSOR LH	NOT NECESSARY	157.00	-
1	FRONT FENDER INNER PROTECTOR LH	NOT NECESSARY	67.00	-
1	FRONT RIM COVER LH	CRACKED	175.00	175.00
1	FRONT FOGLAMP COVER LH	NOT NECESSARY	111.00	-
1	FRONT FOGLAMP LH	CRACKED	235.00	235.00
	LESS 25% DISCOUNT		-4,595.00	-1,269.65
			13,785.00	3,808.95
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE LH (SN)	NOT NECESSARY	350.00	-
1	FRONT RIM LH (SN)	NECESSARY	450.00	60.00

Report Ref No. CS/INC19006305/T1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CVT OIL (SN)	NOT NECESSARY	150.00	-
			950.00	60.00
	LABOUR			
	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL LH AND FRONT DOOR LH.		2,200.00	600.00
	TO PUTTY AND RESRRAY REPLACED PARTS AND ACCIDENT REPAIR AREA.		1,800.00	700.00
	TO CHECK & RE-WIRING.		150.00	30.00
	TO REMOVE & REFIT FRONT WINDSCREEN.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD, TO TOP UP A/C GAS.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.		280.00	120.00
	TO DO WHEEL ALIGNMENT.		180.00	60.00
	TO DO TYRE BALANCING.	NOT NECESSARY	150.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	180.00	-
	TO RESET FAULT CODE.		350.00	100.00
	TO SPRAY RUST PROOF.		280.00	30.00
	TO REMOVE & INSTALL FRONT DOOR RH COMPONENTS.	NOT NECESSARY	180.00	-
	TO PRESSURE BRAKE TEST.	NOT NECESSARY	180.00	-
			6,290.00	1,640.00
GRAND TOTAL			21,025.00	5,508.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,400.00

Report Ref No. CS/INC19006305/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.