



Your Ref : S9M01JHS

Date: 16th April 2019

Our Ref : CS/ASM19006306/Dqd3s2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

(The Motor Claims Department)

Attn: Jas Tan

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SFT 26A
ACCIDENT ON 06/04/2019**

Instruction was received to inspect the vehicle Reg. No. SFT 26A. The inspection was conducted on 09/04/2019 at the premises of M/s Progressive Car Care Pte Ltd, Blk 3022A Ubi Road 1 #01-45/46 Singapore 048716.

The following vehicle information was recorded:


Registration Number	: SFT 26A
Make/Model	: B.M.W. 535
Year of Registration	: 2010
Body Colour	: Blue
Chassis Number	: WBAFR72080C264732
Engine Capacity	: 2979 cc

The vehicle caught fire. Cause of fire due to electrical nature at engine compartment.
(Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Market Value	S\$ 55,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 39,167.00)
Nett Liability	<u>S\$ 15,833.00</u>

Vehicle Inspected By:



ANG BRYAN TANI
Automotive Assessor / Investigator



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.