

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0419 - 5468
Assessment number: 001886
Version: 1810
Date calculated: 04/09/2019 01:43 PM

Full Report
Registration: SLA1388C
Printed: 09/04/2019 1:43 PM

Summary Information

Claim

Location: Singapore (SG)
Printed by: Wayne Lim
Claim Reference: TP 0419 - 5468
Estimated Repair Time:
Actual Repair Days:

Work Provider:
Currency:
Date of Incident:
Hire Car Start:
Hire Car End:

AXA Insurance Pte Ltd
SGD
2019-04-04

Vehicle Details

Vehicle

Manufacturer: MERCEDES-BENZ
Model: C-CLASS (W205)
Sub Model: C 180
Model Sheet Number: 03 AP 42
Registration: SLA1388C
VIN number: WDD2050402R094967
Odometer:

Model Specs

FR PRODUCTION START	MODIFICAT PACK 14/2	EQUIPMENT AVANTGARDE	EQUIPMENT AVANTGARDE
MODEL 2015	A/C THERMATIC	MIRROR PACKAGE	DIPPING MIRROR
ELECT FOLDING MIRROR	FRT COLLISION ALARM	KEYLESS IGNITION SYS	KEYLESS GO
REARVIEW CAMERA	AUDIO 20 TOUCHPAD	RADIO-CD/DVD	WIPER/RAIN SENSOR
INTERIOR LAMP PACK	LED HEADLAMP	LEATHER PAD ARTICO	FOLDING REAR SEAT
SEAT COMFORT PACKAGE	STORAGE PACKAGE	ALU MOULDINGS	PARK ASSISTENT
KEYLESS GO	ELECTRIC BOOTLID	ILLUMINAT AMBIENTE	BOOTLID SENSORS
AMG SILL MOULDINGS	HD COOLING	ECO START/STOP	AGILITY SELECT SWITC
7 SPEED AUTOMATIC	TYRE PRESSURE SENSOR	AGILITY CONTR SUSPEN	CRUISE CONTROL
TYRES 225/50 WR 17	WHEELS 7J X 17 ALLOY	TYRE W/FLAT RUNNING	EXTENDED FUEL TANK
PEDESTRIAN PROTECT	AMG STYLING	PRODUCT SOUTH AFRICA	TWO COAT METALLIC
CLEAR COAT HARD			

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0419 - 5468

Assessment number: 001886

Version: 1810

Date calculated: 04/09/2019 01:43 PM

Full Report

Registration: SLA1388C

Printed: 09/04/2019 1:43 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		3.0	13.50
61-1086 01	R + R FRONT AND CENTRE ENGINE COMPARTMENT COVERING		3.0	13.50
88-1102 01	R + R FRONT BUMPER CPL		9.0	40.50
88-1133 01	DIS + ASS FRONT BUMPER (BUMPER REMOVED)		8.0	36.00
88-1358 01	AFTER CHECK: RENEW PARTS IF NECESSARY ADDITION TO DIS + ASS FRONT BUMPER (BUMPER REMOVED)		2.0	9.00
88-1374 01	(VEHICLE WITH ULTRASONIC PARKING AID) ADDITION TO FRONT BUMPER DIS + ASS (VEHICLE WITH PEDESTRIAN PROTECT)		1.0	4.50
82-4734 01	R + R BOTH HEADLAMP UNITS (BUMPER REMOVED)		3.0	13.50

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0419 - 5468

Assessment number: 001886

Version: 1810

Date calculated: 04/09/2019 01:43 PM

Full Report

Registration: SLA1388C

Printed: 09/04/2019 1:43 PM

Code	Description	WU	Price SGD
88-4704 01	R + R R/F WHEELHOUSE LINER FRONT	3.0	13.50
54-0800 ZAX	CHECK REARVIEW CAMERA	1.0	4.50
82-1120 01	ADJUST HEADLAMPS	5.0	22.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		3.80	38.0
Total of Labour			171.00

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - CLEAR COAT HARD	WU	Price SGD
98-1682 01	FRONT BUMPER COVER PAINTING STAGE I-M	11.0	49.50
98-1710 ZAX	R/F OUTER SENSOR PAINTING STAGE I-M	1.0	4.50
98-1710 ZAX	R/F INNER SENSOR PAINTING STAGE I-M	1.0	4.50
98-2617 01	R/F WING PAINTING STAGE III	9.0	40.50
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	14.0	63.00
Total Paint		Hrs 3.60	WU 36.0
			Price SGD 162.00
Material Cost - Paint			Price SGD
Repair Painting			13.53
Material-constant Metal			13.47
Total			79.50

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER COVER	205 880 1840 9999		Deep cut 7880.00 ✓
0304	R/F BUMP LWR GRILLE	205 885 1223		17 40.00 ✓
0343	L/F BUMPER CARRIER	205 885 3165		17 37.00 ✓
0344	R/F BUMPER CARRIER	205 885 3265		17 37.00 ✓
0349	FRT/CTR IMPACT DAMP	205 885 1037		17 78.00 ✓
0354	SCREW	N000000 001459		10L 30.00 ✓
0362	R/F OUTER SENSOR	000 905 5604 9999		cut 83.00 ✓

headlamp o/s one ✓

headlamp bracket one ✓

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0419 - 5468

Assessment number: 001886

Version: 1810

Date calculated: 04/09/2019 01:43 PM

Full Report

Registration: SLA1388C

Printed: 09/04/2019 1:43 PM

Code	Description	Part Number	Supplier	Price SGD
0364	R/F CTR PARKING SENS	000 905 5504 9999		11 83.00x
0366	R/F INNER SENSOR	000 905 5504 9999		11 83.00x
0392	R/F BUMPER MOULDING	205 885 1474		22 33.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,384.00
u: Used parts	Addition(+15.00%)			207.60
	Total			1,591.60

Extras

Code	Description	Price SGD
1000	AUDATEX FEE AUDATEX FEE	42.00*
	Total Extras	42.00

Final Calculation

	SGD	SGD
Parts	1,384.00	
Addition(+15.00%)	207.60	
Total Parts		1,591.60
Labour Time Base 10 WU/h		
Total 38.0 WU X 45.00 SGD/h	171.00	
Total of Labour		171.00
Total Of Extras		42.00
Paint Work Time Base 10 WU/h		
Labour Cost 36.0 WU X 45.00 SGD/h	162.00	
Material Cost	79.50	
Total Paint Including Material		241.50
Repair Cost Excludes GST		2,046.10
GST (+7.00%)		143.23
Repair Cost Included GST		2,189.33

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 #01-46
408716

Claim Reference: TP 0419 - 5468

Assessment number: 001886

Version: 1810

Date calculated: 04/09/2019 01:43 PM

Full Report
Registration: SLA1388C
Printed: 09/04/2019 1:43 PM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

PROGRESSIVE CAR CARE PTE LTD
BLK 3022A UBI ROAD 1 #01-45/46
SINGAPORE 408716

Prepared by WENDY , HP 8258 5595
Vehicle No. SLA 1388 C
Make/Model MERCEDES BENZ C180 AVANTGARDE (R17 LED)
Chassis No. WDD2050402R094967
Tyre/Size M - 225/50R17

Fax 6844 4802
Date 08.07.19
Supplier PASS AUTO

ESTIMATE - SUPP

S/n	Qty	Parts Description	Cost Price (Yes)			
1	1	HEADLAMP - RH	\$1,350.00	CNA		
2	1	HEADLAMP LOWER RETIANER - RH	\$35.00	cm		
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						