

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 10 December 2019 5:13 PM
To: Carrine Leong
Cc: SUR; Chang Chee Sing; jlayee.yap@premiumauto.com.sg; Boo seng yak
Subject: RE: FINAL REVISION - SFA8662K - OD AIG - SURVEYED 9 APR 19 - TAUFIKH

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$30,223.08 before excess \$0/- & GST and 18 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Tuesday, 19 November 2019 11:02 AM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: FW: FINAL REVISION - SFA8662K - OD AIG - SURVEYED 9 APR 19 - TAUFIKH

Hi Taufikh,

Please find attachment photo for your attention as per your request.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 189902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Apr 2019 15:16	Cim Veh Model Changed		[I] Merimen Administrator
2	06 Apr 2019 15:16	Cim Created	Reg No: SFA8662K. Acct Date: 2019/04/05. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA119044752	[I] Merimen Administrator
3	10 Apr 2019 11:46	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[I] Nivitha Govindasamy
4	10 Apr 2019 11:46	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[I] Nivitha Govindasamy
5	10 Apr 2019 11:46	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
6	10 Apr 2019 11:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/22	[A] Nivitha Govindasamy
7	10 Apr 2019 11:46	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	10 Apr 2019 11:46	Cim Registration Modified	Rep:1137->204491.	[A] Nivitha Govindasamy
9	10 Apr 2019 11:46	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] Nivitha Govindasamy
10	10 Apr 2019 11:46	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
11	10 Apr 2019 14:37	Adj Rpt Initiated		[A] SHIAU CHAN
12	10 Apr 2019 14:37	Insured Phone No Updated	[None] -> [+6597395401]	[A] SHIAU CHAN
13	10 Apr 2019 14:37	Cim Dtl Modified	JPJ Reg. Date: -> 2016/09/16.	[A] SHIAU CHAN
14	10 Apr 2019 14:37	Cim Details Notified		[A] SHIAU CHAN
15	10 Apr 2019 16:05	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/04/22	[A] SHIAU CHAN
16	10 Apr 2019 16:06	Adj Mandate Request	Cur.Req:39952.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	11 Apr 2019 11:15	Cim Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 0.00. Excess Waived: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Gan, Hunchung
18	11 Apr 2019 11:15	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	11 Apr 2019 14:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/22. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
20	11 Apr 2019 14:32	Adj Mandate Set	Approved:18240.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK
21	05 Dec 2019 09:10	Adj Mandate Request	Cur.Req:30223.08:KINDLY APPROVE REPAIR COST OF \$30,223.08 INCLUSIVE OF CHECK ITEMS.	[A] SHIAU CHAN
22	05 Dec 2019 16:34	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/04/22. Mandate Remarks:	[I] Fong, Andy-SY
23	05 Dec 2019 16:34	Adj Mandate Set	Approved:30223.08:	[I] Fong, Andy-SY

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2112571	10 Apr 2019 14:37:02	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFA8662K		10.70

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 11 April 2019 2:40 PM
To: Claims Dept; SUR; assignments
Subject: RE: OD CLAIMS FOR SFA 8662 K (VEHICLE IN)

Dear George,

As instructed by our client, please proceed to repair the insured vehicle **SFA 8662K (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Thursday, 11 April 2019 1:20 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: OD CLAIMS FOR SFA 8662 K (VEHICLE IN)

Dear Shiau Chan,

Please advise approval status.

Thank you.

Best Regards,

George Wong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Apr 2019 15:16	Cim Veh Model Changed		[] Merimen Administrator
2	06 Apr 2019 15:16	Cim Created	Reg No: SFA8662K, Acct Date: 2019/04/05, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119044752	[I] Merimen Administrator
3	10 Apr 2019 11:46	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] Nivitha Govindasamy
4	10 Apr 2019 11:46	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Nivitha Govindasamy
5	10 Apr 2019 11:46	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
6	10 Apr 2019 11:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/22	[A] Nivitha Govindasamy
7	10 Apr 2019 11:46	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	10 Apr 2019 11:46	Cim Registration Modified	Rep:1137->204491.	[A] Nivitha Govindasamy
9	10 Apr 2019 11:46	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] Nivitha Govindasamy
10	10 Apr 2019 11:46	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
11	10 Apr 2019 14:37	Adj Rpt Initiated		[A] SHIAU CHAN
12	10 Apr 2019 14:37	Insured Phone No Updated	[None] -> [+6597395401]	[A] SHIAU CHAN
13	10 Apr 2019 14:37	Cim Dtl Modified	JPJ Reg. Date: -> 2016/09/16.	[A] SHIAU CHAN
14	10 Apr 2019 14:37	Cim Details Notified		[A] SHIAU CHAN
15	10 Apr 2019 16:05	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/04/22	[A] SHIAU CHAN
16	10 Apr 2019 16:06	Adj Mandate Request	Cur.Req:39952.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	11 Apr 2019 11:15	Cim Registration Modified	Init.Est.->5,000 - 6,000, Excess: -> 0.00, Excess Waived: -> 600.00, 2F Remark s: -> Not Applicable, GST: -> 7.00.	[I] Gan, Hunchung
18	11 Apr 2019 11:15	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	11 Apr 2019 14:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/22, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
20	11 Apr 2019 14:32	Adj Mandate Set	Approved:18240.00:Re-inspection to be done for damage check and supplementary items / labour, Reinsp:Yes.	[I] Koh, Victor-CK

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2112571	10/04/2019 14:37	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFA8662K		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 10 Apr 2019

Preliminary Advice

Vehicle No	: SFA8662K	Accident Date	: 05/04/2019
Make	: AUDI A4	Policy No.	:
Assignment Date	: 10/04/2019	Excess	: S\$0.00
Date of Inspection	: 09/04/2019	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	55,404.00
Revised Amount	:S\$	18,240.00
Check Items (Estimated)	:S\$	21,712.00
Total	:S\$	39,952.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	106,000.00
COE / PARF Rebate	:S\$	62,624.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,376.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5826Z
Vehicle Details	
Vehicle No.:	SFA8662K
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CVN018158
Chassis No.:	WAUZZZF45HA031792
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,161.00
Original Registration Date:	16 Sep 2016
First Registration Date:	16 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$27,026.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Sep 2026
PARF Rebate Amount:	\$20,269.00
Intended COE Rebate Details	
COE Expiry Date:	15 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$42,355.00
Total Rebate Amount:	\$62,624.00

The information contained herein is correct as at 10 Apr 2019

OK

MPM19044752 / Premium Automobiles Pte Ltd - UBI
 ENTRY DATE & TIME: 06/04/2019 11:16
 SUBMITTED BY: Jeffrey Tan Eng Su

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/04/2019 11:16
 Date Of Accident 05/04/2019 19:30
 Exact Location Of Accident 252 PASIR PANG JANG RD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFA8662K
Insured/Policyholder
 Name Of Registered Owner LIM LEE KOON
 NRIC No S1735826Z
 Email Address GIAMSEANGTIAN@GMAIL.COM
 Mobile Phone No (LOCAL) +65-97395401
 Alternative Phone No Office-97395401

Vehicle Particulars

Manufacturer AUDI
 Model A4 SEDAN 1.4 TFSI
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number
 Cover Note Number

Driver

Name of Driver LUCAS GIAM JIAN FENG
 NRIC No S9328819Z
 Date Of Birth 08/08/1993
 Occupation INDOOR
 Date Of Driving Pass 10/07/2012
 Driving Experience 6 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96445044

Fax Number

Contact Number	HOME-66417808
Email Address	GIAMSEANGTIAN@GMAIL.COM
Address	259 PASIR PANGJANG ROAD
Postcode	118626
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : DEBORAH GOH Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SFA8662K WAS STATIONARY AT THE SINGLE WHITE LINE, WAITING FOR ONCOMING TRAFFIC TO CLEAR BEFORE TURNING RIGHT (REFER TO SKETCH PLAN ABOVE). BRAKE LIGHTS OF SFA 8662 K WERE FUNCTIONING AND RIGHT - SIGNAL WAS TURNED ON . ANOTHER CAR (INITIALLY BEHIND SFA 8662 K) MANAGED TO BY PASS / OVERTAKE THE STATIONARY SFA 8662 K FROM BEHIND BEFORE SLJ 5124 Z CRASHED INTO SFA8662K. A FEW SECONDS LATER, SLJ5124Z (SECOND CAR BEHIND) CRASHED INTO THE BOTTOM-LEFT SIDE OF SFA8662K, BOTH CARS SUSTAINED DAMAGES. BOTH DRIVER CAME OUT OF THE THE VEHICLES TO EXCHANGE PARTICULARS, NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ5124Z
Vehicle Make/Model/Colour	HONDA SHUTTLE
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	KHIEW SUI YEN
NRIC/Passport Number	S7625617I
Contact Number	93676436
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 11:14 AM
06-11-19


Reporting Centre Personnel's Signature
Name: Juvany Hiteny Sene, Asean
NRIC/FIN No.: G987143X



Sketch Plan #2

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- ① SPAB62K was stationary at the single white line, waiting for oncoming traffic to clear before turning right (refer to sketch plan above)
- ② Brake lights of SPAB62K were functioning and right-signal was turned on
- ③ Another car (initially behind SPAB62K) managed to bypass/overtake the stationary SPAB62K from behind before SLJ51242 crashed into SPAB62K
- ④ A few seconds later, SLJ51242 (second car behind) crashed into the bottom-left side of SPAB62K, both cars sustained damages
- ⑤ Both drivers came out of the vehicles to exchange particulars, no one was injured

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

CHABUS, 14/04/2019, 19:30

Driver's Signature
(If driver is not the policyholder)
Date & Time: 11:29 AM
06-Apr-19

Reporting Centre Personnel's Signature
Name: Wally Lenny Seng George
NRIC/FIN No.: G278719X



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0453/2019/DY/GW
Date : 8-Apr-19

Vehicle IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Lee Koon
Address : 259 Pasir Panjang Road
Singapore 118626
Telephone : 97395401
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SFA 8662 K**
Model Code : A4 Sedan 1.4 TFSI S
Model / Year : 16/9/2016
Engine No : CVN 018158
Chassis No : WAUZZZF45HA031792
Mileage :
Date In : 6-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Apr-19
Place of Accident : 252 Pasir Panjang Road

LKK Auto Consultants hereby notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary sum(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by:

Signature:

Date:

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary sum(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFA 8662 K

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function.	s/n S	360.00 ✓	
2	To renew lhs 1/4 glass and rear windscreen to facilitate fender renewal.	s/n S	600.00 ✓	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. Inspect for damage and renew where necessary.	s/n S	1,400.00 ✓ photo.	
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	s/n S	1,400.00 ✓ photo.	
5	To carry out first measurement on car-o-liner.	s/n S	800.00 ? photo x nn	
6	To remove and reinstall exhaust silencers, rear suspension assembly. Inspect for damages and renew accordingly.	s/n S	3,200.00 ? photo ✓	
SUB-TOTAL LABOUR CHARGES		:	<u>S 7,760.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFA 8662 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
7	To place vehicle on car-o-liner for repairs.	s/n \$ 1,800.00	¹²⁰⁰ photo.?
8	To dismantle rear bumper and rear lid. Cut and weld lhs rear fender, outer wheel house, inner wheel house, inner D-pillar, reinforcements, and rear end panelling. Align rear sub-structure to specification of origin. Re-organise rear crash management components. Reinstall all parts removed.	\$ 13,200.00	⁵⁰⁰⁰ 3850. 3500
9	To respray rear bumper, lhs rear fender, outer/liner wheel house, lhs D-pillar and reinforcements, lhs sill panel, drain panel, roof channel, door entrances and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 6,200.00	⁷⁰⁰⁰ 2200
10	To renew lhs rear exhaust silencer. Align to position.	s/n \$ 480.00	? X mm
11	To renew lhs rear rim and carry out wheel alignment. Inspect tyre for damage.	s/n \$ 280.00	? ✓
12	To carry out diagnostic check.	s/n \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 30,104.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFA 8662 K**

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	REAR BUMPER COVER	\$	2,015.00	de-1612
2	REAR BUMPER FIXING PARTS	\$	66.00	? x un
3	REAR BUMPER SECURING PLATE	4 \$	60.00	? x un
4	REAR BUMPER SPOILER	\$	227.00	at-181.20
5	REAR BUMPER SECURING STRIP	\$	203.00	re-167.80
6	REAR LIGHT REFLECTOR - LH	\$	38.00	Cns-29.88
7	REAR LIGHT REFLECTOR - RH	\$	38.00	X un
8	REAR PARKING SENSOR	2 \$	462.00	? x RA
9	REAR PARKING SENSOR SEAL RING	4 \$	12.00	rec-8.96
10	WIRING SET FOR REAR BUMPER	\$	618.00	X
11	CABLE HOLDER FOR WIRING SET	\$	9.00	X un
12	REAR BUMPER REINFORCEMENT BEAM	\$	819.00	X
13	REAR BUMPER SEAL	\$	25.00	X
14	REAR BUMPER GUIDE SECTION-LH	\$	40.00	re-31.52
15	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$	40.00	LH-de-RA X 31.52
16	REAR BUMPER SEALING PLATE	2 \$	7.00	? x un
17	REAR FENDER-LH	\$	2,443.00	but-1954.40
18	REAR VENT TRIM-LH	1 \$	127.00	de-LH 101.28
19	CONSOLE TENSION SPRING	\$	27.00	? x un
20	CONSOLE TENSION SPRING BRACKET - LH	\$	89.00	? 70.88
SUB TOTAL SPARE PARTS		:	\$ 7,276.00	2765

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFA 8662 K**

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
21	REAR SIDE PANEL REINFORCEMENT BEAM-LH	\$	187.00	? 149.60 ✓ bt
22	REAR D-PILLAR SUPPORT-LH	\$	89.00	? 70.88 ✓ bt
23	REAR WHEEL HOUSING LINER -LH	\$	223.00	de 178.40
24	REAR OUTER WHEEL HOUSING LINER-LH	\$	574.00	? 459.70 ✓ bt
25	REAR INNER WHEEL HOUSING LINER -LH	\$	1,119.00	? 895.70 ✓ de
26	WHEEL HOUSING LINER - LH	\$	223.00	X nn bt
27	REAR BOTTOM PLATE-LH OUTER	\$	439.00	? 390.80 ✓
28	REAR CROSS PANEL	\$	238.00	? X nn
29	REINFORCEMENT FOR REAR CROSS PANEL	\$	461.00	? X nn
30	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$	82.00	? 65.52 ✓ ne
31	HEAT SHIELD FOR REAR SILENCER	\$	139.00	? 110.80 ✓ bt
32	REAR SIDE WINDOW - LH	\$	561.00	nn 440.40
33	REAR WINDSCREEN	\$	1,049.00	nn 839.20
34	PRIMER	2 \$	38.00	ne 29.76
35	FUSE HOLDER SUPPORT	\$	42.00	? 32.96 ✓ de
36	FUSE HOLDER	\$	68.00	? 54.32 ✓ dis
37	FUSE HOLDER FOR PLUG IN FUSE	\$	4.00	? 2.72 ✓ con
38	FUSE HOLDER FOR FLAT FUSE	\$	14.00	? 11.04 ✓ dis
39	LED TAIL LIGHT - LH	\$	931.00	? photo 744.80 con
40	REAR ALUMINIUM RIM-LH	\$	558.00	? ant 406.40 ✓
SUB-TOTAL SPARE PARTS		:	\$ 7,039.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFA 8662 K**

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
41	RUBBER VALVE	4 S	13.00	? X nh
42	REAR SUSPENSION CROSS MEMBER-LH	S	2,975.00	? X nh
43	REAR LOWER CONTROL ARM-LH	S	785.00	? 628 ✓ bt ✓
44	REAR TRACK CONTROL ARM-LH UPPER	S	507.00	? 405.70 ✓ bt
45	REAR LOWER CONTROL ARM-LH FRONT	S	112.00	? 89.60 ✓ bt
46	REAR UPPER CONTROL ARM-LH	S	407.00	? 375.60 ✓ bt
47	REAR TRACK ROD-LH	S	155.00	? 124 ✓ bt
48	REAR WHEEL BEARING HOUSING-LH	S	903.00	? 722.40 ✓ bt
49	REAR WHEEL BEARING WITH ASSEMBLY-LH	S	404.00	? 322.80 ✓ bt
50	REAR LEVEL SENSOR-LH	S	298.00	? X
51	REAR GAS SHOCK ABSORBER-LH	S	276.00	? X
52	REAR COUPLING ROD-LH	S	79.00	? X
53	REAR SILENCER-LH	S	999.00	? X
54	REAR SILENCER DUAL CLIP-LH	S	45.00	? X
55	REAR EXHAUST SILENCER BRACKET LH	S	38.00	? X
56	REAR TYRE (YOKOHAMA)	TBC	?	X
57	ACRYLIC SEALANT	2 S	360.00	acc ✓
58	CAVITY WAX	2 S	280.00	acc ✓
59	STONE CHIP	S/N S	180.00	acc ✓
60	1/4 GLASS SEALANT	S/N S	100.00	acc ✓
SUB-TOTAL SPARE PARTS		:	\$ 19,020.00	8916

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFA 8662 K**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	REAR WINDSCREEN SEALANT	S/N \$ 200.00	OK
62	METAL FILLER POWDER	S/N \$ 280.00	OK
63	SUNDRIES	\$ 1,500.00	? 287.32 OK
TOTAL SPARE PARTS		\$ 35,315.00	75300
TOTAL LABOUR CHARGES		\$ 30,104.00	
GRAND TOTAL		\$ 65,419.00	55404

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tan Jiah 97495749.

Ex: tba.

Repair before paint.

sure maintenance.

Revert, Not Authorised.

9/4/19 @ 530pm

2/8 days

[Signature]
11/4/19.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0453/2019/DY/GW
Date : 8-Apr-19

Vehicle IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

We took 18 days exclude 2 Sundays

jb - 15 Jun 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Lee Koon
Address : 259 Pasir Panjang Road
Singapore 118626
Telephone : 97395401
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SFA 8662 K**
Model Code : A4 Sedan 1.4 TFSI S
Model / Year : 16/9/2016
Engine No : CVN 018158
Chassis No : WAUZZZF45HA031792
Mileage :
Date In : 6-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Apr-19
Place of Accident : 252 Pasir Panjang Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFA 8662 K

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function.	s/n	\$ 360.00	\$ 360.00
2	To renew lhs 1/4 glass and rear windscreen to facilitate fender renewal.	s/n	\$ 600.00	\$ 600.00
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. Inspect for damage and renew where necessary.	s/n	\$ 1,400.00	\$ 1,400.00
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	s/n	\$ 1,400.00	\$ 1,400.00
5	To carry out first measurement on car-o-liner.	s/n	\$ 800.00	na
6	To remove and reinstall exhaust silencers, rear suspension assembly. Inspect for damages and renew accordingly.	s/n	\$ 3,200.00	\$ 3,200.00
SUB-TOTAL LABOUR CHARGES		:	<u>\$ 7,760.00</u>	<u>\$ 6,960.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFA 8662 K

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 6,960.00
7	To place vehicle on car-o-liner for repairs. (C/Bench)	s/n	\$ 1,800.00	\$ 1,200.00
8	To dismantle rear bumper and rear lid. Cut and weld lhs rear fender, outer wheel house, inner wheel house, inner D-pillar, reinforcements, and rear end panelling. Align rear sub-structure to specification of origin. Re-organise rear crash management components. Reinstall all parts removed. (Wheelhouse, bottom plate, d pillar repair 3 days added)		\$ 13,200.00	\$ 5,000.00
9	To respray rear bumper, lhs rear fender, outer/liner wheel house, lhs D-pillar and reinforcements, lhs sill panel, drain panel, roof channel, door entrances and end panelling. To carry out joint sealer works and stone chip treatment. ((\$825/- 1.5 panel added for wheel house, bottom plate etc)		\$ 6,200.00	\$ 3,025.00
10	To renew lhs rear exhaust silencer. Align to position.	s/n	\$ 480.00	na
11	To renew lhs rear rim and carry out wheel alignment. Inspect tyre for damage.	s/n	\$ 280.00	\$ 280.00
12	To carry out diagnostic check.	s/n	\$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	<u>\$ 30,104.00</u>	<u>\$ 16,849.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFA 8662 K**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	REAR BUMPER COVER	\$ 2,015.00	\$ 1,612.00
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SECURING PLATE	4 \$ 60.00	
4	REAR BUMPER SPOILER	\$ 227.00	\$ 181.20
5	REAR BUMPER SECURING STRIP	\$ 203.00	\$ 162.40
6	REAR LIGHT REFLECTOR - LH	\$ 38.00	\$ 29.68
7	REAR LIGHT REFLECTOR - RH	\$ 38.00	
8	REAR PARKING SENSOR	2 \$ 462.00	
9	REAR PARKING SENSOR SEAL RING	4 \$ 12.00	\$ 8.96
10	WIRING SET FOR REAR BUMPER	\$ 618.00	
11	CABLE HOLDER FOR WIRING SET	\$ 9.00	
12	REAR BUMPER REINFORCEMENT BEAM	\$ 819.00	
13	REAR BUMPER SEAL	\$ 25.00	
14	REAR BUMPER GUIDE SECTION-LH	\$ 40.00	\$ 31.52
15	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$ 40.00	\$ 31.84
16	REAR BUMPER SEALING PLATE	2 \$ 7.00	
17	REAR FENDER-LH	\$ 2,443.00	\$ 1,954.40
18	REAR VENT TRIM-LH	2 \$ 127.00	\$ 101.28
19	CONSOLE TENSION SPRING	\$ 27.00	
20	CONSOLE TENSION SPRING BRACKET - LH	\$ 89.00	\$ 70.88
SUB TOTAL SPARE PARTS		\$ 7,276.00	\$ 4,184.16

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFA 8662 K**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
			\$ 4,184.16
21	REAR SIDE PANEL REINFORCEMENT BEAM-LH	\$ 187.00	\$ 149.60
22	REAR D-PILLAR SUPPORT-LH	\$ 89.00	\$ 70.88
23	REAR WHEEL HOUSING LINER -LH	\$ 223.00	\$ 178.40
24	REAR OUTER WHEEL HOUSING LINER-LH	\$ 574.00	\$ 459.20
25	REAR INNER WHEEL HOUSING LINER -LH	\$ 1,119.00	\$ 895.20
26	WHEEL HOUSING LINER - LH	\$ 223.00	
27	REAR BOTTOM PLATE-LH OUTER	\$ 439.00	\$ 350.80
28	REAR CROSS PANEL	\$ 238.00	
29	REINFORCEMENT FOR REAR CROSS PANEL	\$ 461.00	
30	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 82.00	\$ 65.52
31	HEAT SHIELD FOR REAR SILENCER	\$ 139.00	\$ 110.80
32	REAR SIDE WINDOW - LH	\$ 561.00	\$ 448.40
33	REAR WINDSCREEN	\$ 1,049.00	\$ 839.20
34	PRIMER	2 \$ 38.00	\$ 29.76
35	FUSE HOLDER SUPPORT	\$ 42.00	\$ 32.96
36	FUSE HOLDER	\$ 68.00	\$ 54.32
37	FUSE HOLDER FOR PLUG IN FUSE	\$ 4.00	\$ 2.72
38	FUSE HOLDER FOR FLAT FUSE	\$ 14.00	\$ 11.04
39	LED TAIL LIGHT - LH	\$ 931.00	\$ 744.80
40	REAR ALUMINIUM RIM-LH	\$ 558.00	\$ 446.40
SUB-TOTAL SPARE PARTS		\$ 7,039.00	\$ 9,074.16

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFA 8662 K**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
			\$	9,074.16
41	RUBBER VALVE	4	\$ 13.00	
42	REAR SUSPENSION CROSS MEMBER-LH		\$ 2,975.00	
43	REAR LOWER CONTROL ARM-LH		\$ 785.00	\$ 628.00
44	REAR TRACK CONTROL ARM-LH UPPER		\$ 507.00	\$ 405.20
45	REAR LOWER CONTROL ARM-LH FRONT		\$ 112.00	\$ 89.60
46	REAR UPPER CONTROL ARM-LH		\$ 407.00	\$ 325.60
47	REAR TRACK ROD-LH		\$ 155.00	\$ 124.00
48	REAR WHEEL BEARING HOUSING-LH		\$ 903.00	\$ 722.40
49	REAR WHEEL BEARING WITH ASSEMBLY-LH		\$ 404.00	\$ 322.80
50	REAR LEVEL SENSOR-LH		\$ 298.00	
51	REAR GAS SHOCK ABSORBER-LH		\$ 276.00	
52	REAR COUPLING ROD-LH		\$ 79.00	
53	REAR SILENCER-LH		\$ 999.00	
54	REAR SILENCER DUAL CLIP-LH		\$ 45.00	
55	REAR EXHAUST SILENCER BRACKETLH		\$ 38.00	
56	REAR TYRE (YOKOHAMA)		TBC	
57	ACRYLIC SEALANT	2	\$ 360.00	\$ 360.00
58	CAVITY WAX	2	\$ 280.00	\$ 280.00
59	STONE CHIP	S/N	\$ 180.00	\$ 180.00
60	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
SUB-TOTAL SPARE PARTS		:	\$ 19,020.00	\$ 12,611.76

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFA 8662 K**

S/N	Parts Description	c/f	<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remark</u>
				\$ 12,611.76
61	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
62	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
64	SUNDRIES		\$ 1,500.00	\$ 282.32
TOTAL SPARE PARTS			\$ 35,315.00	\$ 13,374.08
TOTAL LABOUR CHARGES			\$ 30,104.00	\$ 16,849.00
GRAND TOTAL			\$ 65,419.00	\$ 30,223.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFA 8662 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0453/2019/NH

30TH JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SFA 8662 K, Audi A4 SEDAN 1.4 TFSI.

With reference to the above-mentioned vehicle, no. **SFA 8662 K**, claimant, **Ms. Lim Lee Koon**, please find the related document per attached.

1. A copy of the Original invoice no. 85014772 – S\$ 32,338.70.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SFA 8662 K

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9826 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014772 Date : 28/01/2020 Order : SFA8662K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
Regn No: SFA8662K (V 31150)		Regn Date: 16/09/2016	Mileage: 78900	WIP No.: 49332	
Model: A4 SEDAN 1.4 TFSI S tronic		Chassis: WAUZZZF45HA031792	Engine: CVN 018158	Dept: U	
You have been assisted by :- UB-Siti Marsilia (137)					
		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY.CHECK FUNCTION	360.00	1.00	360.00
S	BODYWORK	M: TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	600.00	1.00	600.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT,BATTERY MANAGER,FUSE AND RELAY TRAY,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL EXHAUST SILENCER, REAR SUSPENSION ASSEMBLY.INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	3200.00	1.00	3,200.00
S	BODYWORK	M: TO PLACE VEHICLE ON CELLETE BENCH FOR REPAIR	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER AND REAR LID.CUT OUT AND WELD LHS REAR FENDER,OUTER WHEEL HOUSE, INNER WHEEL HOUSE,INNER D PILLAR,REINFORCEMENT, AND REAR END PANELLING.ALIGN REAR SUB-STRUCTURE TO SPECIFICATION OF ORIGIN.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL PARTS REMOVED	5000.00	1.00	5,000.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,LHS REAR FENDER, BOOT LID,WHEEL HOUSING,LHS SILL PANEL AND ROOF CHANNEL.TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT.	3025.00	1.00	3,025.00
S	BODYWORK	M: TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.INSPECT FOR DAMAGE	280.00	1.00	280.00
S	BODYWORK	M:	384.00	1.00	384.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014772	Account: A0006 (T 0)	
		Date : 28/01/2020	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
		Order : SFA8662K		
		Term : 30		

Regn No: SFA8662K (V 31150)	Regn Date: 16/09/2016	Mileage: 78900	WIP No.: 49332
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF45HA031792	Engine: CVN 018158	Dept: U
You have been assisted by :- UB-Siti Marsilla (137)			

		Details	Qty	Unit Price	Amount
I	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	1400.00	1.00	1,400.00
S	BODYWORK	TO SUPPLY ACRYLIC SEALANT,CAVITY WAX, STONE CHIP,1/4 GLASS SEALANT,REAR WINDSCREEN SEALANT AND METAL FILLER POWDER M:	1400.00	1.00	1,400.00
		TO REMOVE AND REINSTALL REAR SEAT,BACK REST, HAT TRAY,ABCD PILLAR TRIM,LUGGAGE COMPARTMENT TRIMS,SEAT BELTS.DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG			
X	ABW5807067A GRU	COVER Less 020%	1.00	2015.00	1,612.00
X	ABW0807521K 9B9	SPOILER Less 020%	1.00	226.50	181.20
X	ABW0807900D	STRIP(LAST) Less 020%	1.00	203.00	162.40
X	ABW0945105C	REFLECTOR Less 020%	1.00	37.10	29.68
X	A5Q0919133 704	WASHER Less 020%	4.00	2.80	8.96
X	ABW5807453	GUIDE Less 020%	1.00	39.40	31.52
X	AN 10621301	NUT Less 020%	10.00	1.80	14.40
X	ABW5807889	GUIDE Less 020%	1.00	19.90	15.92
X	ABW5807890	GUIDE Less 020%	1.00	19.90	15.92
X	ABW5809837	SUBPART Less 020%	1.00	2443.00	1,954.40
X	ABW0809409TA	007181/(V) (GER)HOUSI Less 020%	1.00	574.00	459.20
X	A6R0819465B	(A) (SK)TRIM 12/4/19 Less 020%	2.00	63.30	101.28
X	ABW5809305	007181/(V) (GER)SUPPO Less 020%	1.00	88.60	70.88
X	ABW5810613	REINFORCEM Less 020%	1.00	187.00	149.60
X	ABW5810205	007181/(A) (GER)SUPPO Less 020%	1.00	88.60	70.88
X	ABW0802089A	(A) (SK)FLOOR PAN 12/ Less 020%	1.00	438.50	350.80
X	ABW5810363TA	007181/(V) (GER)HOUSI Less 020%	1.00	1119.00	895.20
X	ABW0810171F	WHEEL HOUS Less 020%	1.00	223.00	178.40
X	ABW0098629	ATT.PARTS Less 020%	1.00	81.90	65.52
X	ABW0804171	(A) (SK)PLATE 12/4/19 Less 020%	1.00	138.50	110.80
X	ABW5845297D NVB	SIDE WINDO(LAST) Less 020%	1.00	560.50	448.40
X	ABW5845501B NVB	REARWINDOW Less 020%	1.00	1049.00	839.20
X	AD 00920002	PRIMER (DG) Less 020%	2.00	18.60	29.76
X	ABW0971845AH	(A) (SK)MOUNTING 12/4 Less 020%	1.00	41.20	32.96

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 3 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014772	Account: A0006 (T 0)	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
		Date : 28/01/2020				
		Order : SFA8662E				
		Term : 30				
Regn No: SFA8662E (V 31150)		Regn Date: 16/09/2016	Mileage: 78900	WIP No.: 49332		
Model: A4 SEDAN 1.4 TFSI S tronic		Chassis: WAUZZZF45HA031792	Engine: CVN 018158	Dept: U		
You have been assisted by :- UB-Siti Marsilla (137)						
		Details	Qty	Unit Price	Amount	
X	A4F1941824	(A) (GER) HOLDER 12/4/	Less 020%	1.00	67.90	54.32
X	A8W0937530	(A) (GER) HOLDER 12/4/	Less 020%	1.00	3.40	2.72
X	A4A0937530	(A) (GER) HOLDER 12/4/	Less 020%	1.00	13.80	11.04
X	A8W5945091C	LED TAIL LIGHT (LAST)	Less 020%	1.00	931.00	744.80
X	AN 91228001	SCREW	Less 020%	2.00	20.10	32.16
X	A8W0505311H	007187/ (V) (SK) CONTR	Less 020%	1.00	785.00	628.00
X	AWHT007092A	007186/ (V) (GER) SCREW	Less 020%	2.00	1.10	1.76
X	AWHT007043A	WASHER	Less 020%	1.00	5.10	4.08
X	AN 91236401	BOLT	Less 020%	1.00	8.50	6.80
X	AN 10106402	NUT	Less 020%	1.00	2.80	2.24
X	A8W0505323F	007187/ (V) (SK) CONTR	Less 020%	1.00	506.50	405.20
X	AN 10272302	NUT	Less 020%	1.00	2.70	2.16
X	A4M0505291D	007187/ (V) (SK) CONTR	Less 020%	1.00	112.00	89.60
X	AN 91228901	BOLT	Less 020%	1.00	5.10	4.08
X	AN 10272302	NUT	Less 020%	1.00	2.70	2.16
X	A8W0505397F	007187/ (V) (SK) CONTR	Less 020%	1.00	407.00	325.60
X	AN 10602202	BOLT	Less 020%	1.00	5.20	4.16
X	AN 10106402	NUT	Less 020%	1.00	2.80	2.24
X	A8W0501529D	007186/ (V) (GER) TIE R	Less 020%	1.00	155.00	124.00
X	AWHT007096	BOLT	Less 020%	7.00	11.00	61.60
X	AWHT007090A	007187/ (V) (SK) SCREW	Less 020%	2.00	14.20	22.72
X	AWHT007041	WASHER	Less 020%	1.00	3.30	2.64
X	AWHT007828	FLANGE NUT	Less 020%	1.00	3.60	2.88
X	AN 91236401	BOLT (LAST)	Less 020%	1.00	8.50	6.80
X	AN 10106402	NUT	Less 020%	1.00	2.80	2.24
X	A8W0598611A	BEARING (LAST)	Less 020%	1.00	403.50	322.80
X	A8W0907368	007181/ (V) (GER) MOUNT	Less 020%	1.00	31.30	25.04
X	AN 91233601	NUT	Less 020%	4.00	1.00	3.20
X	ASK0807470A	007181/ (V) (SK) SEAL W	Less 020%	2.00	3.10	4.96
X	AWHT005180	BOLT	Less 020%	2.00	8.30	13.28
X	AN 91029902	007181/ (V) (GER) BOLT	Less 020%	10.00	1.20	9.60
X	AN 91017602	BOLT	Less 020%	10.00	1.20	9.60
X	A8W0505431P	007186/ (V) (GER) HOUSI	Less 020%	1.00	903.00	722.40
X	AWHT007043A	WASHER	Less 020%	1.00	5.10	4.08

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 4 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014772 Date : 28/01/2020 Order : SFA8662K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SFA8662K (V 31150) Regn Date: 16/09/2016 Mileage: 78900 WIP No.: 49332

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF45HA031792 Engine: CVN 018158 Dept: U

You have been assisted by :- UB-Siti Marsilla (137)

		Details		Qty	Unit Price	Amount
X	AWHT007610	NUT	Less 020%	2.00	5.10	8.16
X	AN 10106402	NUT	Less 020%	2.00	2.80	4.48
X	AN 10602202	BOLT	Less 020%	1.00	5.20	4.16
X	AWHT007828	FLANGE NUT	Less 020%	2.00	3.60	5.76
X	AN 10608501	007187/(V) (SK) RIVET	Less 020%	2.00	1.50	2.40
X	AN 91228901	BOLT	Less 020%	2.00	5.10	8.16
X	AN 10272302	NUT	Less 020%	2.00	2.70	4.32
X	A8W0601025B	007204/(V) (SK) RIM 16	Less 020%	1.00	558.00	446.40

Parts 11,974.08
Labour 0.00
Sublet 18,249.00
Menus 0.00
Lubricant 0.00

Sub-Total 30,223.08

7% GST 2,115.62

Grand Total 32,338.70



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SFA 8662 K

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0453/2019/KK
7TH May 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI

Vehicle Chassis No. : WAUZZZF45HA031792

Vehicle Regn No. : SFA 8662 K

Vehicle Mileage : 69003 KM

Vehicle Owner : **Mg** Lim Lee Koon

Certificate No : 2100482790-02

Own Damage Excess : 0

Accident Date : 5/4/2019

Place : **252 Pasir Panjang Road**

Repair Cost : \$ 32,338.70

WIP No. : 49332

Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

7/5/19 18.47

Date :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2019 14:37		10 Apr 2019 11:46 Edit Adj Rpt	S\$30,223.08 Edit Estimates	S\$30,223.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: LIM LEE KOON , ID: S17358262, Tel: +6597395401									
Vehicle Reg. No.: SFA8662K		Date of Loss: 05/04/2019 19:00 - :59 [30 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 0655223038SG		Policy/Cover Note No.: (Comprehensive)							
		Excess: S\$0.00							
Repairer: Premium Automobiles Pte Ltd (Benoi) 24 Benoi Sector, 629857 Pioneer - Tel: 67689911 / 63882323									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHO TAUFIKH BIN HAMID] ... [Final Rpt due 22/04/2019]									
Driver/Custodian: LUCAS GIAM JIAN FENG (25 / Male) , NRIC: S9328819Z, Tel: +6596445044 Email: GIAMSEANGTIAN@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (05/12/2019): Alert - Adj Mandate Approved (S\$30223.08) - SFA8662K - Claim Handler: Gan, Hunch... - AIG_SG (11/04/2019): Alert - Adj Mandate Approved (S\$18240.00) - SFA8662K - Claim Handler: Gan, Hunch...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFA8662K (0655223038SG)
 OD
 Apr 5 2019 7:30PM
 [LIM LEE KOON]
 Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Assessment Reports			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	10/04/19 16:05	Adjuster Immediate Advice		Load HTML v ☒
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	10/04/19 14:34	Odometer Reading		Load JPG ☒
2	10/04/19 14:34	General View		Load JPG ☒
3	10/04/19 14:34	General View		Load JPG ☒
4	10/04/19 14:34	Chassis Number		Load JPG ☒
5	10/04/19 14:34	General View		Load JPG ☒
6	10/04/19 14:34	General View		Load JPG ☒
7	10/04/19 14:34	General View		Load JPG ☒
8	10/04/19 14:34	General View		Load JPG ☒
9	10/04/19 14:34	General View		Load JPG ☒
10	10/04/19 14:34	General View		Load JPG ☒
11	10/04/19 14:34	General View		Load JPG ☒
12	10/04/19 14:34	General View		Load JPG ☒
13	10/04/19 14:34	General View		Load JPG ☒
14	10/04/19 14:34	General View		Load JPG ☒
15	10/04/19 14:34	General View		Load JPG ☒
16	10/04/19 14:34	General View		Load JPG ☒
17	10/04/19 14:34	General View		Load JPG ☒
18	10/04/19 14:34	General View		Load JPG ☒
19	10/04/19 14:34	General View		Load JPG ☒
20	10/04/19 14:34	General View		Load JPG ☒
21	10/04/19 14:34	General View		Load JPG ☒
22	10/04/19 14:34	General View		Load JPG ☒
23	10/04/19 14:34	General View		Load JPG ☒
24	10/04/19 14:34	General View		Load JPG ☒
25	10/04/19 14:34	General View		Load JPG ☒
26	10/04/19 14:34	General View		Load JPG ☒
27	10/04/19 14:34	General View		Load JPG ☒
28	10/04/19 14:34	General View		Load JPG ☒
29	10/04/19 14:34	General View		Load JPG ☒
30	10/04/19 14:34	General View		Load JPG ☒
31	10/04/19 14:34	General View		Load JPG ☒
32	10/04/19 14:34	General View		Load JPG ☒
33	10/04/19 14:34	General View		Load JPG ☒
34	10/04/19 14:34	General View		Load JPG ☒
35	10/04/19 14:34	General View		Load JPG ☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	10/04/19 14:34	General View	 Load JPG	☒
37	10/04/19 14:34	General View	 Load JPG	☒
38	10/04/19 14:34	General View	 Load JPG	☒
39	10/04/19 14:34	General View	 Load JPG	☒
40	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
41	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
42	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
43	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
44	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
45	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
46	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
47	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
48	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
49	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
50	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
51	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
52	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
53	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
54	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
55	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
56	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
57	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
58	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
59	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
60	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
61	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
62	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
63	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
64	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
65	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
66	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
67	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
68	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
69	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
70	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
71	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
72	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
73	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
74	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
75	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
76	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
77	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
78	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
79	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
80	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
81	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
82	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
83	26/11/19 16:17	Reinspection Photo	 Load JPG	☒
84	26/11/19 16:18	Replacement Part Photo	 Load JPG	☒
85	26/11/19 16:18	Replacement Part Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	26/11/19 16:18	Replacement Part Photo		☒
87	26/11/19 16:18	Replacement Part Photo		☒
88	26/11/19 16:18	Replacement Part Photo		☒
89	26/11/19 16:18	Replacement Part Photo		☒
90	26/11/19 16:18	Replacement Part Photo		☒
91	26/11/19 16:18	Replacement Part Photo		☒
92	26/11/19 16:18	Replacement Part Photo		☒
93	26/11/19 16:18	Replacement Part Photo		☒
94	26/11/19 16:18	Replacement Part Photo		☒
95	26/11/19 16:18	Replacement Part Photo		☒
96	26/11/19 16:18	Replacement Part Photo		☒
97	26/11/19 16:18	Replacement Part Photo		☒
98	26/11/19 16:18	Replacement Part Photo		☒
99	26/11/19 16:18	Replacement Part Photo		☒
100	26/11/19 16:18	Replacement Part Photo		☒
101	26/11/19 16:18	Replacement Part Photo		☒
102	26/11/19 16:18	Replacement Part Photo		☒
103	26/11/19 16:18	Replacement Part Photo		☒
104	26/11/19 16:18	Replacement Part Photo		☒
105	26/11/19 16:18	Replacement Part Photo		☒
106	26/11/19 16:18	Replacement Part Photo		☒
107	26/11/19 16:18	Replacement Part Photo		☒
108	26/11/19 16:18	Replacement Part Photo		☒
109	26/11/19 16:18	Replacement Part Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/04/19 14:33	GIA & ADDENDUM		☒
2	10/04/19 14:33	ESTIMATE		☒
3	10/04/19 15:44	Driver's Driving License		☒
4	10/04/19 15:44	Certificate of Insurance		☒
5	05/12/19 09:09	REVISED ESTIMATE		☒
6	04/02/20 12:23	Workshop Invoice		☒
7	04/02/20 12:23	Discharge Voucher		☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/04/19 11:39	Addendum Sheet		☒
2	04/09/19 00:32	Accident Statement		☒
3	04/09/19 00:33	Accident Statement		☒
4	04/09/19 00:36	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/04/19 11:24	Accident Photo		☒
2	06/04/19 11:24	Accident Photo		☒
3	06/04/19 11:24	Accident Photo		☒
4	06/04/19 11:24	Accident Photo		☒
5	06/04/19 11:24	Accident Photo		☒
6	06/04/19 11:24	Accident Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
7	06/04/19 11:24	Accident Photo	 Load JPG	☒
8	06/04/19 15:35	Accident Photo	 Load JPG	☒
9	06/04/19 15:35	Accident Photo	 Load JPG	☒
10	06/04/19 15:36	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/04/19 15:38	Accident Sketch Plan	 Load JPG	☒
2	08/04/19 11:33	Accident Sketch Plan	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19006324/T1QD3E2

Date: 04/02/2020

REFERENCE

Insured/Claimant: LIM LEE KOON Policy No:
Date of Loss: 05/04/2019 Nature of Claim: OD Claim No: 0655223038SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFA8662K
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN018158
Reg. Date: 16/09/2016 (Man. Year: 2016) Chassis No: WAUZZZF45HA031792
Colour: Blue Odometer: 69001 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$106,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,300.00	13,374.08	11,925.92	47.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	30,104.00	16,849.00	13,255.00	44.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	55,404.00	30,223.08	25,180.92	45.45
+ GST 7.00/7.00% (S\$)	3,878.28	2,115.62	1,762.66	45.45
Nett Amount (S\$)	59,282.28	32,338.70	26,943.58	45.45

INSPECTION

Date of Assignment: 10/04/2019
Date Inspected: 09/04/2019 Inspected At: Premium Automobiles Pte Ltd (Benoi)
24 Benoi Sector
Singapore 629857
Estimated Period of Repair: 18.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	2,015.00 FS	*1,612.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	66.00 FS	*- FS
3	4		*REAR BUMPER SECURING PLATE	Not Necessary	60.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Cut	227.00 FS	*181.20 FS
5	1		*REAR BUMPER SECURING STRIP	Necessary	203.00 FS	*162.40 FS
6	1		*REAR LIGHT REFLECTOR - LH	Cracked	38.00 FS	*29.68 FS
7	1		*REAR LIGHT REFLECTOR - RH	Not Necessary	38.00 FS	*- FS
8	2		*REAR PARKING SENSOR	Not Necessary	462.00 FS	*- FS
9	4		*REAR PARKING SENSOR SEAL RING	Necessary	12.00 FS	*8.96 FS
10	1		*WIRING SET FOR REAR BUMPER	Not Necessary	618.00 FS	*- FS
11	1		*SET CABLE HOLDER FOR WIRING	Not Necessary	9.00 FS	*- FS
12	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	819.00 FS	*- FS
13	1		*REAR BUMPER SEAL	Not Necessary	25.00 FS	*- FS
14	1		*REAR BUMPER GUIDE SECTION - LH	Necessary	40.00 FS	*31.52 FS
15	2		*REAR BUMPER UPPER GUIDE SECTION - LH / RH	N/S Distorted / O/S Deformed	40.00 FS	*31.84 FS
16	2		*REAR BUMPER SEALING PLATE	Not Necessary	7.00 FS	*- FS
17	1		*REAR FENDER - LH	Buckled	2,443.00 FS	*1,954.40 FS
18	1		*REAR VENT TRIM - LH	Deformed	127.00 FS	*101.28 FS
19	1		*CONSOLE TENSION SPRING	Not Necessary	27.00 FS	*- FS
20	1		*CONSOLE TENSION SPRING BRACKET - LH	Distorted	89.00 FS	*70.88 FS
21	1		*REAR SIDE PANEL REINFORCEMENT BEAM - LH	Bent	187.00 FS	*149.60 FS
22	1		*REAR D-PILLAR SUPPORT - LH	Bent	89.00 FS	*70.88 FS
23	1		*REAR WHEEL HOUSING LINER - LH	Deformed	223.00 FS	*178.40 FS
24	1		*REAR OUTER WHEEL HOUSING LINER - LH	Bent	574.00 FS	*459.20 FS
25	1		*REAR INNER WHEEL HOUSING LINER - LH	Deformed	1,119.00 FS	*895.20 FS
26	1		*WHEEL HOUSING LINER - LH	Not Necessary	223.00 FS	*- FS
27	1		*REAR BOTTOM PLATE - LH OUTER	Bent	439.00 FS	*350.80 FS
28	1		*REAR CROSS PANEL	Not Necessary	238.00 FS	*- FS
29	1		*REINFORCEMENT FOR REAR CROSS PANEL	Not Necessary	461.00 FS	*- FS
30	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Necessary	82.00 FS	*65.52 FS
31	1		*HEAT SHIELD FOR REAR SILENCER	Bent	139.00 FS	*110.80 FS
32	1		*REAR SIDE WINDOW - LH	Necessary	561.00 FS	*448.40 FS
33	1		*REAR WINDSCREEN	Necessary	1,049.00 FS	*839.20 FS
34	2		*PRIMER	Necessary	38.00 FS	*29.76 FS
35	1		*FUSE HOLDER SUPPORT	Deformed	42.00 FS	*32.96 FS
36	1		*FUSE HOLDER	Distorted	68.00 FS	*54.32 FS
37	1		*FUSE HOLDER FOR PLUG IN FUSE	Cracked	4.00 FS	*2.72 FS
38	1		*FUSE HOLDER FOR FLAT FUSE	Distorted	14.00 FS	*11.04 FS
39	1		*LED TAIL LIGHT - LH	Cracked	931.00 FS	*744.80 FS
40	1		*REAR ALUMINIUM RIM - LH	Cut	558.00 FS	*446.40 FS
41	4		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
42	1		*REAR SUSPENSION CROSS MEMBER - LH	Not Necessary	2,975.00 FS	*- FS
43	1		*REAR TRACK CONTROL ARM - LH UPPER	Bent	507.00 FS	*405.20 FS
44	1		*REAR LOWER CONTROL ARM - LH FRONT	Bent	112.00 FS	*89.60 FS
45	1		*REAR UPPER CONTROL ARM - LH	Bent	407.00 FS	*325.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR TRACK ROD - LH	Bent	155.00 FS	*124.00 FS
47	1		*REAR WHEEL BEARING HOUSING - LH	Bent	903.00 FS	*722.40 FS
48	1		*REAR WHEEL BEARING WITH ASSEMBLY - LH	Bent	404.00 FS	*322.80 FS
49	1		*REAR LEVEL SENSOR - LH	Not Necessary	298.00 FS	*- FS
50	1		*REAR COUPLING ROD - LH	Not Necessary	79.00 FS	*- FS
51	1		*REAR SILENCER - LH	Not Necessary	999.00 FS	*- FS
52	1		*REAR SILENCER DUAL CLIP - LH	Not Necessary	45.00 FS	*- FS
53	1		*REAR EXHAUST SILENCER BRACKET - LH	Not Necessary	38.00 FS	*- FS
54	1		*REAR TYRE (YOKOHAMA) (NPA)	Not Necessary	0.00 FS	*- FS
55	2		*ACRYLIC SEALANT	Necessary	360.00 FS	*360.00 FS
56	2		*CAVITY WAX	Necessary	280.00 FS	*280.00 FS
57	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
58	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
59	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
60	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
61	1		*SUNDRIES	Necessary	1,500.00 FS	*282.32 FS
62	1		*REAR LOWER CONTROL ARM - LH	Bent	785.00 FS	*628.00 FS
63	1		*REAR GAS SHOCK ABSORBER - LH	Not Necessary	276.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 25,300.00 13,374.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY. CHECK FUNCTION	New	360.00	360.00
2	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
5	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	0.00
6	TO REMOVE AND REINSTALL EXHAUST SILENCERS, REAR SUSPENSION ASSEMBLY. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	New	3,200.00	3,200.00
7	TO PLACE VEHICLE ON CAR-O-LINER FOR REPAIRS	New	1,800.00	1,200.00
8	TO DISMANTLE REAR BUMPER AND REAR LID. CUT AND WELD LHS REAR FENDER, OUTER WHEEL HOUSE, INNER WHEEL HOUSE, INNER D-PILLAR, REINFORCEMENTS, AND REAR END PANELLING. ALIGN REAR SUB-STRUCTURE TO SPECIFICATION OF ORIGIN. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	13,200.00	5,000.00
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, OUTER / LINER WHEEL HOUSE, LHS D-PILLAR AND REINFORCEMENTS, LHS SILL PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	6,200.00	3,025.00
10	TO RENEW LHS REAR EXHAUST SILENCER. ALIGN TO POSITION	New	480.00	0.00
11	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT. INSPECT TYRE FOR DAMAGE	New	280.00	280.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			30,104.00	16,849.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >