



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLV 5069 L**
Make & Model : **TOYOTA CHR**
Chassis No. : **ZYX102085469**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>Pl</i>	1	\$45.00	S.N	✓
2	Front number plate garnish <i>C M</i>	1	\$89.70		✓
3	Front grille	1	\$422.92		✓
4	Front grille emblem <i>C M</i>	1	\$1,641.20		✓
5	Front bumper <i>Bu</i>	1	\$441.90		✓
6	Front bumper clip <i>u</i>	10	\$40.00		✓
7	Front bumper reinforcement	1	\$487.30		✓
8	Front bumper side retainer LH <i>D.Y</i>	1	\$123.90		✓
9	Front bumper side retainer RH <i>Sn</i>	1	\$123.90		X
10	Front bumper bracket LH	1	\$201.50		✓
11	Front bumper bracket RH	1	\$201.50		✓
12	Front bumper sponge	1	\$89.50		✓
13	Front bumper sensor	2	\$379.60	S.N	✓
14	Front bumper lower grille <i>C M</i>	1	\$494.20		✓
15	Reverse sensor <i>Short 2/</i>	2	\$379.60	S.N	✓
16	Rear bumper <i>Bu</i>	1	\$398.30		✓
17	Rear bumper clip <i>u</i>	10	\$40.00		✓
18	Rear bumper side retainer LH <i>Sn</i>	1	\$97.80		X
19	Rear bumper side retainer RH <i>Sn</i>	1	\$97.80		X
20	Rear bumper bracket LH	1	\$122.67		✓
21	Rear bumper bracket RH	1	\$122.67		✓
22	Rear bumper reinforcement <i>B</i>	1	\$398.90		✓
23	Rear bumper reflector LH <i>Sn</i>	1	\$62.30		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLV 5069 L**
 Make & Model : **TOYOTA CHR**
 Chassis No : **ZYX102085469**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Rear bumper reflector RH	1	\$62.30		X
25	Rear bumper reflector garnish LH	1	\$108.70		X
26	Rear bumper reflector garnish RH	1	\$108.70		X
27	Rear bumper lower garnish Centre	1	\$397.60		✓
28	Rear bumper tow cover	1	\$21.69		✓
29	Tail door	1	\$1,022.50		✓
30	Tail door lock	1	\$478.40		?
31	Tail door emblem	1	\$61.70		✓
32	Wording "CH-R"	1	\$51.36		✓
33	Wording "HYBRID"	1	\$49.87		✓
34	Tail door garnish	1	\$882.70		X
35	Taildoor reflector LH	1	\$486.70		X
36	Taildoor reflector RH	1	\$489.70		X
37	Tail end panel	1	\$701.25		?
38	Tail end panel garnish	1	\$295.50		?
39	Tail end panel garnish clip	8	\$28.00		?
40	Boot weatherstrip	1	\$361.70		X
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLV 5069 L** Submit By : **Carmen Lim**
Make & Model : **TOYOTA CHR** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,600.00	800-900
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,400.00	1000
3	To check wiring	\$50.00	40
4	To remove & refit front bumper sensor	\$120.00	50
5	To remove & refit rear bumper sensor	\$120.00	50
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	?
7	To remove & refit rear windscreen.	\$120.00	✓
8	To tuff coat.	\$150.00	30
9	To transfer boot mechanism to new boot	\$120.00	60
10	To conduct water leakage tests to ensure proper air and sealing	\$120.00	?

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLV 5069 L

*Not authorized
Respray B4 paint*

Parts	(a) Cost / List Price Items	\$	11,306.33
	Plus/Less 25%	\$	2,826.58
	Total of Cost / List	\$	8,479.75
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	804.20
Total Parts Cost		\$	9,283.95
Labour		\$	3,950.00
Total		\$	13,233.95

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kenneth

Company

:

UIC

Survey conducted on

:

9/4/19

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : *07* day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

:

[Signature]

Date:

9/4/19