

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0456/2019/DY
Date : 9-Apr-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Ding Ah Ding
Address : Blk 989C Jurong West St 93
#03-669
Singapore 643989
Telephone : HP +65 96337528
Type of Claim : Own Damage Claims
Policy No. : 1800062578
Vehicle No : **SMH 2528 K**
Model Code : Audi A6 1.8 TFSI S tronic
Model / Year : May-18
Engine No : CYG 024506
Chassis No : WAUZZZ4G9JN057145
Mileage : 31699
Date In : 9-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Apr-19
Place of Accident : KJE merging to PIE towards-

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMH 2528 K

S/N	Nature of Jobs	Estimated Charges
1	To remove , check and reinstall front wire harness for headlights, horns, outside temperature sensor headlight washer assy and front parking aid.	s/n \$ 480.00 ✓
2	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew accoding to damage.	s/n \$ 360.00 ✓
3	To renew front windscreen.	s/n \$ 480.00 X.
4	To remove and reinstall rhs 1/4 glass to facilitate chrome trim renewal.	s/n \$ 300.00 X.
5	To dismantle front bumper, rhs front fender, rhs wing mirror assy, rhs headlight, rhs sill panel trim and rear bumper. To renew front bumper, rhs front fender, rhs headlight and rhs wing mirror assy. Reorganize crash management. Reinstall all parts removed.	1500. \$ 4,200.00 Bumper Front 1dy Bumper Reas. 1dy Headlamp 1/2 dy. Mirror 1/2 dy 3 days.
SUB-TOTAL LABOUR CHARGES		: \$ 1,620.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMH 2528 K

S/N	Nature of Jobs	Estimated Charges
6	To respray front bumper, bonnet, rhs front fender, rhs upper A-pillar, rhs wing mirror cover, rhs front door, rhs rear door, rhs sill panel trim, door handles, rhs rear fender and rear bumper.	4550. \$ 7,800.00
7	To renew rhs front rim and rhs rear rim. To carry out wheel alignment.	s/n \$ 320.00 X
8	To carry out diagnostic check.	s/n \$ 192.00 /
TOTAL LABOUR CHARGES		: \$ 9,932.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 2528 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>del</i>	\$ 2,445.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 453.00	✗
3	FRONT BUMPER GRILLE-LOWER CENTRE <i>new</i>	\$ 106.00	✗
4	FRONT BUMPER LOCKING CLIP <i>new</i>	14 \$ 47.00	✗
5	FRONT BUMPER COVER ADAPTER-RH <i>2 new</i>	\$ 31.00	✗
6	FRONT BUMPER CLOSING ELEMENT-RH	\$ 178.00	✗
7	FRONT BUMPER SPOILER <i>Regis</i>	\$ 203.00	✗
8	FRONT BUMPER LOWER TRIM SPOILER <i>Regis</i>	\$ 768.00	✗
9	RADIATOR GRILLE <i>at</i>	\$ 1,640.00	✓
10	RADIATOR GRILLE COVER <i>new</i>	\$ 31.00	✗
11	FRONT SUPPORT SENSOR-LH/RH <i>new</i>	2 \$ 112.00	✗
12	FRONT AIR GUIDE GRILLE-RH <i>at</i>	\$ 517.00	✓
13	FRONT BUMPER COVER -RH <i>new</i>	\$ 42.00	✗
14	FRONT WHEEL SPOILER-RH <i>new</i>	\$ 225.00	✗
15	FRONT STONE CHIP GUARD-RH <i>new</i>	\$ 66.00	✗
16	ADHESIVE TAPE <i>?</i>	\$ 50.00	?
17	FRONT BUMPER COVER CAP - LH	\$ 47.00	✗
18	FRONT BUMPER COVER CAP - RH	\$ 47.00	✗
19	LED HEADLIGHT LIFT CYLINDER - RH	\$ 204.00	✗
20	HOSE FOR LED HEADLIGHT WASHER SYSTEM	\$ 426.00	✗
SUB TOTAL SPARE PARTS		\$ 7,638.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 2528 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FOAM FILLER PIECE	\$ 193.00	✓
22	FRONT BUMPER REINFORCEMENT BEAM	\$ 674.00	✓
23	FRONT BUMPER GUIDE PIECE-RH	\$ 31.00	✓
24	FRONT BUMPER COVER	\$ 100.00	✓
25	CAUTION' SIGN	\$ 12.00	✓
26	FRONT FENDER-RH	\$ 1,158.00	✓
27	FRONT FENDER ATTACHMENT PARTS-RH	\$ 952.00	✓
28	FRONT STONE CHIP GUARD-RH	\$ 102.00	✓
29	FRONT FENDER BRACE-RH	\$ 70.00	✓
30	FRONT WHEEL HOUSING LINER-RH	\$ 256.00	✓
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH	\$ 61.00	✓
32	LED HEADLIGHT MOUNTING-RH	\$ 100.00	✓
33	LED HEADLIGHT - RH	\$ 6,454.00	✓
34	LED HEADLIGHT FOR POWER MODULE FOR DIPPED BEAM-RH	\$ 508.00	✓
35	LED HEADLIGHT FOR POWER MODULE FOR DAYTIME LIGHTS-RH	\$ 492.00	✓
36	LED HEADLIGHT RANGE CONTROL MOTOR-RH	\$ 295.00	✓
37	FRONT SENSOR-OUTER	\$ 208.00	✓
38	FRONT SENSOR-INNER	\$ 194.00	✓
39	FRONT SENSOR SEAL RING	\$ 5.00	✓
40	RADAR SENSOR CONTROL UNIT-RH	\$ 6,177.00	✓
SUB TOTAL SPARE PARTS		\$ 18,042.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 2528 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	COVER FRAME FOR RADAR SENSOR <i>den</i>	\$ 12.00	+
42	FRONT EXTERIOR MIRROR MOUNTING - RH <i>lit</i>	\$ 1,197.00	✓
43	FRONT EXTERIOR MIRROR MOUNTING HOUSING - RH <i>Ryir</i>	\$ 179.00	+
44	FRONT MIRROR GLASS FOR WING MIRROR - RH <i>missy</i>	\$ 1,451.00	✓
45	FRONT TURN SIGNAL INDICATOR LIGHT - RH <i>lit</i>	\$ 116.00	✓
46	WARNING DISPLAY FOR LANE CHANGE ASSIST - RH <i>nu</i>	\$ 176.00	+
47	FRONT TRIM FOR B PILLAR- RH <i>lit</i>	\$ 143.00	✓
49	FRONT WINDOW SLOT SEAL WITH TRIM STRIP - RH <i>lit</i>	\$ 287.00	✓
50	FRONT ROOF MOLDING-RH <i>den</i>	\$ 430.00	+
51	FRONT ROOF MOLDING COVER TRIM-RH ?	\$ 303.00	?
52	REAR WINDOW SLOT SEAL WITH TRIM STRIP-RH <i>den</i>	\$ 237.00	+
53	REAR TRIM FOR PILLAR C-RH <i>lit</i>	\$ 136.00	✓
54	REAR TRIM FOR PILLAR C- RH OUTER <i>den</i> ?	\$ 68.00	den ?
55	REAR TRIM STRIP FOR SIDE WINDOW CHROME-RH <i>nu</i>	\$ 217.00	+
56	REAR COVER TRIM FOR PILLAR C-RH <i>den</i> ?	\$ 168.00	den ?
57	REAR TRIM FOR PILLAR B-RH ?	\$ 143.00	?
58	REAR STONE GUARD FILM-RH <i>den</i>	\$ 100.00	✓
59	1 SET ATTACHMENT PARTS CLIP ?	\$ 75.00	?
60	1 SET ATTACHMENT PARTS ADHESIVE TAPE ?	\$ 14.00	?
SUB TOTAL SPARE PARTS		\$ 5,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 2528 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	WINDSCREEN <i>new</i>	\$ 1,436.00	<i>x</i>
62	GEL FOIL FOR RAIN SENSOR <i>new</i>	\$ 124.00	<i>x</i>
63	FRONT WATER DEFLECTOR STRIP-LH/RH <i>new</i>	2 \$ 114.00	<i>x</i>
64	ALUMINIUM RIM- RH FRONT / REAR <i>new</i>	2 \$ 1,447.00	<i>x</i>
65	RUBBER VALVE <i>new</i>	4 \$ 11.00	<i>x</i>
66	WATER DEFLECTOR STRIP - RH <i>new cut</i>	\$ 57.00	<i>x</i>
67	ALUMINIUM RIM <i>new</i>	2 \$ 1,447.00	<i>x</i>
68	RUBBER VALVE FOR RIM <i>new</i>	4 \$ 11.00	<i>x</i>
69	FRONT NUMBER PLATE <i>m</i>	S/N \$ 60.00	<i>-</i>
70	FRONT WINDSCREEN SEALANT <i>new</i>	S/N \$ 200.00	<i>x</i>
71	1/4 GLASS SEALANT <i>new</i>	S/N \$ 100.00	<i>x</i>
72	SUNDRIES <i>?</i>	\$ 800.00	<i>?</i>
TOTAL SPARE PARTS		\$ 36,939.00	
TOTAL LABOUR CHARGES		\$ 9,932.00	
GRAND TOTAL		\$ 46,871.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian King

Surveyed Date

: 10/04/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant