

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0454/2019/DY
Date : 9-Apr-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Stephanus Dwidianto Gunawan
Address : 521 Bedok Reservoir Road
#02-73
Singapore 479277
Telephone : HP +65 82685031
Type of Claim : Own Damage Claims
Policy No. : 1900011684
Vehicle No : **SMH 6658 S**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Jan-19
Engine No : CHZ C26051
Chassis No : WAUZZZ8V0K1013701
Mileage : 3155
Date In : 8-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Apr-19
Place of Accident : Junction of Yishun Central

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMH 6658 S

S/N	Nature of Jobs	Estimated Charges
1	To remove , check and reinstall front wire harness for headlights, horns, outside temperature sensor headlight washer assy.	s/n \$ 360.00 ✓
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Reorganize crash management components. Reinstall all parts removed.	\$ 2,100.00 500 ✓
3	To respray front bumper and lhs front fender.	\$ 1,500.00 550 ✓
4	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>4,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 6658 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Replaced</i>	\$ 1,667.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	+
3	FRONT BUMPER GUDIE SECTION-LH <i>Repl</i>	\$ 31.00	✓
4	FRONT BUMPER GRILLE-CENTER <i>new</i>	\$ 133.00	+
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>new</i>	\$ 445.00	+
6	FRONT BUMPER CLOSING ELEMENT-LH <i>new</i>	\$ 445.00	+
7	FRONT BUMPER COVER TRIM-LH <i>new</i>	\$ 135.00	+
8	FRONT ADAPTER WHEEL HOUSING LINER-LH <i>torn?</i>	\$ 34.00	✓ ?
9	RADIATOR GRILLLE <i>new</i>	\$ 1,176.00	+
10	RADIATOR GRILLLE CLOSING ELEMENT <i>new</i>	\$ 158.00	+
11	FRONT BUMPER AIR GUIDE GRILLE-LH <i>new</i>	\$ 171.00	+
12	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	\$ 660.00	+
13	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$ 157.00	+
14	FRONT BUMPER COVER <i>new</i>	\$ 111.00	+
15	SIGNAL HORN HIGH TONE-LH <i>new</i>	\$ 173.00	+
16	FRONT FENDER -LH <i>new</i>	\$ 708.00	+
17	FRONT FENDER ATTACHMENT PARTS-LH <i>new</i>	\$ 65.00	+
18	FRONT FENDER BRACE-LH <i>3 new</i>	\$ 81.00	+
19	FRONT FENDER BRACKET-LH <i>3 new</i>	\$ 33.00	+
20	FRONT WHEEL HOUSING LINER-LH <i>torn</i>	\$ 146.00	✓
SUB TOTAL SPARE PARTS :		\$ 6,699.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 6658 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-LH <i>new ?</i>	\$ 75.00	?
22	LED HEADLIGHT-LH ?	\$ 5,458.00	?
23	LED HEADLIGHT LIFT CYLINDER FOR WASHER SYSTEM-LI <i>new</i>	\$ 128.00	X
24	HOSE FOR LED HEADLIGHT WASHER SYSTEM-LH <i>new</i>	\$ 61.00	X
25	WASH WATER RESERVOIR <i>new</i>	\$ 173.00	X
26	WINDSCREEN WASHER SYSTEM PUMP <i>new</i>	\$ 112.00	X
27	HEADLIGHT PUMP FOR WAHER SYSTEM <i>new</i>	\$ 139.00	X
28	AIR CONDITIONER STICKER ?	\$ 7.00	X
29	SIGN 'CAUTION' <i>new</i>	\$ 13.00	X
30	FRONT CAR PLATE NO. S/N	\$ 40.00	X
31	SUNDRIES ?	\$ 600.00	?
TOTAL SPARE PARTS		\$ 13,505.00	
TOTAL LABOUR CHARGES		\$ 4,152.00	
GRAND TOTAL		\$ 17,657.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Lj

Surveyed Date

:

10/04/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Authorised Repairs, 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant