



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 1

Vehicle No. GW3468K TOYOTA DYNA

TPA19. 1723SR
Jic le.

WHITE No.		GW3468K TOYOTA DYNA		7P A16 Jic le.		1723SR	
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	ADJUSTMENT			
PARTS (LIST ITEMS)							
1	REAR TAILGATE <i>Dented</i>	3623.20 2717.40	1837.50	1248			
1	REAR TAILGATE SIDE L BRACKET <i>Best</i>		166.00	✓			
1	REAR TAILGATE LAMP <i>Not new</i>		393.75	X			
1	REAR END PANEL (LOWER MEMBER) <i>Dented</i>		1341.90	495			
2	REAR TAILLAMP LH & RH @\$359.10 <i>can d</i>		712.20	500.20			
2	REAR LOWER MEMBER BRACKET @\$145.10 <i>new</i>		390.81	X			
1	REAR CHASSIS FRAME (DECK SUPPORT) <i>Regis</i>		1659.00	X			
1	REAR FLOOR DECKING <i>Regis</i>		2079.00	X			
1	REAR CHASSIS FRAME U BOLTS <i>new</i>		367.50	+			
1	REAR EXHAUST PIPE <i>Best</i>		504.00	✓			
1	REAR EXHAUST PIPE BRACKET <i>new</i>		126.00	X			
1	REAR TOW HOCK <i>new</i>		78.75	X			
2	REAR TAILGATE STEP BRACKET @84 DM		168.00	✓			
1	REAR TAILGATE INNER ALUMINIUM COVER PLATE <i>new</i>		787.50	+			
2	REAR TAILGATE HINGE 1 @\$85.00 <i>Best</i>		170.00	✓			
2	REAR TAILGATE STOPPER LH & RH @\$35.00 <i>ut</i>		70.00	✓			
2	REAR NUMBER PLATE PANEL LH & RH @\$151.00 <i>Best</i> <i>Tail lamp</i>		302.00	✓			
			11069.91				
less 25%			2767.48	25%			
			8302.43				
SPECIAL NETT ITEMS							
1 SET	REVERSE SENSOR <i>new</i>	TOTAL PARTS	300.00	X			
1	STICKER "13 PAX " <i>2</i>		70.00	15			
1	STICKER " 70 KM/H " <i>1</i>		70.00	15			
1	TAILGATE " TOYOTA " STICKER <i>new</i>		100.00	✓			
1	CAR PLATE <i>Best</i>		50.00	30			
			8892.43				

160



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Vehicle No. GW3468K TOYOTA DYNA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace parts	2200.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	800
3	To remove, refix wiring system at accident damaged areas	250.00	30
4	To carry out chassis alignment	350.00 ✓	
5	To perform anti-rust treatment on affected areas	270.00	80
6	To remove and refix rear taillamp	80.00	X
7	To remove and replace exhaust pipe	150.00	80
8	To remove rear deck to facilitate repairs	300.00	
	Labour Total :	4900.00	
	TOTAL (PARTS & LABOUR) :	13792.43	

2520

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5387.40

1/s A.3K.

06 Days

(A.3K)