

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: PIP	S\$ 5282.98	days) Reduction: 4209.93 = 28	Email: ☐ Call: ☐
FINAL SETTLEMENT	Date/Time: 10/7/2020	Confirm with: June	Email: ☐ Call: ☐
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.: 27	If NO or B 28, Ass. Lia:
Repair Cost: (WAT)	S\$ 5652.57	Front to rear	
Loss of Rental (LOR):	S\$ - (days)		
Loss of Use (LOU):	S\$ 260.00 (5 x 6 days)		
Loss of Income (LOI):	S\$ - (5 x days)		
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ (Tick only one)			
GIA/LTA Search:	S\$ -		
Medical:	S\$ -		1) Claim status: No Claim/Reject/Private Settle
Disbursement:	S\$ -	(e.g. Tow/Independent)	2) Report Format: TP
Legal Cost:	S\$ -		3) Survey fee: \$350.
Total:	S\$ 6012.57	Global Sum S\$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email: ☐ Call: ☐
Payee 1:	S\$ 6012.57	Name 1: Cheng Hoe motor Pte Ltd	
Payee 2 (Strike if N.A.):	S\$ -	Name 2:	
Payee 3 (Strike if N.A.):	S\$ -	Name 3:	

ASS. REC. BY:

REF:

AAA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

8105k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5-6 days

Res.: Yes or No

Lum Sum:

1-8-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 3409C

Yr Regn:

05.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 218i

c.c

1499

Colour:

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

32418

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA 2F12000V758169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

5

mm

L/Bal.

6

mm

L/Bal.

5

mm

D.O.A.

8/4/19

D.O.I.

10/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to
10/4 Est not ready

PIP 5282.78 (Red = 2079.93 / 28.1)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS SI

Parking

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1991375/WS

Date: 10 Apr 2019

Policy No: 5108317492

Veh Reg No: SLC3409C

Make/Model: BMW 2181 COUPE AT
HID ABS NAV SR

Chassis No: WBA2F12000V758169

Engine No: F4441382B38B15A

Reg. Date: 11/05/2016

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 08/04/2019

TP Veh Reg No: SHD395U

Not Authorised

Resurvey B4 paint

85282.78

4 days

Estimate Repair Cost to Vehicle No :SLC3409C

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR BUMPER	1,018.95	1 PC	1,018.95	✓
2 REAR BUMPER REINFORCEMENT	416.45	1 PC	416.45	✓
3 REAR BUMPER CENTRE LOWER MOULDING	95.50	1 PC	95.50	✓
4 REAR BUMPER REFLECTOR LH	38.60	1 PC	38.60	✓
5 REAR BUMPER SIDE RETAINER LH	49.50	1 PC	49.50	✓
6 REAR BUMPER CLIP	5.00	6 PCS	30.00	✓
7 REAR PANEL	497.45	1 PC	497.45	✓
8 REAR PANEL INNER TOP GARNISH	79.15	1 PC	79.15	✓
9 REAR BUMPER INNER GARNISH	48.35	1 PC	48.35	✓
10 TAILLAMP LH	398.90	1 PC	398.90	✓
11 REVERSE SENSOR	236.80	2 PCS	473.60	✓
12 REAR EXHAUST PIPE	908.05	1 PC	908.05	✓
13 REAR BOOT	1,136.15	1 PC	1,136.15	✓
14 REAR BOOT LOGO	71.25	1 PC	71.25	✓
15 REAR BOOT EMBLEM -2181	79.10	1 PC	79.10	✓
16 REAR BOOT INNER RUBBER	125.80	1 PC	125.80	✓
			5,466.80	
		Less 5%	273.34	5,193.46
Labour				
17 REMOVE AND REFIX REAR BUMPER ASSY, TAILALMPS, RR BOOT & ATTACHMENT, CUT, WELD AND RENEW RR PANEL, KNOCK AND REPAIR RR LH FENDER AND RE-ALIGN TO SA ME	1,000.00	1 LA	1,000.00	8501
18 PUTY AND RESPRAY ON RR LH FENDER, BOOT, RR BUMPER, RR PANEL AND RR AFFECTED AREAS	1,000.00	1 LA	1,000.00	8001
19 REMOVE AND REFIX RR EXHAUST AND CHECK SYSTEM	60.00	1 LA	60.00	✓
			2,060.00	2,060.00
			Total	S\$ 7,253.46
			Add GST @ 7%	507.74
			Total Amount Payable	S\$ 7,761.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

7362.71

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SUPP 1

SLC3409C

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1991375/WS

Date: 12 Apr 2019

Policy No: 5108317492

Veh Reg No: SLC3409C

Make/Model: BMW 2181 COUPE AT
HID ABS NAV SR

Chassis No: WBA2F12000V758169

Engine No: F4441382B38B15A

Reg. Date: 11/05/2016

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 08/04/2019

TP Veh Reg No: SHD395U

Estimate Repair Cost to Vehicle No :SLC3409C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Net Price				
1 REVERSE SENSOR BRACKET	115.00	1 SET	115.00	
			115.00	
		Less 5%	5.75	109.25
Total				S\$ 109.25
GST Amount				S\$ 7.65
Total Amount Payable				S\$ 116.90

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cor - ϕ
Lou 6 + 2 = 8 x ϕ 80 = 640
L7A - MIL

SLC 3409 C.

1 pc rear bumper Br-

_____ reinforcement Br-

_____ reinforcement 4x bracket ?

_____ Centre lower moulding scr-

_____ 4x reflector cr-

_____ 4x side reflector cr-

4pc _____ clips - cr

1 pc rear panel ?

_____ inner top garnish cr x

1 pc rear bumper inner garnish ?

1 pc 4x tail lamp - cr

2 pc rear 4x reverse sensors. 4x star

1 pc rear exhaust pipe. ?

1 pc rear boot Br-

_____ logo - cr

_____ emblem 218i - cr

_____ inner rubber cr x

CHENG HSE

67557719

SLC 3409C.

① R & R rear bumper assy, tail lamps,
rear boot and attachment, To cutting,
welding and renew rear panel, R & R
rear $\frac{1}{4}$ fender and realign the same \$1000 ✓?

② Buff & respray on rear $\frac{1}{4}$ fender, boot,
rear bumper, rear panel and rear
affected area \$1000^{per} ✓

② R & R rear exhaust and check system \$60 ✓?

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2279H

Vehicle Details

Vehicle No.: SLC3409C
Vehicle to be Exported: No
Intended Deregistration Date: 08 Apr 2019
Vehicle Make: B.M.W.
Vehicle Model: 218i COUPE AT HID ABS NAV SR
Primary Colour: Red
Manufacturing Year: 2016
Engine No.: F4441382B38B15A
Chassis No.: WBA2F12000V758169
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$27,426.00
Original Registration Date: 11 May 2016
First Registration Date: 11 May 2016
Transfer Count: 2
Actual ARF Paid: \$25,397.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 10 May 2026
PARF Rebate Amount: \$19,047.00

Intended COE Rebate Details

COE Expiry Date: 10 May 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$51,010.00
COE Rebate Amount: \$36,159.00
Total Rebate Amount: \$55,206.00

The information contained herein is correct as at 08 Apr 2019

OK

Service Request Details

Claim

S9MD1JHC

Reference

None 

Loss Date

8 April 2019

Report Date

9 Apr 2019 9:40:00 AM

Request Date

10 April 2019

Due Date

10 April 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Start Date	Finish Date
------------	-------------

Vehicle Information

Incident Vehicle Registration #

SLC3409C

Make

TPVD BMW

Model

218i COUPE

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Navigation](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[View Messages](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/1/2020

Survey Details:

Date of loss	8-Apr-19
Date of appointment	10-Apr-19
Date of survey	10-Apr-19
Location of survey	CHENG HOE MOTOR PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLC 3409C
Make and Model	BMW 218i
Date of registration	11-May-16
Parf Rebate	
Market Value	\$ 105,000.00
Parf Rebate	\$ 55,206.00
Nett Loss	\$ 49,794.00

Repair details:

Initial Estimate	7,362.71
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 3,772.78
Check items (estimate)	\$ -
Labour	\$ 1,510.00
Total	\$ 5,282.78
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>6 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVENUE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

06 RECOMMENDED REPAIR DAYS + 1 SUNDAY + 1 PRS = 8 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 5,652.57	W/GST
Loss of use	\$ 480.00	6days x \$60
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ -	
Others	\$ -	
Proposed Total	\$ 6,132.57	

 <MANDATE IA> - S9M01JHC {ACCIDENT INVOLVING SHD 395U (OI) & SLC 3409C (TP) ON 08/04/2019}

Type

 Question

Message

LIABILITY: 100% BOLA 527 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$6132.57 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 16/01/2020

[Reply](#)



Pls proceed DS with below revised quantum

Type

🔔 Question

Message

COR: \$4522.06(-20% discount for lump-sum repair, incl. GST); LOU: \$300.00 (\$50/day for 6 days). Total: \$4822.06. You have global-sum mandate up to \$4850.00 (all-in)

Reply

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 08/04/2019

TP Veh Reg No: SHD395U

NO: **CL8190922**
Date: 29 Aug 2019
Policy No: 5108317492
Veh Reg No: **SLC3409C**
Make/Model: BMW 2181 COUPE AT
HID ABS NAV SR
Job No: JC1600397

Description

Quantity

List Price

PAGE:1

Amount

S\$

S\$

To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges.

1 PC

S\$ 5,282.78

S\$ 5,282.78

(As recommended by your appointed surveyor)

Total

S\$ 5,282.78

Add GST @ 7%

369.79

Total Amount payable

S\$ 5,652.57

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

Cecilia Chong (LKK Auto)

From: Cheng Hoe Motor Pte Ltd (June-Yishun) <chmotor@singnet.com.sg>
Sent: Tuesday, 11 February 2020 10:50 AM
To: CHIONH Hock San Christopher
Cc: Cecilia Chong (LKK Auto)
Subject: DV- ACCEPTANCE - Your ref: SLC3409C Our ref: S9M01JHC (SHD395U)
Attachments: 3409.jpg

Hi Christopher,

Signed DV is attached.

Pls assist to process payment to be made payable to "CHENG HOE MOTOR PTE LTD"

Thank you.

Rgds
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: CHIONH Hock San Christopher
Sent: Monday, February 10, 2020 4:18 PM
To: Cheng Hoe Motor Pte Ltd (June-Yishun)
Cc: ceciliachong@lkkauto.com
Subject: RE: [EXTERNAL] ACCEPTANCE - Your ref: SLC3409C Our ref: S9M01JHC (SHD395U)

Dear June,

Please see attached DV.



Warmest Regards,

Christopher Chionh | Senior Manager, Claims Services

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: <mailto:cheekeong.pan@axa.com.sg>

DID: (65) 6880 5594

HP: (65) 8189 3051

axa.com.sg



From: Cheng Hoe Motor Pte Ltd (June-Yishun) <chmotor@singnet.com.sg>
Sent: Monday, February 10, 2020 3:55 PM
To: CHIONH Hock San Christopher <chris.chionhhs@axa.com.sg>
Cc: ceciliachong@lkkauto.com
Subject: [EXTERNAL] ACCEPTANCE - our ref: SLC3409C Our ref: S9M01JHC (SHD395U)

Dear Sir,

Your offer as below is accepted.

Pls forward DV.

Thank you.

Rgds
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: CHIONH Hock San Christopher
Sent: Monday, February 10, 2020 2:44 PM
To: chmotor@singnet.com.sg
Cc: ceciliachong@lkkauto.com
Subject: Your ref: SLC3409C Our ref: S9M01JHC (SHD395U)

Without Prejudice

Dear June,

We are prepared to revise our offer as follows:

COR:	\$5652.57
LOU:	\$360 (\$60x6)
Total:	\$6012.57

Please advise acceptance.



Warmest Regards,
Christopher Chionh | Senior Manager, Claims Services

axa.com.sg



-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is

- prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 06 SEP 2019

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SLC3409C & SHD395U ON 08/04/2019
CHURCH ST, TURN RIGHT INTO TELOK AYER ST.**

We are authorized by SLC3409C for their above matter.

Record reveals that you are the insurer of SHD395U. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 5652.57
2. Loss of Use (6 days x \$80/Day)	S\$ 640.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 0.00
TOTAL	S\$ 6292.57

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19006361/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: PETER

Date : 19-02-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 395U	Veh. Inspected	SLC 3409C
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01JHC	Excess (\$)	0.00
Assign From		Assign Date	10/04/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 218i (A)	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA2F12000V758169	Colour	METALLIC RED
Odometer	32418	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 R18	GOODYEAR	6 mm
L/H Front Tyre	225/40 R18	GOODYEAR	6 mm
R/H Rear Tyre	225/40 R18	GOODYEAR	5 mm
L/H Rear Tyre	225/40 R18	GOODYEAR	5 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.**5. General Information**

Accident Date	08/04/2019	Inspection Date	10/04/2019
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. RemarksA) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 3409C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N) (CONSISTENT)	BENT	1,018.95	1,018.95
1	REAR BUMPER REINFORCEMENT (N) (CONSISTENT)	BENT	416.45	416.45
1	REAR BUMPER CENTRE LOWER MOULDING (N) (CONSISTENT)	CRACKED	95.50	95.50
1	REAR BUMPER REFLECTOR LH (N) (CONSISTENT)	CRACKED	38.60	38.60
1	REAR BUMPER SIDE RETAINER LH (N) (CONSISTENT)	DISTORTED	49.50	49.50
6	REAR BUMPER CLIP @\$5.00 (N) (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR PANEL (N) (CONSISTENT)	TO REPAIR SEE LABOUR	497.45	-
1	REAR PANEL INNER TOP GARNISH (N) (CONSISTENT)	SERVICEABLE	79.15	-
1	REAR BUMPER INNER GARNISH (N) (CONSISTENT)	CRACKED	48.35	48.35
1	TAILLAMP LH (N) (CONSISTENT)	CRACKED	398.90	398.90
2	REVERSE SENSOR @\$236.80 (N) (CONSISTENT)	SHORTED	473.60	473.60
1	REAR EXHAUST PIPE (N) (CONSISTENT)	TO REPAIR SEE LABOUR	908.05	-
1	REAR BOOT (N) (CONSISTENT)	BENT	1,136.15	1,136.15
1	REAR BOOT LOGO (N) (CONSISTENT)	NECESSARY	71.25	71.25
1	REAR BOOT EMBLEM -218i (N) (CONSISTENT)	NECESSARY	79.10	79.10
1	REAR BOOT INNER RUBBER (N) (CONSISTENT)	SERVICEABLE	125.80	-
1	SET REVERSE SENSOR BRACKET (N) (CONSISTENT) (ADDITIONAL)	NECESSARY	115.00	115.00
	LESS 5% DISCOUNT		-279.09	-198.57
			5,302.71	3,772.78
LABOUR				
	REMOVE AND REFIX REAR BUMPR ASSY ,TAILLAMPS ,RR BOOT & ATTACHMENT ,CUT ,WELD AND RENEW RR PANEL ,KNOCK AND REPAIR RR LH FENDER AND REALIGN TO SAME.INCLUSIVE OF THE REPAIR OF REAR PANEL AND REAR EXHAUST PIPE .		1,000.00	650.00
	PUTTY AND RESPRAY ON RR LH FENDER ,BOOT ,RR BUMPER ,RR PANEL AND RR AFFECTED AREAS.		1,000.00	800.00

Report Ref No. CC4/ASM19006361/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX RR EXHAUST AND CHECK SYSTEM.		60.00	60.00
			2,060.00	1,510.00
GRAND TOTAL			7,362.71	5,282.78
RECOMMENDED COST OF REPAIRS				5,282.78

Report Ref No. CC4/ASM19006361/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

S9H01JHC

Reference

CCA/ASM19006361/Nga342

Loss Date

8 April 2019

Report Date

9 Apr 2019 9:40:00 AM

Request Date

10 April 2019

Due Date

Vendor Name

L&K AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SUC349WC

Make

TPVD BMW

Model

218I COUPE

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, S69111, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Auto Invoice

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Mentimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (2).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2020
 Discharge Voucher.png	Forms / Claim Documents	Satisfaction / Discharge Voucher	CHIONH Hock San Christopher	13 February 2020
 PARF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 MANDATE IA DO 16012020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 January 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 SURVEYOR APPOINTED.mg	Letters and Correspondence	Surveyor / Assessor	VISHNU BATHAM Shekhar	10 April 2019
 LIST OF SURVEYOR SRT.mg	Letters and Correspondence	Surveyor / Assessor	VISHNU BATHAM Shekhar	9 April 2019
 CIA SLC3409C TP PDF	Reports & Statement	CIA Report	VISHNU BATHAM Shekhar	9 April 2019
 EMAIL TP PH1.mg	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	9 April 2019