

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

8-Apr-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8628 G


1 pc	Rear bumper <i>X repair</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X su</i>	\$	206.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X su</i>	\$	36.00
1 pc	Rear bumper inner sponge <i>X su</i>	\$	114.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X su</i>	\$	36.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X su</i>	\$	108.00
		\$	1,196.00
		Less 10%	\$ 119.60
		\$	1,076.40

S/NETT

1 set	Rear bumper clips <i>X su</i>	\$	48.00
1 set	Reverse sensor <i>X su</i>	\$	280.00
1 pc	Rear bumper top protector <i>X su</i>	\$	80.00 50
Sundry		\$	50.00
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00 120.00 <i>X su</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 180.00 <i>X su</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc.		\$	500.00 200
To putty and spray painting on rear bumper, end panel <i>X</i>		\$	400.00 180
To apply rustproofing on the repaired and replaced panels.		\$	120.00 120.00 <i>X su</i>
		\$	2,854.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.



Kahr Uley
9/4/19 1635h
2 hrs
U/S
At the Repair shop