

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9798G**AAD1904-072***Not Authorised*
C/Sing &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9798G

VF1ABL15AUC277292

RENAULT

LATITUDE

7.4.2019

III

14/4/2014

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>BT/CM</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>B</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Dr's</i> 113.47	✓
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMPR RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	✓
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMPR RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Dr's</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>B</i> 225.95	✓
13	1 BOOT REAR	\$	<i>B</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>DD/Dr's</i> 323.05	✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>SL</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	X
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	X
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	X
26	1 BOOT LOCK	\$	<i>Dr's</i> 202.67	✓
27	1 BOOT LOCK CATCH	\$	<i>SL</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	X
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	X

Trans-cab Auto Services Pte Ltd**AAD1904-072**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9798G

30	1 FENDER PANEL REAR RH	\$	R	3,299.13	X
31	1 WHEELARCH REAR RH	\$	Sn	543.47	X
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	X
33	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
34	1 WHEELARCH REAR LH	\$	Sn	543.47	X
35	1 TAILLAMP LH	\$	mgm	552.55	✓
36	1 TAILLAMP PANEL LH	\$	R	986.70	X
37	1 TAILLAMP RH	\$	cm	552.55	✓
38	1 TAILLAMP PANEL RH	\$	R	986.70	X
39	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	cm	404.56	✓
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
42	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
43	1 EXHAUST REAR	\$	R	7,489.05	X
44	1 EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	35,197.49
10%	\$	3,519.75
	\$	31,677.74

Special Nett

1	1SET PARKING AID	\$	Short	700.00	Goosn
2	1SET REAR BUMPER CLIP	\$	nn	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	nn	24.20	X
12	1 REAR BOOT STICKER 'TRANS-CAB'	\$	nn	80.00	30sn
13	1 REAR BOOT STICKER '6555-3333'	\$	nn	80.00	30sn ✓

Trans-cab Auto Services Pte Ltd**AAD1904-072**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9798G

15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i>	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i>	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	<i>na</i>	28.00	X
18	1 FENDER INNER TRIM CLIP LH	\$	<i>na</i>	28.00	X
19	1 TAILLAMP CLIP RH	\$	<i>na</i>	5.00	✓
20	1 TAILLAMP CLIP LH	\$	<i>na</i>	5.00	✓
21	2 REAR WINDSCREEN SELANT	\$	<i>na</i>	80.00	X
22	1 WINDSCREEN MOULDING	\$	<i>na</i>	100.00	X
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	X
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sm</i>	385.00	X
25	1 SPARE TYRE	\$	<i>sm</i>	330.00	X

TOTAL \$ 2,280.02**TOTAL PARTS \$ 33,957.76****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>8801</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>8001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>601</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1904-072**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9798G

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	4 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	4 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	4 380.00	X

TOTAL \$ 14,340.00**Over All Total \$ 48,297.76****(LUMP SUM)****Repair Days****20 DAYS****5 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: