

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 900L**AAD1904-081***Not Notified**Recovery B4 painting*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 900L

WDD2120012B223329

MERCEDES BENZ

E 220 BLUETEC

7.4.2019

AIG

16/12/2015

PART**LIST**

1	1	Rear Bumper	\$	<i>Buddi</i> 3,105.00 ✓
2	1	Rear Bumper Lower	\$	<i>ndidit</i> 1,080.00 ✓
3	1	Rear Bumper Reinforcement	\$	910.00 ?
4	1	Rear Bumper Centre Pad	\$	<i>nsp</i> 307.83 X
5	1	Rear Bumper Side Pad	\$	<i>nsp</i> 186.33 X
6	1	Rear Bumper Tow Hook Cover	\$	<i>sn</i> 42.00 X
7	1	Rear Bumper Bracket	\$	<i>n</i> 22.50 X
8	1	Rear Bumper Side Retainer Bracket	\$	<i>dis</i> 132.00 ✓
9	1	Rear Bumper Inner Frame	\$	297.00 ?
10	1	Rear Bumper Bottom Bracket	\$	<i>cm</i> 60.00 ✓
11	1	Rear Bumper Top Bracket	\$	<i>n</i> 129.00 X
12	1	Rear Bumper Side Holder Bracket	\$	<i>n</i> 135.00 X
13	1	Rear Bumper Inner Bracket LH	\$	<i>n</i> 198.00 X
14	1	Rear Bumper Inner Bracket RH	\$	<i>n</i> 198.00 X
15	1	Rear Bumper Beam	\$	1,215.00 ?
16	1	Rear Bumper Beam Bracket LH	\$	<i>n</i> 307.50
17	1	Rear Bumper Beam Bracket RH	\$	<i>n</i> 307.50
18	1	Rear Bumper Bracket Centre	\$	<i>n</i> 461.75
19	1	Rear Bumper Tow Hook Cover	\$	<i>sn</i> 63.00
20	1	Rear Bumper Retainer Bracket LH	\$	<i>sn</i> 202.50
21	1	Rear Bumper Retainer Bracket RH	\$	<i>sn</i> 202.50
22	1	Bootlid	\$	<i>n</i> 4,140.00
23	1	Bootlid 'E220' Badge	\$	<i>nn</i> 153.00
24	1	Bootlid 'BLUETEC' Badge	\$	<i>nn</i> 153.00
25	1	Bootlid Centre Logo Badge	\$	<i>nn</i> 153.00

Trans-cab Auto Services Pte Ltd

AAD1904-081

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 900L

26	1	Bootlid Protector Garnish With Chrome	\$	Su	732.00	} X
27	1	Bootlid Weatherstrip	\$	Su	360.00	
28	1	Bootlid Lock - Top	\$	M	300.00	
29	1	Bootlid Lock - Bottom	\$	M	216.00	
30	1	Bootlid Lock Actuator	\$	Su	420.00	
31	1	Bootlid Weatherstrip	\$	Su	240.00	
32	1	Bootlid Third Brake Lamp	\$	Su	577.50	
33	1	Rear End Panel Outer	\$	M	1,971.00	
34	1	Rear End Panel Inner	\$	M	324.00	
35	1	Rear End Panel Inner Trim	\$	Su	630.00	
36	1	Rear End Panel Inner Trim Flap	\$	Su	360.00	
37	1	Rear Lamp RH	\$	Su	1,170.00	
38	1	Rear Lamp Panel Outer RH	\$	M	382.95	
39	1	Rear Lamp LH	\$	Su	1,170.00	
40	1	Rear Lamp Panel Outer LH	\$	M	382.95	
41	1	Rear Luggage Floor Panel Tray	\$	Su	762.00	
42	1	Rear Luggage Floor Compartment Tray	\$	Su	116.00	
43	1	Rear Luggage Floor Panel Trim Board	\$	Su	420.00	

	\$	24,695.81
10%	\$	2,469.58
	\$	22,226.22

Specical Nett

1	1 SET	Rear Bumper Parking Sensor	\$	Su	1,200.00	X
2	1 SET	Bootlid Inner Trim Clip	\$	na	90.00	X
3	1 SET	Rear End Panel Inner Trim Clip	\$	na	90.00	X
4	1 SET	Rear Bumper Fastener Clip	\$	na	101.54	✓
5	1 SET	Rear Fender Top Garnish Clip	\$	na	90.00	X
6	1 SET	Rear Fender Inner Trim Clip	\$	na	45.00	X
7	1 SET	License plate	\$	Su	225.00	X
8	1	Rear Windscreen Glass Sealant	\$	na	225.00	X

Trans-cab Auto Services Pte Ltd

AAD1904-081

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 900L

9	1	Rear Windscreen Glass Inner Seal	\$	<i>nn</i> 180.00 X
10	1	Tyre Mechanical Jack	\$	<i>nn</i> 605.48 X
11	1	Tyre Mechanical Jack Holder Bracket	\$	<i>nn</i> 177.98 X
12	1	Rear Bootlid 'DYNASTY' Sticker	\$	<i>nn</i> 33.75 X

TOTAL \$ 3,063.74**GRAND TOTAL \$ 25,289.97****LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<i>2501</i> 5,250.00
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	120.00 <i>101</i>
Putty And Spray Painting Of The Affected Portion.	\$	<i>2501</i> 4,500.00
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	<i>nn</i> 270.00 X
To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 X
To Transfer Of Tire, Rim And On Wheel Balancing.	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1904-081

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD 900L

To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test.	\$	na 170.00 X
Towing Fee	\$	na 250.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	na 170.00 X
To Dismantle And Refit Rear Undercarriage Parts, Final Checking And Testing.	\$	na 380.00 X
To Repair And Realign Rear Exhaust Pipe.	\$	na 170.00 X
To Reinstall Rear Bumper Parking Sensor.	\$	170.00 601
To Supply And Re-Do Rear Luggage Floor Panel Insulation Padding.	\$	na 380.00 X
To Reseal Sealant On Gap	\$	na 120.00 X

TOTAL	\$	12,460.00
(LUMP SUM)		
Over all total	\$	37,749.97

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: