

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Desmond Lee

Date: 10 Apr 2019

Preliminary Advice

Vehicle No	: SLD5378P	Accident Date	: 06/04/2019
Make	: HONDA VEZEL	Policy No.	: MPC18B00031501
Assignment Date	: 09/04/2019	Excess	: S\$750.00
Date of Inspection	: 10/04/2019	Est. Duration of Repair	: 0.00
Inspection At	: BH AUTO SERVICES PTE LTD (SIN MING) BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C, #01/111/113/115/117 SINGAPORE 575636		

Point of Impact / General Description of Damages

The vehicle caught fire. The cause of fire due to electrical nature.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	47,398.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,602.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending investigation