

ASSIGNMENT (OFFICE)

REF: es/CTI19006383/Aqd3nz

Assigned To: Adrian

ASSIGNMENT (OFFICE)

From (Person): chong Boon Sen

CTI

Date/Time: 9/4/19 @ 432pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SMG 4936H

Insured:

SKD 5128G

at Workshop no:

90 Motorsports

Tel:

6702 6996

of:

62/64 Kaki Bukit Ave 6

Policy No:

mpcgn 3004081900

Claim No:

SNM19DUI553C02

Sum Insured:

Excess:

Make of Vch:

D.O.A

7/4/2019

(Client's Record)

CA / REV / REP / REV 24 HRS

up?

Date/Time:

10:15am @ 10/4/19

Person Contacted:

Rayce

H.O.U. Endorsement:

Vehicle:

IN / OFF

Date/Time

Action/Instruction (✓) Estimate

SMG 4936H - x

SKG 5128G - x

Kmal Rig @ 788.01, 3 days (led to 6622.02, 89%)

ASS. REC. BY:

REF:

Adrian.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SMG4936H Yr Regn: 2018 / DecType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle c.c. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 23431 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP71211208Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15R: 185/60R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/04/19Survey held at 96 MotorsportDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China.

RECEIVED 18 JUL 2019

mv:

pv:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1) 18/7 11:58

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 9 April 2019 4:32 PM
To: claims@96motorsports.com
Cc: 'assignments'
Subject: RE: PRI FOR SMG 4936H; YOUR INSURED SKD 5128G / OUR REF: SNM19D01553C02

Without Prejudice

Dear Sir,

We pri.

Dear LKK,

Pls pri.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: claims@96motorsports.com [mailto:claims@96motorsports.com]
Sent: Tuesday, 9 April, 2019 4:30 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: PRI FOR SMG 4936H; YOUR INSURED SKD 5128G / OUR REF: SNM19D01553C02

Dear Sir,

Kindly arrange for Adrian Ling

Thank you

Royce

96 MOTORSports

62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : Operation@96motorsports.com

Website: www.96motorsports.com

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 9 April, 2019 3:36 PM
To: claims@96motorsports.com
Subject: RE: PRI FOR SMG 4936H; YOUR INSURED SKD 5128G / OUR REF: SNM19D01553C02

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: claims@96motorsports.com [<mailto:claims@96motorsports.com>]
Sent: Tuesday, 9 April 2019 3:23 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: PRI FOR SMG 4936H; YOUR INSURED SKD 5128G

Dear China.

Please let us have your list

Thank you
Royce



62/64 Kaki Bukit Avenue 6
Ark @ KB Singapore 417893
Tel : 6702 6996
Fax : 6384 6996
Email : Operation@96motorsports.com
Website: www.96motorsports.com

From: claims@96motorsports.com <claims@96motorsports.com>
Sent: Monday, 8 April, 2019 5:14 PM
To: claimsdept@sg.cntaiping.com
Cc: Gary 96 <gary.chang@96motorsports.com>; Andyson <andysonckl@yahoo.com>
Subject: PRI FOR SMG 4936H; YOUR INSURED SKD 5128G

WITHOUT PREJUDICE

Dear CHINA TAIPING,

**ACCIDENT INVOLVING SMG 4936H and SKD 5128G on 07-04-2019
AT / ALONG JUNC OF BUANGKOK EAST DRIVE / SENGKANG EAST DRIVE**

We act for **MS CARZ LEASING PTE LTD**, whose vehicle registration number **SMG 4936H** was damaged in the above accident.

Kindly let us have your list of surveyors within **2 working days** of your receipt of this notice should you like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Jade Lim



62/64 Kaki Bukit Avenue 6
Ark @ KB Singapore 417893
Tel : 6702 6996
Fax : 6384 6996
Email : claims@96motorsports.com
Website: www.96motorsports.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



96 MOTORSPORTS PTE LTD

64 Kaki Bukit Ave 6 Singapore (417893)

Email: estimator@96motorsports.com

Tel: 67026996/83118211

VEHICLE NUM:

SMG 4936 H

MAKE & MODEL:

H.SHUTTLE

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

Shiau Chan
TRAFA
VIVIAN

ATTN:						
NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE		
1	TAIL GATE <i>Repair</i>	1	\$ 1,193.00	+		
2	TAIL GATE EMBLEM (SHUTTLE) <i>3 per</i>	1	\$ 87.00	✓ 87		
3	TAIL GATE EMBLEM (HYBRID)	1	\$ 98.10	✓ 98.10		
4	TAIL GATE OUTER GARNISH <i>3 per</i>	1	\$ 425.00	+		
5	TAIL GATE OUTER GARNISH CLIP	1SET	\$ 30.00	+		
6	REAR BUMPER <i>Repair</i>	1	\$ 1,050.00	+		
7	REAR BUMPER SIDE RETAINER L+R <i>3 per</i>	2	\$ 160.00	+		
8	REAR BUMPER ATTACHMENT RETAINER L+R	2	\$ 140.00	+		
9	REAR BUMPER REFLECTOR BASE COVER L+R <i>seen</i>	2	\$ 372.00	+		
10	END PANEL <i>seen</i>	1	\$ 589.60	+		185.10
11	END PANEL TOP TRIM <i>3 per</i>	1	\$ 185.40	+		148.08
12	END PANEL TOP TRIM CLIP	1SET	\$ 30.00	+		
SUBTOTAL			\$ 4,360.10	\$ 185.10		-
			\$ -70	\$		-
PARTS TOTAL			\$ 4,360.10	\$ 148.08		-
SPECIAL NETT		QTY	PRICE	PRICE		
1	REAR SENSOR <i>seen</i>	1	\$ 450.00	+		
2	REVERSE CAMERA <i>Not seen</i>	1	\$ 550.00	+		
SPECIAL NETT			\$ 1,000.00	\$		-
LABOUR		QTY	PRICE	PRICE		
1	TO KNOCK. STRINHTEN AND REALIGN ACCIDENT AREA	1	\$ 1,000.00	200		
2	TO PUTTY AND RESPRAY ACCIDENT AREA	1	\$ 800.00	400		
3	TO RUST PROOF ACCIDENT AREA	1	\$ 90.00	+		
4	TO R&R REVERSE CAMERA AND CHECK FUNCTION	1	\$ 80.00	+		
5	TO R&R REAR SENSOR AND CHECK FUNCTION	1	\$ 80.00	40		
6						
7				640.00		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006383/AQD3N2

Date: 18/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3004081900	
Claimant Vehicle No :	SMG4936H	Insured Vehicle No :	SKD5128G	
Date of Loss:	07/04/2019	Nature of Claim:	TP	Claim No: SNM19D201553C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG4936H	Engine No:	LEB6553624
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71211208
Reg. Date:	21/12/2018 (Man. Year: 2018)	Odometer:	23431 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,360.10	148.08	5,212.02	97.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	640.00	1,410.00	68.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,410.10	788.08	6,622.02	89.36
+ GST 7.00/7.00% (S\$)	518.71	55.17	463.54	89.36
Nett Amount (S\$)	7,928.81	843.25	7,085.56	89.36

INSPECTION

Date of Assignment:	15/04/2019	
Date Inspected:	10/04/2019	Inspected At:
		96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB Singapore 417893
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jul 2019)
Parts:	N/A HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG4936H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Repair	1,193.00 F	*- FL
2	1		*TAIL GATE EMBLEM (SHUTTLE)	Necessary	87.00 F	*87.00 FL
3	1		*TAIL GATE EMBLEM (HYBRID)	Necessary	98.10 F	*98.10 FL
4	1		*TAIL GATE OUTER GARNISH	Not Necessary	425.00 F	*- FL
5	1		*SET TAIL GATE OUTER GARNISH CLIP	Not Necessary	30.00 F	*- FL
6	1		*REAR BUMPER	Repair	1,050.00 F	*- FL
7	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	160.00 F	*- FL
8	2		*REAR BUMPER ATTACHMENT RETAINER L+R	Not Necessary	140.00 F	*- FL
9	2		*REAR BUMPER REFLECTOR BASE COVER L+R	Not Necessary	372.00 F	*- FL
10	1		*END PANEL	Not Necessary	589.60 F	*- FL
11	1		*END PANEL TOP TRIM	Not Necessary	185.40 F	*- FL
12	1		*SET END PANEL TOP TRIM CLIP	Not Necessary	30.00 F	*- FL
13	1		*REAR SENSOR	Not Necessary	450.00 FS	*- FS
14	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,360.10	185.10
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	37.02
Total Parts (\$\$)	5,360.10	148.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,STRAIGHTEN AND REALIGN ACCIDENT AREA	New	1,000.00	200.00
2	TO PUTTY AND RESPRAY ACCIDENT AREA	New	800.00	400.00
3	TO RUST PROOF ACCIDENT AREA	New	90.00	0.00
4	TO R&R REVERSE CAMERA AND CHECK FUNCTION	New	80.00	0.00
5	TO R&R REAR SENSOR AND CHECK FUNCTION	New	80.00	40.00
Gross Labour Cost (S\$)			2,050.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >