

REF: cs/ICS19006389/T19d3 | n2
ASSIGNMENT (Office)
From (Person): Taufikh
Crystabelle Tan
of ICS
Date/Time: 10/4/19 @ 10:17am
Estimated Cost: RM166

OD / TP / WS / TP RES / OD RES / EYA / INV / MV / CS

To Inspect Vehicle No: SKA 256T Insured: GBC 33612
at Workshop no: performance Motor Tel: GS190174
of 303 Alexandra Road

Policy No: Claim No: DMCV19000194 / 02 / CT

Sum Insured: Excess:

Make of Veh: D.O.A. 8/4/2019
(Client's Record)

CA / REV / REP / REV 24 HRS H.O.D. Endorsement

Date/Time: 10:56am @ 10/4/19 Person Contacted: caroline Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKA 256T - CS/ASM17019055/bxx D.O.A. 27/4/2019
	GBC 33612 - x
	12.4.2019 - vni - caroline
16/5/19 @ 1:20pm	revised to Crystabelle Tan via mesman.

Surveyor

Tamplin

REF: ICS

ASSIGNMENT

From:

Date: 15/5/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKA 256T

at Workshop m/s

performance

of

303 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Hen

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Imp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKA 256T

Yr Regn. 2018, Dec.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X2

C.C. 1499

Colour:

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

7781

T/Radio: Insured / Std / NI / NA

Eng/No:

WHA9H12000. EM91670

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R19

R:

225/45R19

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15/5/19 02pm

Survey held at

PML

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/7/19

Email Caroline \$7568.35, 5 days. (Red \$2348.65, 24%).

RECEIVED 12 JUL 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 12/7/19

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + R.S. \$

Photos

Others

TOTAL

Report Format:

over-7P

Lump Sum / I.B.I. (\$

7568.35

350

11

361

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 16 May 2019

Preliminary Advice

Insured Vehicle No	: GBC3361Z	Accident Date	: 08/04/2019
TP Vehicle No	: SKA256T	Assignment Date	: 10/04/2019
Make	: BMW X2 SDRIVE18I MSPT LED FOG LIGHTS	Est. Duration of Repair	: 5.00
Date of Inspection	: 15/05/2019		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,916.00
Revised Amount	:S\$	7,102.35
Check Items (Estimated)	:S\$	1,569.20
Total	:S\$	8,671.55
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Wednesday, 10 April 2019 10:17 AM
To: pml-pbsp@simedarby.com.sg; assignments
Subject: FW: REQUEST FOR DIRECT SETTLEMENT - SKA256T & GBC3361Z ON 08/04/2019 - Ref : DMCV1900019H/02/CT
Attachments: SKM_558e19041008230.pdf; SKA256T.PDF

WITHOUT PREJUDICE

Our Ref : DMCV1900019H/02/CT

Dear Caroline

We are unable to confirm liability as our insured has yet to report the accident to us.

Aside to LKK

Please arrange survey.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Wednesday, 10 April, 2019 8:27 AM
To: Janice Goh Siew Geok (ECICS, Claims); Crystabelle Tan Gek Peng (ECICS, Claims)
Subject: REQUEST FOR DIRECT SETTLEMENT - SKA256T & GBC3361Z ON 08/04/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2019 15:31
Date Of Accident	08/04/2019 22:00
Exact Location Of Accident	ANCHORVALE STREET (OUTSIDE SENGKANG HOSPITAL)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA256T
Insured/Policyholder	
Name Of Registered Owner	JACQUELINE TAN JIAJIA @JACQUI
NRIC No	S7724385B
Email Address	JACQUITAN@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91691911
Alternative Phone No	OTHERS-91691911

Vehicle Particulars

Manufacturer	BMW
Model	X2
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD19V00245/VPC/R00
Cover Note Number	

Driver

Name of Driver	JACQUELINE TAN JIAJIA @JACQUI
NRIC No	S7724385B
Date Of Birth	11/09/1977
Occupation	INDOOR
Date Of Driving Pass	22/08/2005
Driving Experience	13 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91691911
Fax Number	
Contact Number	OTHERS-91691911
EMail Address	JACQUITAN@YAHOO.COM

Address	29 TANGLIN HALT ROAD #09-130
Postcode	141029
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG-BURN CD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC3361Z
Vehicle Make/Model/Colour	NISSAN WHITE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HO SOON HOCK
NRIC/Passport Number	S1184692J
Contact Number	84336004
Address	112 PUNGGOL WALK #07-25 TWIN WATERFALLS
Postcode	828766
Insurance Company Name	ECICS LIMITED
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	1

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X  Policyholder's Signature


Date & Time: 09 APR 19

2-10 PM

X  Driver's Signature

(If driver is not the policyholder)

Date & Time: 09 APR 19
2-10 PM

 Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

car stopped at
 my car was at the traffic light along Anchorvale Street
 outside Sengkang Hospital. car was stationary at the red
 light. Van GBC 3361 Z hit my car when the traffic light
 was red. My rear bumper dented and minor cracked.
 No passenger in both our cars and there were no
 injury. Accident time was 10 pm and it was not raining.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 09 APR 19
 2.10 PM

Driver's Signature

(if driver is not the policyholder)

Date & Time: 09 APR 19
 2.10 PM

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

10 APR 2019

E S T I M A T E

Estimate No. : b1 50799
Date Estimated : 09/04/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Jacqueline Tan JiaJia (Chen JiaJia)
Blk 29 Tanglin Halt Road
#09-130

Singapore 141029

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA256T	EM91670	27/12/2018	X2 sDrive18i	0

DESCRIPTION

To replace rear bumper & attachments, rear boot lid bottom trim panel including to knock out dented area caused by the accident

1700, 2,550.00

To respray rear bumper and boot lid trim panel

21331730, 1,923.00

To check electrical wiring systems and lightings at the rear section for proper function.

150, 177.00

To supply rear emboss number plate.

bt, 83.00

Sundries.

nu, 80.00

Total Labour 1: 4,813.00

DESCRIPTION

REAR BUMPER LH SIDE INNER GUIDE
REAR BUMPER RH SIDE INNER GUIDE
REAR BUMPER CARRIER
MOUNTING SMART OPENER (M)
REAR BUMPER TOWING EYE COVER PRIMED
REAR BUMPER PANEL PRIMED (M)
REAR BUMPER TRIM PANEL BOTTOM PAINT
TRIM TAILGATE BOTTOM PRIMED
LETTERING X2
PLAQUE 74MM
GROMMET
REAR BUMPER HEAT INSULATION
SEAL TRIM TAILGATE TOP
GUTTER STRIP FOR TRIM OF TAILGATE
EXPANDING RIVET
NUMBER PLATE LIGHT LED
Ultrasonic s
DECOUPING RING PDC TORQUE CONVERTER

QTY PRIC VALUE

1	61.50	X 61.50
1	61.50	nn X 61.50
1	508.55	? 508.55 X
1	45.30	? 45.30
1	51.45	ki 51.45
1	1,167.60	de 1,167.60
1	1,602.60	de 1,602.60
1	481.70	474.80 de 481.70
1	64.10	ne 64.10
1	71.25	ne 71.25
2	0.75	na 1.50
1	69.55	? 69.55 X
1	33.70	? 33.70 X
2	22.25	? 44.50 X
30	1.35	na 40.50
2	25.00	X 50.00
2	368.80	nn 737.60
2	5.05	? 10.10

Total Parts : 5,103.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50799
Date Estimated : 09/04/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA256T	EM91670	27/12/2018	X2 sDrive18i	0

[Signature]
16/5/19

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 15/5/19 2:20 pm Excess \$S _____

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 97497409 Authorised Yes / No

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tan.jiah@lkkauto.com

No. of Working Days Recommend 4 days 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	4,813.00
Parts	:	5,103.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	694.12
Grand Total	:	10,610.12

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

9416

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 50799**
Date Estimated : **09/04/2019**
Prepared By : **Han Kwan Yong**

Page No.:

REPAIR FOR -
Jacqueline Tan JiaJia (Chen Jiajia
Blk 29 Tanglin Halt Road
#09-130

- ACCOUNT - 144674
ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

Singapore 141029

REGN.NO.	CHASSE NO.	REGN.DATE	MODEL	MILEAGE
SKA256T	EM91670	27/12/2018	X2 sDrive18i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, tailgate bottom trim include making good the boot lid and knocking out dents caused by the accident	1700.00		1,700.00	
* To respray rear bumper, rear bumper lower apron and boot lid	2133.00		2,133.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To supply rear emboss number plate	83.00		83.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (M PDC/ICA	1,167.60	1.00		1,167.60
REAR BUMPER TRIM PANEL BOTTOM PAINT	1,602.60	1.00		1,602.60
TRIM TAILGATE BOTTOM PRIMED	474.80	1.00		474.80
LETTERING X2	64.10	1.00		64.10
PLAQUE 74MM	71.25	1.00		71.25
GROMMET	0.75	2.00		1.50
EXPANDING RIVET	1.35	30.00		40.50

SUPPLEMENTARY ITEMS

Total Labour :	4,146.00
Total Parts :	3,422.35
Total Labour & Parts :	7,568.35 ✓
Deduction for Excess :	
Total Repair Costs less Excess:	7,568.35
GST @7%:	529.78
Grand Total :	8,098.13

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19006389/T1QD3N2

Date: 16/07/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SKA256T	Insured Vehicle No :	GBC3361Z
Date of Loss:	08/04/2019	Nature of Claim:	TP
		Claim No:	DMCV1900019H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA256T	Engine No:	30785369B38A15A
Make & Model:	BMW X2, 1.5 SDRIVE18I (A)	Chassis No:	WBAYH12000EM91670
Reg. Date:	27/12/2018 (Man. Year: 2018)	Odometer:	7781 km
Colour:	Yellow		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,266.00	3,585.35	1,680.65	31.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,860.00	3,983.00	877.00	18.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,126.00	7,568.35	2,557.65	25.26
+ GST 7.00/7.00% (S\$)	708.82	529.78	179.04	25.26
Nett Amount (S\$)	10,834.82	8,098.13	2,736.69	25.26

INSPECTION

Date of Assignment:	10/04/2019	
Date Inspected:	15/05/2019 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2019)
Parts:	M1-SUV	BMW X2 1.5 SDRIVE18I (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA256T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER LH SIDE INNER GUIDE	Not Necessary	61.50 FS	*- FS
2	1	*REAR BUMPER RH SIDE INNER GUIDE	Not Necessary	61.50 FS	*- FS
3	1	*REAR BUMPER CARRIER	Not Necessary	508.55 FS	*- FS
4	1	*MOUNTING SMART OPENER (M)	Not Necessary	45.30 FS	*- FS
5	1	*REAR BUMPER TOWING EYE COVER PRIMED	Repair	51.45 FS	*- FS
6	1	*REAR BUMPER PANEL PRIMED M	Deformed	1,167.60 FS	*1,167.60 FS
7	1	*REAR BUMPER TRIM PANEL BOTTOM PAINT	Deformed	1,602.60 FS	*1,602.60 FS
8	1	*TRIM TAILGATE BOTTOM PRIMED	Deformed	481.70 FS	*474.80 FS
9	1	*LETTERING X2	Necessary	64.10 FS	*64.10 FS
10	1	*PLAQUE 74MM	Necessary	71.25 FS	*71.25 FS
11	2	*GROMMET	Necessary	1.50 FS	*1.50 FS
12	1	*REAR BUMPER HEAT INSULATION	Not Necessary	69.55 FS	*- FS
13	1	*SEAL TRIM TAILGATE TOP	Not Necessary	33.70 FS	*- FS
14	2	*GUTTER STRIP FOR TRIM OF TAILGATE	Not Necessary	44.50 FS	*- FS
15	1	*EXPANDING RIVET (30 Pcs)	Necessary	40.50 FS	*40.50 FS
16	2	*NUMBER PLATE LIGHT LED	Not Necessary	50.00 FS	*- FS
17	2	*ULTRASONIC S	Not Necessary	737.60 FS	*- FS
18	2	*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	10.10 FS	*- FS
19	1	*SUNDRIES	Necessary	80.00 FS	*80.00 FS
20	1	*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,266.00	3,585.35
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER & ATTACHMENTS, REAR BOOT LID BOTTOM TRIM PANEL INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND BOOT LID TRIM PANEL	New	2,133.00	2,133.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			4,860.00	3,983.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >