

Inspector: Kalvin

REF: NS/INC 19006399/ K19d3n2

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SJR 7841E

Policy No. 5108316860 28-3-19

Claims No. NJ/1039489-102 27-3-20

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Vch: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN/OUT

Veh No: SHA 63422 Yr Regn: 5 Jan, 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / T/O / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Hyundai 240 cc 1685

Colour: Blue A/C: Insured / Std / Nil / NA

Sp. Reading: 29 6316 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: KM HLP414 MH 4097900

Gen. Cond: Good / F/O / Poor / Burnt

Steering: Inoperative / Jammed / Leaked / Burnt or

Brake: Inoperative / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/T or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 8/4/19 D.O.I. 9/4/19

Survey held at CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHA 63422 - CC4 / AIG / 7021217 / MIWA392 D.O.A - 04/11/2017 <u>INC</u>
	SJR 7841E - NS/INC13006399 / Hiyin D.O.A - 06/04/2013 <u>40</u>
15/4/19	Checked L/S \$2650 / 3 Pgs. (Red 891272, 2610)

RECEIVED 16 APR 2019

Date/Time, File Pass to?  : Prell. Report

15/4/19  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
S + RS:	\$1
Photo:	160
_____	
_____	

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

L/S = 2650

[My Desktop](#)  
[Notice of Loss](#)

### Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="08/04/2019 14:49"/>
Vehicle No.(For Motor)	<input type="text" value="SJR7841E"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5108316860		FOO YIRUI DAMIAN	S9148712H	GPC	drivo CLASSIC	SJR7841E	SJR7841E	28/03/2019	27/03/2020

**TP Claims against NTUC Income: Follow-Through Survey**

Date: 15/04/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/1039503-002	COMFORT TRANSPORTATION PTE LTD	SHA 2607L	SFH 6018Y	8/4/2019
2	MT/1037163-002	COMFORT TRANSPORTATION PTE LTD	SHC 8114S	SKS 7095A	23/3/2019
3	MT/1039404-002	COMFORT TRANSPORTATION PTE LTD	SHB 4150T	FBC 1381D	6/4/2019
4	MT/1039734-002	CITYCAB PTE LTD	SHC 7954R	SKL 4032M	11/4/2019
5	MT/1040229-001	COMFORT TRANSPORTATION PTE LTD	SHC 1972C	FBD 5744J	8/4/2019
6	MT/1040234-001	COMFORT TRANSPORTATION PTE LTD	SHD 6667X	SHD 2183B	8/4/2019
7	MT/1039489-002	COMFORT TRANSPORTATION PTE LTD	SHA 6342Z	SJR 7841E	8/4/2019

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/04/2019 08:05
Date Of Accident	08/04/2019 15:45
Exact Location Of Accident	PUNGGOL PLAZA BASEMENT CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA6342Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	SOH KEE LIANG
NRIC No	S0041210D
Date Of Birth	20/04/1950
Occupation	OUTDOOR
Date Of Driving Pass	18/01/1969
Driving Experience	50 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92990908
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	204D #16-358 PUNGGOL FIELD
Postcode	824204
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

SEE ATTACH.

### Attachment(s)



Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR7841E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT RHT
No. Of Passenger (Including Driver)	







**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 6342Z

DATE 9/4/2019 9:53

MAKE :

MODEL : HYUNDAI i40


*LKK/Kalwin*

*U/Sunn*

*L. Ke*

*NTUC*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>— behind</i>			\$ <del>544.50</del> <i>1052.20</i>
	Front Bumper Bracket Top (LH) <i>X sun</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>X sun</i>			\$ 24.60
	Headlamp (LH) <i>— behind</i>			\$ 1,388.00
	Front Fender (LHH) <i>— behind</i>			\$ 566.30
	Front Fender Shield (LH) <i>X sun</i>			\$ 175.90
	Front Fender Retainer <i>X sun</i>			\$ 24.60
	Frnt Wheel Hub Cap, LH <i>— behind</i>			\$ 107.10
	<b>SUB TOTAL</b>			\$ 2,853.40
	<b>LESS 20%</b>			\$ 570.68
	<b>DISCOUNTED TOTAL</b>			\$ 2,282.72
	Front Fender Advertisement Logo (LH) <i>— sun</i>			\$ 100.00 <i>Nett</i>
				\$ 100.00
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>400.00</del> <i>300</i>
	Spray Painting Charge			\$ <del>600.00</del> <i>400</i>
	Wiring			\$ <del>50.00</del> <i>20</i>
	Tuff Kote			\$ <del>50.00</del> <i>20</i>
	Frnt Wheel Alignment			\$ <del>80.00</del> <i>X 2</i>
	<b>TOTAL LABOUR</b>			\$ 1,180.00
	<b>ESTIMATE TOTAL</b>			\$ 3,562.72
				<i>3968.88</i>



*Kalwin (LKK)*  
*M 9/4/19 1115hrs*  
*307,*  
*45*  
*After Repair photo*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO

Date/Time: 09.04.2019 09:22

Page : 1

Team: ARC Repair TP(CLS0)1

## JOB CARD

Sales Order:

JC NO.: 305285575


CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (C) (P) COUNT CARD NO.	REGN NO.	SHA6342Z	MILEAGE
	MAKE	HYUNDAI	FUEL E.....1/2.....F
	MODEL	I-40	DATE/TIME IN 08.04.2019 16:15
	YR OF MANU	05.01.2017	TARGET DATE
	CHASSIS CODE	KMHLB41UMHU097900	COMPLETION DATE/TIME

*NTUC*

### JOB DESCRIPTION

Accident Date: 08.04.2019  
 NATURE: 3P 08.04.2019/C

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Vehicle No.: **SHA6342Z**

LKE

*Kahm*

Exit Pass

Vehicle No.: **SHA6342Z**

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305285575  
Date : 11.04.19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK Fax : \_\_\_\_\_  
Attn : Mr KALVIN ANG  
Vehicle Reg No. SHA6342Z CTPL 08.04.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SJR7841E
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c.) Lumpsum Repair (if applicable)
  - Total for Lumpsum repair cost after Less: 20% \$2,650.00
  - Final Lumpsum Repair cost** \$2,650.00

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM KWOK ENG  
Tel : 62148316  
Fax : 65468156

Signature :   
Name : Kalvin  
Date : 15/4/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19006399/K1qd3n2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 18-04-2019
Code: INC4	



### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 7841E	Veh. Inspected	SHA 6342Z
Policy No.	5108316860	Coverage (\$)	0.00
Claim No.	MT/1039489-002	Excess (\$)	0.00
Assign From		Assign Date	09/04/2019

### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHLB41UMHU097900	Colour	BLUE
Odometer	296316	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	6 mm
L/H Front Tyre	205/60 R16	HANKOOK	6 mm
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	08/04/2019	Inspection Date	09/04/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6342Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER COVER	DEFORMED	1,052.20	1,052.20
1	FRONT BUMPER BRACKET TOP (LH)	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET (LH)	SERVICEABLE	24.60	-
1	HEADLAMP (LH)	GRAZED	1,388.00	1,388.00
1	FRONT FENDER (LH)	BUCKLED	566.30	566.30
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	175.90	-
1	FRONT FENDER RETAINER	SERVICEABLE	24.60	-
1	FRT WHEEL HUB CAP, LH	GRAZED	107.10	107.10
	LESS 20% DISCOUNT		-672.22	-622.72
			<b>2,688.88</b>	<b>2,490.88</b>
<b>SPECIAL NETT ITEMS</b>				
1	FRONT FENDER ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
			100.00	100.00
<b>LABOUR</b>				
	PANEL BEATING.		400.00	300.00
	SPRAY PAINTING CHARGE.		600.00	400.00
	WIRING.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			<b>1,180.00</b>	<b>740.00</b>
<b>GRAND TOTAL</b>			<b>3,968.88</b>	<b>3,330.88</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>2,650.00</b>

Report Ref No. NS/INC19006399/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.