

Sheet1

# HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714  
Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526  
Email : [chris\\_chanbebe@hotmail.com](mailto:chris_chanbebe@hotmail.com)

TP ALG.  
Khanchana

08<sup>th</sup> April 2019

LU LIN  
BLOCK 3020A UBI ROAD 1  
# 01-33  
Singapore 408714

Accident date: 03<sup>rd</sup> APRIL 2019

Estimated repair cost for vehicle no: SMG7755T HONDA VEZEL

| S/n | Qty | Items                                         | U/price  | Amount                      |
|-----|-----|-----------------------------------------------|----------|-----------------------------|
|     |     |                                               |          | <del>\$1,195.00</del> 1100. |
| 1   | 1   | Rear Boot Lid Distorted.                      |          | \$360.00 X                  |
| 2   | 2   | Rear Boot Lid damper Ne new                   | \$180.00 | \$336.00 X                  |
| 3   | 2   | rear Boot Lid hinges Not new                  | \$168.00 | \$55.00 X                   |
| 4   | 1   | Rear boot lid emble logo Ne new               |          | \$38.10 ✓                   |
| 5   | 1   | Rear boot lid VEZEL logo Ne                   |          | \$38.10 ✓                   |
| 6   | 1   | rear boot lid Emble logo Ne                   |          | \$804.40 ✓                  |
| 7   | 2   | Rear Boot Lid side reflector Cracked          | \$402.20 | \$237.00 ✓                  |
| 8   | 1   | Rear boot lid inner rubber Lit                |          | \$284.20 ✓                  |
| 9   | 1   | Rear Boot Lid Inner Lock Damaged.             |          | \$50.00 X                   |
| 10  | 1   | Rear Boot Lid Number Plate Not new            |          | \$110.00 X                  |
| 11  | 1   | rear Boot Lid number Plate top garnish Ne new |          | \$122.20 X                  |
| 12  | 2   | Rear Boot Lid Number Plate Lamp Ne            | \$61.10  | \$320.80 X                  |
| 13  | 1   | Rear Boot Lid center moulding Ne              |          | \$50.00 30                  |
| 14  | 10  | Rear Boot Lid Inner Trim board clips Ne       | \$5.00   | \$354.00 ✓                  |
| 15  | 1   | Rear Boot Lid Inner Trim board Deland         |          | \$760.00 X                  |
| 16  | 2   | Rear tail lamp Ne                             | \$380.00 | \$420.00 X                  |
| 17  | 1   | Rear end panel Rep's                          |          | \$168.00 ✓                  |
| 18  | 1   | Rear End Panel Top Garnish Deland             |          | \$745.30 ✓                  |
| 19  | 1   | Rear Bumper Deland                            |          | \$226.20 X                  |
| 20  | 1   | Rear bumper top garnish Ne new                |          | \$96.00 ✓                   |
| 21  | 2   | Rear Bumper Side Bracket Ne                   | \$48.00  | \$400.00 200(SN)            |
| 22  | 1   | Rear Bumper reverse sensor Damaged            |          | \$258.00 125                |
| 23  | 2   | Rear side Bumper Deland RH                    | \$125.00 | \$40.00 30                  |
| 24  | 8   | Rear bumper clips Ne                          | \$5.00   | \$174.00 88                 |
| 25  | 2   | Rear Bumper Side Reflector RH Cracked         | \$88.00  | \$158.00 ✓                  |
| 26  | 1   | Rear windscreen moulding Ne                   |          | \$298.50 X                  |
| 27  | 1   | rear spare tyre top board 3 new               |          | \$428.00 X                  |
| 28  | 1   | Rear spare tire panel lower cover 1 new       |          |                             |

|    |   |                                  |              |            |
|----|---|----------------------------------|--------------|------------|
| 29 | 2 | Rear spare tire panel insulation | <i>3 new</i> | \$150.00 ✓ |
| 30 | 1 | Rear spare tire panel sealant    |              | \$180.00 + |

4296.10 SN.200  
3436.88

Subtotal :- \$8,851.80

**Labour charges**

To Remove & refix cushion

~~\$150.00~~ 60

To Remove & refix rear windscreen

~~\$120.00~~ ✓

Gum

~~\$50.00~~ ✓

To Remove & refix reverse Sensor

~~\$120.00~~ 60

Tuff kote

1580

~~\$120.00~~ 60

To Check Wiring System

~~\$60.00~~ 30

Panel beating

~~\$800.00~~ 600

Spray painting

~~\$800.00~~ 600.

Subtotal :- \$2,220.00

Total:- \$11,071.80

total: 5216.88

H/S: 4.11C.

05Ryp

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: