

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0466/2019/DY
Date : 11-Apr-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured veh no. : **SKS 9247 R**

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Tan Peng Leng
Address : Blk 676A Choa Chu Kang Crescent
#09-467
Singapore 681676
Telephone : (HP) + 65 97997689
Type of Claim : Third Party Claims
Policy No. : 1700042804-01
Vehicle No : **SLR 6502 S**
Model Code : A3 SEDAN 1.0 TFSI 8V
Model / Year : Aug-17
Engine No : CHZ 512211
Chassis No : WAUZZZ8V0J1006763
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Apr-19
Place of Accident : Bukit Batok East Ave 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 6502 S

S/n	Nature of Jobs	Estimated Charges
1	To remove and reintsall rear parking aid. Check function and renew according to damage.	s/n \$ 280.00
2	To dismantle and renew rear bumper.Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00
3	To respray rear bumper.	\$ 800.00
4	To carry out diagnostic check.	s/n \$ 192.00
TOTAL LABOUR CHARGES		: \$ 2,172.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 6502 S

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>
1	REAR BUMPER COVER	\$	1,567.00
2	STICKY PAD	4 \$	21.00
3	FIXING PARTS FOR REAR BUMPER	\$	175.00
4	GUIDE SECTION FOR REAR BUMPER - LH	\$	13.00
5	GUIDE SECTION FOR REAR BUMPER - RH	\$	13.00
6	LOCKING MECHNISM	2 \$	49.00
7	SPOILER	\$	193.00
8	REAR LIGHT REFLECTOR - LH	\$	24.00
9	SIDE REINFORCEMENT	\$	481.00
10	BRACKET - LH	\$	22.00
11	BRACKET - RH	\$	23.00
12	PARKING SENSOR	2 \$	415.00
13	PARKING SENSOR SEAL RING	4 \$	14.00
14	SUNDRIES	\$	400.00
TOTAL SPARE PARTS CHARGES		:	\$ 3,410.00
TOTAL LABOUR CHARGES			\$ 2,172.00
GRAND TOTAL			\$ 5,582.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant