

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Mr
KELVINDER
SINGH
457 YISHUN STREET 41
Singapore 760457

Page 1/1
Document no.
Document date 11-04-2019
Customer no. 5211038487
Customer GST-ID
Dealer 39999
Job order number 2019000137/ 1
Job order date 06-04-2019
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SLR7752E	5G1	28-08-2017	WWWZZZAUZHW078992	Golf 7	15,762

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5G2857508BF9B9	Housing X	1	pcs.	296.00	#1	296.00	316.72
5G0857538E GRU	Mirror Cap Primed X	1	pcs.	150.42	#1	150.42	160.95
	LABOUR X	3	pcs.	840.00	#1	2,520.00	2,696.40
	FRONT BUMPER, RHF WING MIRROR						
	Spray Painting X	3	pcs.	800.00	#1	2,400.00	2,568.00
	FRONT BUMPER, RHF WING MIRROR						
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Harness Repair and Short Circuit Check						

Quotation valid till 13-04-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1		6,126.42	7%	428.85	6,126.42	6,555.27
Total		6,126.42		428.85	6,126.42	6,555.27

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Repair
Hp 90010068
3 days
12/04/19 @ 1020
Repair after repair