

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 09.04.2019

Time: 16:14:11

Page: 1

AXA-45

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305285932  
REGN NO : SHA3550J  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 10.03.2016  
DATE/TIME IN : 09.04.2019 11:50  
ACCIDENT DATE : 09.04.2019

1630

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|      |                   |                           |      |        |       |        |   |     |
|------|-------------------|---------------------------|------|--------|-------|--------|---|-----|
| 0001 | 04-01-0103-0579-G | REAR BUMPER               | 1    | 553.00 | 20.00 | 442.40 | — | Ref |
| 0002 | 04-01-0103-0738-G | REAR BUMPER UNDER COVER   | 1    | 228.00 | 20.00 | 182.40 | X | sm  |
| 0003 | 04-01-0103-0783-G | REAR BUMPER SIDE BRKT RH  | 1    | 35.60  | 20.00 | 28.48  | ✓ | cm  |
| 0004 | 04-01-0103-0852-G | REAR BUMPER REFLECTOR RH  | 1    | 30.60  | 20.00 | 24.48  | X | sm  |
| 0005 | 04-01-0101-0111-G | REAR BUMPER CLIPS         | 10 L | 22.00  | 20.00 | 17.60  | — | sm  |
| 0006 | 09-01-9999-0068-A | REVERSE SENSOR            | 1    | 135.70 |       | 135.70 | X | sm  |
| 0007 | 04-01-0103-1150-A | REAR BUMPER MAT           | 1    | 50.00  |       | 50.00  | — | sm  |
| 0008 | 04-01-0103-0739-G | REAR BUMPER SPONGE        | 1    | 118.40 | 20.00 | 94.72  | X | sm  |
| 0009 | 04-01-0103-0740-G | REAR BUMPER REINFORCEMENT | 1    | 428.40 | 20.00 | 342.72 | X | sm  |
| 0010 | 04-01-0103-0743-G | REAR BUMPER REIN-BRKT RH  | 1    | 80.30  | 20.00 | 64.24  | X | sm  |

SUB-TOTAL : 1,382.74

## JOB NATURE

0000 PB PANEL BEATING

~~280.00~~ 200

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 09.04.2019

Time: 16:14:11

Page: 2

AXA-45

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305285932  
REGN NO : SHA3550J  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 10.03.2016  
DATE/TIME IN : 09.04.2019 11:50  
ACCIDENT DATE : 09.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0001 SP SPRAYPAINT CHARGE

250.00 200

0002 L R/I REVERSE SENSOR

120.00 30

SUB-TOTAL : 650.00

TOTAL : 2,032.74

LIMFS

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Ka hua (UCC)

✓

16/4/19 1105 hr

2 days

45

After Repair photo

1. To notify the insurance company of the accident.

- To notify the insurance company of the accident.
- To display, and maintain, the survey report.
- Parts prices are subject to final approval.
- Third party survey is subject to "prejudice" basis.
- No illegal modification is allowed.
- Supplementary items will be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date: