



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060
VECHICLE NUM: SLL 6724 G
MAKE & MODEL: MERCEDES A250
MILEAGE:
TYRE:
CHASSIS NUM:

not Authorized
Nob
2/5 2200
3 day
11/4/19

ATTN:			QTY	PRICE	
NO.	DESCRIPTION - PARTS				
	REAR BOOTLID	11		\$ 1,680.00	X
	REAR BOOTLID LOCK	11		\$ 348.00	X
	REAR BOOTLID WEATHERSTRIP	11		\$ 270.00	X
	REAR BOOTLID LOGO	11		\$ 50.00	X
	TAILLAMP L+R	11		\$ 1,226.00	X
	TAILLAMP LOWER BRACKET L+R	11		\$ 140.00	X
	TAILLAMP CLIPS L+R	11		\$ 20.00	X
	REAR BUMPER 1532.12	DD/22		\$ 1,560.00	✓
	REAR BUMPER SIDE RETAINER L+R	11		\$ 70.00	X
	REAR BUMPER BRACKET L+R	11		\$ 100.00	X
	REAR BUMPER TOW COVER	11		\$ 48.00	X
	REAR BUMPER LOWER 461.00	22		\$ 780.00	✓
	REAR BUMPER LOWER SEAL	11		\$ 180.00	X
	REAR BUMPER REVERSE SENSOR	11		\$ 1,040.00	X
	REAR BUMPER REVERSE SENSOR HOLDER	11		\$ 48.00	X
	REAR BUMPER REVERSE SENSOR WIREHARNES	11		\$ 1,480.00	X
	REAR BUMPER CARRIER	11		\$ 280.00	X
	REAR BUMPER REINFORCEMENT	11		\$ 418.00	X
	REAR BUMPER SENSOR BUZZER	11		\$ 298.00	X
	REAR END PANEL	11		\$ 790.00	X
	REAR END PANEL TOP GARNISH	11		\$ 70.00	X
	SPARE WHEEL PANEL	11		\$ 415.00	X
	EXHAUST PIPE MOUNTING	11		\$ 80.00	X
	EXHAUST PIPE GASKET	11		\$ 75.00	X
	EXHAUST PIPE HEAT SHEID	11		\$ 190.00	X
			SUBTOTAL	\$ 11,656.00	
			LESS 10%	\$ 1,165.60	
			PARTS TOTAL	\$ 10,490.40	
	SPECIAL NETT		QTY	PRICE	
	REAR BUMPER CLIPS	11		\$ 100.00	50
	EXHAUST SILENCER	11		\$ 5,000.00	X
	REAR BUMPER SIDE PROTECTOR SET	11		\$ 1,600.00	X
	REAR END PANEL SEALANT	11		\$ 100.00	X
	SPARE WHEEL PANEL SEALANT	11		\$ 100.00	X
	SPARE WHEEL INSULATOR	11		\$ 300.00	X
			SPECIAL NETT TOTAL	\$ 7,200.00	
	LABOUR		QTY	PRICE	

P-1993.12
102
1793.80

TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	400	\$ 1,600.00
TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	400	\$ 1,400.00
TO RUST PROOF ACCIDENT AFFECTED AREA	11X	\$ 160.00
TO RNR REAR BOOT MECHANISM	11X	\$ 250.00
TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	60	\$ 400.00
TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	\$ 120.00
TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	11X	\$ 200.00
TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	11X	\$ 120.00
TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11X	\$ 400.00
TO DO CODING FOR TAILLAMP	11X	\$ 600.00
	LABOUR TOTAL	\$ 5,250.00
	GRAND TOTAL COST	\$ 22,940.40
	TOTAL \$2753.80	
	20.	
	2203.	

PAGE 2 OF 2

LUK Auto Consultants hence notify the Repairer of the following:

- To resurvey paint after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Non-legal mobile work(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to prior approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: