



FALCON-AIR

WONG CHIN LUNG
6 TAO CHING ROAD #13-12
SINGAPORE 618723

Attention : Motor Claim Department
Contact : 91290861

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003426

Date : 06/04/2019
Vehicle Num.: SJA7298M
Make/Model : TOYOTA SIENTA
Chassis/Eng# :
Accident Date : 30/03/2019
Claim No. :
Reference : TP NTUC VS III
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|---|--|--|---------------------|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | RH FRONT FENDER | | 725.00 <i>bt</i> |
| 3. | 1 | RH SIDE MIRROR BASE - <i>photo.</i> | | 1,145.00 <i>Cur</i> |
| | | RH SIDE MIRROR BACK COVER - <i>photo</i> | | 95.19 <i>dis</i> |

List Total S\$:
25.00% Discount S\$:

1,965.19
491.30

1,473.89

LABOUR :
SPRAY PAINTING FRONT & REAR ACCIDENT DAMAGED AREAS
TO REPAIR RH FRONT DOOR, REPLACE RH SIDE MIRROR
INCLUDES KNOCKING & REPLACEMENT OF PARTS

600.00 *500*
450.00 *300*

Labour Total S\$:

1,050.00

E. & O.E.

Total S\$: 2,523.89

for FALCON AIR AUTO SERVICES PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Taukin 97495749
up
11/4/1901750
04 days
lumpsum
Resurvey after repair
sure lkk auto con.