



Co./GST Regn. No. 200921075G

新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

10 APR 2019

THIRD PARTY CLAIM

Third Party Vehicle No : SLA 3330 E

Date of Accident : 11/03/2019

M/S SLS 518 PTE LTD

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

COST OF REPAIR TO TOYOTA HIACE : PC 7608 X

A) Chassis No : JTFHT02P400033305

B) Date of Registration : 05/11/2008

S/No. Pc/s Item(s) :-

01.	1	rear fender RH
02.	1	wheel hub cap
03.	1	rear bumper

\$	bl
1,670.00	
185.00	ent
415.00	ent

2,270.00

Less 25% discount :-

567.50

1,702.50

Special Nett(s) :-

04.	1	inner seal
05.	2	sealant
06.	1	private bus sticker

40.00	re
80.00	
20.00	re

1,842.50

Labour Charges :

- | | | | |
|----|---|----------|-----|
| a) | To dismantle all damaged parts, cut/weld rear fender RH and re-align, check, adjust and replace the above parts | 1,000.00 | 600 |
| b) | To putty and spray paint rear bumper, step garnish and all affected portions | 600.00 | 400 |
| c) | To remove and refit rear fender glass RH | 200.00 | 100 |
| d) | To check alignment | 60.00 | ✓ |
| e) | To remove and refit trims and upholstery | 120.00 | 60 |

3,822.50

GST (7%) :-

267.58

Total :-

4,090.08

Taufik 97495744
WP

11/4/19 1pm

Resum after repair
6 days

Taufik e/khand.com
sure khand.com

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before after spray painting
- To display damaged parts, subject to resurvey
- Parts price subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental terms and conditions are surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: