



Steve (LKK) wL Pte Ltd

AIG Aisa Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way #07-16

Singapore 079120

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC: 201015366H

3RD PARTY SUPPLY ESTIMATION

Vehicle number SLU130E

Make / Model HONDA / VEZEL

Chassis number RU11228362

Accident date 07 April 2019

Reference 1904-23

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER / CUT	1092.30
2	REAR BUMPER RETAINER (RH) BR	110.30
1	REAR RH CORNER PANEL CR4 /	319.40
1	REAR RH TAILLAMP CUT /	483.00
1	REAR RH TAILGATE INNER LAMP X	405.75
1	REAR BUMPER REFLECTOR RH ?	151.00
1	REAR RH FENDER OUTER GARNISH / CUT	203.55
1	END PANEL X R	585.02
		3350.32
	Less 20%	670.06
	Subtotal	2680.26
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
	Balance B/F	2680.26
1 SET	REAR REVERSE SENSOR	X 300.00
1 SET	REAR BUMPER CLIP NCC	Jo 40.00
1	JOINT SEALANT P	X 150.00
	Subtotal	490.00
	Balance C/F	3170.26
LABOUR AND MISCELLANEOUS CHARGES		
	Balance B/F	3170.26
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	Jo 60.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	X 150.00
3	REMOVE , REFIT REAR LINING, TRIM AND GARNISH	X 120.00
4	PANEL BEATING ON AFFECTED AREAS	Jo 800.00
5	SPRAY PAINTING ON AFFECTED AREAS	400 800.00
6	APPLY ANTI RUST ON AFFECTED AREAS	X 120.00
	Subtotal	2050.00
	Grand total	5220.26