



# 凱摩哆服務

## KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.  
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com  
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 08/04/2019

Attn: The Motor Claims Department

Your Insured veh no : SFS 9936 U

**AIG ASIA PACIFIC INSURANCE PTE LTD.**

**78 Shenton Way**

**# 07-16 Chartis Building**

**Singapore 079120**

10/04/19 - suryer

18.04.19 - resurfer

10 days

WITHOUT PREJUDICE

(By Email Only)

Asher

LKK

9689 3735 Adrian

Dear Sir / Madam

Estimate Cost Repair Bill To Totoya Dyna No GBH 1934 H & SFS 9936 U on 03/04/2019@14:45:00

To Supply:-

|       |                                          |              |                      |
|-------|------------------------------------------|--------------|----------------------|
| 1pc   | Front body panel <i>dented.</i>          |              | \$ 1,205.10 ✓        |
| 1pc   | Front body panel "DYNA" plate            | } <i>new</i> | \$ 85.60 ✓           |
| 1pc   | Front body panel "logo" plate            |              | \$ 89.10 ✓           |
| 1pc   | Front wiper panel <i>dented</i>          |              | \$ 328.10 ✓          |
| 1pc   | Front grille <i>cracked</i>              |              | \$ 565.10 ✓          |
| 10pcs | Front grille clips <i>nec</i>            |              | \$ 100.00 <i>30.</i> |
| 2pcs  | Front head lamp <i>cracked.</i>          | \$ 1,210.10  | \$ 2,420.20 ✓        |
| 1pc   | Front bumper <i>Bent.</i>                |              | \$ 525.10 ✓          |
| 1pc   | Front windscreen glass rubber <i>nec</i> |              | \$ 305.10 ✓          |
| 2pcs  | Front bumper bracket <i>Bent.</i>        | \$ 265.10    | \$ 530.20 ✓          |
| 2pcs  | Rear lamp <i>not nec</i>                 | \$ 286.00    | \$ 572.00 <i>+</i>   |
|       |                                          |              | \$ 6,725.60          |
|       |                                          |              | 25% \$ 1,681.40      |
|       |                                          |              | \$ 5,044.20          |

6083.60 less

4562.70

25%

\$ 1,681.40

\$ 5,044.20

|      |                                                      |           |                               |
|------|------------------------------------------------------|-----------|-------------------------------|
| 1pc  | Rear cool box door <i>Repair</i>                     |           | \$ 2,800.00 nett <i>x.</i>    |
| 1pc  | Rear 70km/h <i>nec</i>                               |           | \$ 20.00 nett <i>10.</i>      |
| 1pc  | Rear door rubber <i>cut</i>                          |           | \$ 650.00 nett <i>200.</i>    |
| 1pc  | Rear foot steep bracket <i>Bent</i>                  |           | \$ 690.00 nett <i>280</i>     |
| 1pc  | Rear stainless steel door lower member <i>Dented</i> |           | \$ 2,200.00 nett <i>1500</i>  |
| 1set | Rear rubber stopper <i>LH cut</i>                    | \$ 265.00 | \$ 530.00 nett <i>265.160</i> |
| 1set | Rear door hook/holder bracket <i>not nec</i>         |           | \$ 350.00 nett <i>x.</i>      |
|      |                                                      |           | \$ 7,240.00                   |
|      |                                                      |           | 10% \$ 724.00                 |
|      |                                                      |           | \$ 6,516.00                   |

\$ 11,560.20



# 凱摩哆服務

## KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.  
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com  
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 08/04/2019

Attn: The Motor Claims Department

Your Insured veh no : SFS 9936 U

**AIG ASIA PACIFIC INSURANCE PTE LTD.**

**78 Shenton Way**

**# 07-16 Chartis Building**

**Singapore 079120**

WITHOUT PREJUDICE

(By Email Only)

Dear Sir / Madam

Page . 2

**Estimate Cost Repair Bill To Totoya Dyna No GBH 1934 H & SFS 9936 U on 03/04/2019@14:45:00**

To Supply:-

\$ 11,560.20

1pc Front number plate *Bent*  
1pc Front number plate *we see*  
1set Reverse sensor *Damaged*

230

\$ 45.00 s/nett *30*  
\$ 45.00 s/nett *\**  
\$ 350.00 s/nett *200*

To dismantl & replace damage parts, panel beat where necessary.

\$ 1,500.00 *1200*

To putty, apply primer & spray paint on the affected portion.

\$ 1,200.00 *1000*

To check wiring functions.

\$ 80.00 *60.*

labour charge to remove & refix windscreen

2380

\$ 120.00 ✓

To remove & refit the dashboard

\$ 280.00 *\**

To top up air cond gas.

\$ 85.00 *\**  
\$ 15,265.20

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Adrian King*  
*P/P 10/04/19.*

*10 Days.*

*total: 9107.70 (P/P)*