

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

TAN WEE TIONG

DATE	8/4/2019
VEHICLE NO:	SGC 3406 U
MAKE:	HONDA
MODEL:	VEZEL

TPAIG

Poh Kin

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	FRONT BUMPER <i>Detached</i>	583.70	583.70 ✓
1 PC	FOG LAMP COVER <i>nd</i>	57.54	57.54 ✓
1 PC	BUMPER LOWER SPOILER <i>cut</i>	285.74	285.74 ✓
1 PC	FRONT FENDER L/H <i>Detached</i>	597.22	597.22 ✓
1 PC	WHEEL ARC GARNISH L/H <i>cut</i>	177.82	177.82 ✓
1 PC	FRONT HEADLAMP L/H <i>included</i>	1,820.54	1,820.54 ✓
1 PC	SIDE RETAINER L/H <i>New</i>	18.71	18.71 ✓

3541.27

2833.01

LESS 20%	----- SUBTOTAL		3,541.27
	----- LESS 20%	-20.00%	-708.25

-	1 SET NUMBER PLATE AND HOLDER		
	TRIP TO LTA FOR NUMBER PLATE SEAL REMOVAL	220.00	220.00 ✓ 80
	TRIP TO INSPECTION CENTRE FOR SEAL INSTALLATION		
	VICOM FEE		
-	TO RESTORE INNER BRACKETS AND PANEL.		
	TO REPLACE, INSTALL AND ALIGN ABOVE PARTS TO SYMMETRICAL SPEC.	680.00	680.00 ✓ 40
-	TO SPRAY PAINT INNER PANEL/BRACKETS, FRONT BUMPER AND FENDER	650.00	650.00 ✓ 40
-	TO CARRY OUT WIRE CHECKING	80.00	80.00 ✓ 30

910

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Tel: 6745 5783
Email: sinhweemotor@gmail.com
Website: www.sinhweemotor.com

Fax: 6744 9582

TOTAL \$4,463.02

Adrian Lij
2/5 09/04/19. 2/5: 3K.
04 days.
Total: 3743.01