

Hwee Jie

REF:

M816 (C3/MSG19006425/3rd3)

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No 26850869

Claims No 589929


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No SHF330X

Yr Regn: 14 Dec 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Togota Prius c.c. 1798Colour: maroon A/C Insured / Std / NI / NASp Reading: 80238 T/Ratio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU303576548Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 7/4/19 D.O.I. 9/4/19Survey held at SumitDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHF 330X - (C3/ALG18021556/12/163) DOA - 27/11/2018

GV 637IR - X


04/19/2027

11/4@1:40pm Sent email to Iryani AIA k estimate.

GV 637IR

Part by Part \$1741.05 (Red: 5483-69, 75%)

RECEIVED 22 JUL 2019



Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1) 19/7 Typist.

☒ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

Transportation

2)

Add Fee: ☐ : Site Insp (\$)

Report Format: TP

☐ : Interview (\$)

Lump Sum / I.B.I. (\$)

☐ : Tech. Invs (\$)☐ : Weekend (\$)

Photos

Others

TOTAL

150

11

161

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 11 April 2019 1:40 PM
To: iryani_amin@sg.msig-asia.com
Cc: SUR; Accounts (LKKAuto); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD (TP VEHICLE: SHF 330X, INSURED VEHICLE: GV 6371R, DOA: 07/04/2019)
Attachments: estimate.pdf; GIA REPORT SHF 330X.pdf

Dear Iryani,

Please be informed that we had inspected the vehicle **SHF 330X** at M/s: SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705.

Enclosed herewith a copy of TP's GIA report and estimate.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/04/19/2027	Date of Collection	09/04/19
Vehicle No	S4F 330X	Date of Request	09/04/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
	(Supp)	Filler, RR Bumper, RH	1	\$119.90
		70 Respray Filler RR Bumper RR		\$180.00

1 BR
Repair
\$80
100

<<<Please submit photographs for damaged parts>>>

I, (Name)

Henry Che Kwong

10/4/19
ay

(Position)

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....*Henry Che Kwong*.....

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/04/2019 14:26
Date Of Accident	07/04/2019 14:40
Exact Location Of Accident	BLK 161 TAMPINES STREET 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF330X
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	YAP ENG MENG
NRIC No	S6933327C
Date Of Birth	30/09/1969
Occupation	OUTDOOR
Date Of Driving Pass	05/01/1996
Driving Experience	23 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	60
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT. I was driving towards Block 162 Tampines Street 12 to pick up a passenger after I got a booking from the Grab app. There was a van (GV6371R) in front of my taxi (SHF330X) when we were turning into the car park. Upon entering the car park, the van made a right turn while I continued to go straight towards the gantry. Suddenly I felt a collision behind my taxi and realised that the van had reversed and hit the right rear of my taxi. There was no way I could have avoided the accident as I was driving past the van when it happened unlike if I had seen him reversing when I was entering the car park then I would have stopped. We came out to take pictures at the accident site and exchanged personal details to make an accident report. The third party explained that he was reversing as the gantry lever did not lift up but upon reviewing my video recording, his van was quite far away from the gantry. Thus I suspect he was trying to make a reverse U-turn in the car park area. There was no passenger in my taxi neither was there any injury and the weather was fine.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV6371R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SOH THIAM SIEW
NRIC/Passport Number	S2503022B
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


8 Apr 19 1300H

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

8/4/19

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see attached word document and video recording for evidence.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)

Date & Time: 8 Apr 19 1300H

[Signature] 8/4/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle



Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHF330X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8259485
Chassis No.:	JTDKB3FU303576548
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	14 Dec 2017
First Registration Date:	14 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$28,500.00
Total Rebate Amount:	\$32,250.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Apr 2019

OK



Section A - Accident Details

Registration Number	SHF330X
Case Reference Number	TAX/04/19/2027
Registration Date	14/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	YAP ENG MENG
Type of Accident	Others
Accident Date and Time	7/4/2019 2:40 PM
Accident Reported Date and Time	8/4/2019 2:35 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100961
Special Instruction to ARC, if any	TP
Prepared Date and Time	8/4/2019 6:28 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Signature

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$500.00
Total Spray Cost	\$1,296.00	\$500.00
Total Spare Part Cost	\$3,262.69	\$681.05
Total Other Cost	\$840.00	\$60.00
TOTAL COST	\$6,412.69	\$1,741.05 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / MSIG
ARC / Surveyor Sign Off Date	08/04/2019 6:45 PM	09/04/2019 1:20 PM
Signature		
Remarks	P/P REPAIR, PHOTO BEFORE PAINT.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0182	Invoice Number	
Quotation Date	10.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$1,014.00	\$500.00 /
Total Labour	\$1,014.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 /
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$100.00 /
Total Spray Painting & Panel Beating	\$1,296.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00 /
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$840.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	30.00	\$296.73	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	30.00	\$10.50	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	30.00	\$5.32	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	30.00	\$5.32	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	30.00	\$5.32	Replace	Replace
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	30.00	\$15.40	Replace	Replace
		52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52575470 40	RETAINER, RR BUMPER, RH	1.00	\$112.70	30.00	\$78.89	Replace	Replace

350

cut

nee

nee

nee

nee

nee

nn

nee

Br

	5259147050	SEAL, RR BUMPER, RH	1.00	\$85.20	30.00	\$59.64	Replace	Replace	✓
	8158147010	LENS & BODY ASSY, RR BUMPER, RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	✓
	6563747080	LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
	4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
Total				\$3,954.84		\$597.12			

hec
nn
R
NN
NN
NN

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
	(SPP)	5256547900	FILLER, RR BUMPER, RH	1.00	\$119.90	30.00	\$83.93	Replace	Replace
Total					119.90		83.93		

cut

681.05
+ 500.00
+ 560.00

1741.05

* Got before spray photo P/P

Stem checked 17/7/19

407474
3150

722474

7320.64

Case Details

Case Reference Number : TAX/04/19/2027
Type of Repair : Accident Repair
Vehicle Registration Number : SHF330X

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-6406-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : MSIG Insurance (S) Pte Ltd
Accident Date and Time : 07/04/2019 06:40 AM
Vehicle Age(In Months) : 16

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	30.00	317.92	Replace	1	317.92	Replace	/ CUT
One Time Key In	Main			CLIPS, PIECE, FRT & RR BUMPER	10	1.50	15.00	30.00	11.25	Replace	10	11.25	Replace	/ APC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	30.00	5.70	Replace	2	5.70	Replace	/ APC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	30.00	5.70	Replace	2	5.70	Replace	/ APC
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	30.00	5.70	Replace	2	5.70	Replace	/ APC
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	30.00	16.50	Replace	2	16.50	Replace	/ APC
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	30.00	89.93	Replace	0	0	Not Give	X / M11
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ APC
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	30.00	84.53	Replace	1	84.53	Replace	/ OR

Total Spare Part Cost 3,172.76

Surveyor Total 631.20

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 1,879.70

Final Sur Total 631.20

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	30.00	63.90	Replace	1	63.90	Replace	APC
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	X MM
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	30.00	618.60	Replace	1	0	Repair	X R
One Time Key In	Main			LINER, REAR FENDER, RH	1	135.80	135.80	30.00	101.85	Replace	0	0	Not Give	X MM
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	30.00	1,166.32	Replace	0	0	Not Give	X MM
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X MM

Total Spare Part Cost	3,172.76	Surveyor Total	631.20
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	1,879.70	Final Sur Total	631.20

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	1,014.00	500	
Total:			1,014.00	500.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
3	Main	TO RESPRAY REAR FENDER RH	378.00	200	
4	Main	TO RESPRAY RIM	180.00	0	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	APC
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	APC
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	APC
6	Main	TO REMOVE / REFIT SEAT	120.00	0	
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
8	Main	TO WASH AND VACUUM	60.00	0	
Total:			840.00	60.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,879.70	631.20
Total Labour Cost	1,014.00	500.00
Total Spray Painting	1,116.00	400.00
Other	840.00	60.00
Overall Total	4,849.70	1,591.20
Lump Sum Repair Option		
Lump Sum Total	0.00	1,591.20
Surveyor Approved Amount		1,591.20
No of Repair Days*	7	4
Remarks	-	P/P REPAIR, PHOTO BEFORE PAINT.
Surveyor Name		Hwee jie

4/3/2019

Signature

Estimator Assessment(\$)

Surveyor Assessment(\$)

g

0

Save

Clear

Survey Date

09/04/2019

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:


















...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Apr 2019		12 Apr 2019 10:51 Edit Adj Rpt	S\$1,741.05 Edit Estimates	S\$1,741.05 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ABV SYSTEMS PTE LTD , Co. Reg. No.: 199003336Z								
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHF330X	Date of Loss:	07/04/2019 14:00 - :59 [15 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 589929	Policy/Cover Note No.:	26850869 (Third Party Only) Coverage: 03/03/2019 - 02/03/2020						
Vehicle Reg. No. (Insured):	GV6371R	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Imm.Advice due 13/04/2019]								
Driver/Custodian (Insured):	SOH THIAM SIEW (), NRIC: S2503022B, Tel: +6590862031 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHF330X (589929)**
[GV6371R]
TP
SMRT TAXIS PTE LTD
Apr 7 2019 2:00PM
[ABV SYSTEMS PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/04/19 10:43	Accident Statement From:SC - Reg. No: GV6371R, Claimant: ABV SYSTEMS PTE LTD	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/04/19 08:56	General View	 Load JPG	<input checked="" type="checkbox"/>
17	19/07/19 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
18	19/07/19 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
19	19/07/19 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/04/19 10:43	E FILE SHF330X From:SC - Reg. No: GV6371R, Claimant: ABV SYSTEMS PTE LTD	 Load PDF	
2	12/04/19 10:50	Estimate	 Load PDF	
3	12/04/19 10:51	Direct Survey by LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19006425/ETD3E2

Date: 07/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 26850869

Claimant Vehicle No : SHF330X

Insured Vehicle No : GV6371R

Date of Loss: 07/04/2019

Nature of Claim: TP Claim No: 589929

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHF330X

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR8259485

Reg. Date: 14/12/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU303576548

Colour: Maroon

Odometer: 80238 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,170.64	681.05	3,489.59	83.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	1,060.00	2,090.00	66.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	7,320.64	1,741.05	5,579.59	76.22

INSPECTION

Date of Assignment: 12/04/2019

Date Inspected: 09/04/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Aug 2019)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF330X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, RR BUMPER ASSY (DISC 30%)	Cut	423.90 F	*296.73 F
2	10		*CLIPS PIECE, FRT & RR BUMPER (DISC 30%)	Necessary	15.00 F	*10.50 F
3	2		*PAD, RR BUMPER, RH & LH, 1 (DISC 30%)	Necessary	7.60 F	*5.32 F
4	2		*PAD, RR BUMPER, RH & LH, 2 (DISC 30%)	Necessary	7.60 F	*5.32 F
5	2		*PAD, RR BUMPER, RH & LH, 3 (DISC 30%)	Necessary	7.60 F	*5.32 F
6	2		*SEAL, RR BUMPER ARM, RH & LH (DISC 30%)	Necessary	22.00 F	*15.40 F
7	1		*RETAINER, RR BUMPER, RH (DISC 30%)	Broken	112.70 F	*78.89 F
8	1		*SEAL, RR BUMPER, RH (DISC 30%)	Necessary	85.20 F	*59.64 F
9	1		*FILLER, RR BUMPER, RH (DISC 30%)	Cut	119.90 F	*83.93 F
10	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
11	1		*FILLER, RR BUMPER, RH	Not Necessary	119.90 F	*- F
12	1		*LENS & BODY ASSY, RR BUMPER, RH	Not Necessary	486.80 F	*- F
13	1		*LINER, REAR FENDER, RH	Not Necessary	135.80 F	*- F
14	1		*WHEEL, DISC	Not Necessary	1,555.10 F	*- F
15	1		*TYRE	Not Necessary	126.74 F	*- F
16	1		*PANEL SUB-ASSY, FENDER REAR RH	Repair	824.80 F	*- F
					Total Parts (S\$)	4,170.64 681.05

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	500.00
2	SPRAY PAINT	New	1,296.00	500.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	20.00
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING	New	120.00	0.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
8	TO REMOVE / REFIX SEAT	New	120.00	0.00
9	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
10	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			3,150.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >