

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Document no.
Document date 09-04-2019
Customer no. 5211042417
Customer GST-ID
Dealer 39999
Job order number 2019000163/ 1
Job order date 09-04-2019
Service Advisor MEI KWAN KONG

Mr
HUA
YONG
270C PUNGGOL FILED
Singapore 823270

Taufik 1749549
wp
11/4/19c 1130
Reservy before paint
6-7 days
sur Elkhamban.

License plate	Model code	First registration	VIN	Model	Mileage
SMF2739D	5T13NZ	31-10-2018	WVGZZZ1TZKW005691	Touran Comfortline 1.4 I TSI 110kW DSG	3,604

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5TA807417 GRU	Cover For Bumper Primed	1	pcs.	1,139.96	#1	1,139.96	1,219.76
5TA807568A 9B9	Spoiler Satin Black	1	pcs.	273.34	#1	273.34	292.47
5TA807305	Bumper	1	pcs.	442.56	#1	442.56	473.54
	BUMPER REINFORCEMENT						
5TA807863	Attachment Strip	1	pcs.	55.98	#1	55.98	59.90
5TA807453	Guide Piece	1	pcs.	36.27	#1	36.27	38.81
	BUMPER REAR GUIDE LH						
5TA807454	Guide Piece	1	pcs.	36.27	#1	36.27	38.81
	BUMPER REAR GUIDE RH						
5TA807393	Guide Piece	1	pcs.	29.49	#1	29.49	31.55
	BUMPER REAR BRACKET LH						
5TA807394	Guide Piece	1	pcs.	29.49	#1	29.49	31.55
	BUMPER REAR BRACKET RH						
3CN945087	Additional Brake Light Wi	1	pcs.	208.66	#1	208.66	223.27
5TA827025P	Rear Trunk Lid	1	pcs.	1,914.28	#1	1,914.28	2,048.28
	BOOTLID						
5TA853687 2ZZ	Inscription Bright Chrome	1	pcs.	58.66	#1	58.66	62.77
	TOURAN						
5TA853630A DPJ	Vw Sign Black/Bright Chro	1	pcs.	89.76	#1	89.76	96.04
	VW						
D 004660M2	2k-Glass Glue Application	1	pcs.	123.02	#1	123.02	131.63
D 00920002	Primer	1	pcs.	25.92	#1	25.92	27.73
D 181802M1	Activator For Precoated W	1	pcs.	23.63	#1	23.63	25.28
D 00920002	Primer	1	pcs.	25.92	#1	25.92	27.73
D 00950025	Applicator	1	pcs.	9.48	#1	9.48	10.14
	Panel Repair and Straightening	5	pcs.	840.00	#1	4,200.00	4,494.00
	RE+REINSTALLED REAR WINDSCREEN	1	pcs.	840.00	#1	840.00	898.80
	Spray Painting	5	pcs.	800.00	#1	4,000.00	4,280.00
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	For Diagnostic and Programming						
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Harness Repair and Short Circuit Check						

Quotation valid till 16-04-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1		14,322.69	7%	1,002.59	14,322.69	15,325.28
Total		14,322.69		1,002.59	14,322.69	15,325.28

LKK Auto Consultants

the Repairer of

- To reserve
- To display
- Parti
- Third
- No
- St
- IS

Ackn

Signature:

Date:

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Mr
HUA
YONG
270C PUNGGOL FILED
Singapore 823270

Page	2/2
Document no.	
Document date	09-04-2019
Customer no.	5211042417
Customer GST-ID	
Dealer	39999
Job order number	2019000163/ 1
Job order date	09-04-2019
Service Advisor	MEI KWAN KONG

License plate	Model code	First registration	VIN	Model	Mileage
SMF2739D	5T13NZ	31-10-2018	WVGZZZ1TZKW005691	Touran Comfortline 1.4 I TSI 110kW DSG	3,604

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: