

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0459/2019/DY
Date : 9-Apr-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

We took 9 days - ok - jb - 1 Jun 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lee Zhen Jian
Address : Blk 83 Yishun Avenue 11
#11-28
Singapore 768864
Telephone : HP +65 91896535
Type of Claim : Own Damage Claims
Policy No. : 1700052840-01
Vehicle No : **SLT 8155 L**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Sep-17
Engine No : CVN 041502
Chassis No : WAUZZZF48HA182383
Mileage : 25922
Date In : 9-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Apr-19
Place of Accident : CTE before Ang Mo Kio Ave 5

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 8155 L

S/N	Nature of Jobs		Estimated Charges		
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	s/n	\$ 360.00	\$	360.00
2	To dismantle both front door panel trim. To remove and reinstall both front wing mirror assy.	s/n	\$ 600.00	\$	600.00
3	To remove and renew aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	s/n	\$ 1,200.00	\$	1,200.00
4	To dismantle and renew front bumper, both front fender, both headlights and bonnet. Renew front lock carrier and align to position. Re-organize front crash management components. Reinstall all parts removed.		\$ 5,600.00	\$	2,000.00
5	To respray front bumper, bonnet hinges, both front fender, bonnet and both front doors.		\$ 4,600.00	\$	2,750.00
6	To carry out diagnostic check.	s/n	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 12,552.00	\$	7,102.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER COVER	\$ 1,703.00	\$ 1,362.40
2	FIXING PARTS FOR FRONT BUMPER	\$ 240.00	
3	SECURING STRIP FOR FRONT BUMPER	2 \$ 57.00	
4	FRONT CENTER GRILLE	\$ 163.00	
5	CLOSING ELEMENT	\$ 171.00	
6	AIR GUIDE GRILLE FOR FRONT BUMPER - LH	\$ 67.00	
7	AIR GUIDE GRILLE FOR FRONT BUMPER - RH	\$ 67.00	
8	RADIATOR GRILLE	\$ 941.00	\$ 752.40
9	AIR GUIDE GRILLE - LH	\$ 112.00	
10	AIR GUIDE GRILLE - RH	\$ 112.00	
11	FOAM FILLER PIECE	\$ 101.00	\$ 90.40
12	BUMPER CARRIER	\$ 674.00	
13	GUIDE SECTION - LH	\$ 29.00	
14	GUIDE SECTION - RH	\$ 31.00	
15	BUMPER COVER	\$ 104.00	\$ 82.80
16	CAUTION' SIGN	\$ 12.00	\$ 9.76
17	STICKER FOR AIR CONDITIONER	\$ 6.00	\$ 5.12
18	BRACKET FOR LOCK CARRIER	\$ 112.00	\$ 89.20
19	SUPPORT - LH	\$ 23.00	\$ 20.32
20	SUPPORT - RH	\$ 23.00	\$ 20.32
SUB TOTAL SPARE PARTS		\$ 4,748.00	\$ 2,432.72

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 2,432.72</i>
21	FRONT FENDER - LH		\$ 643.00	
22	FRONT FENDER -RH		\$ 643.00	<i>\$ 514.40</i>
23	ATTACHMENT PARTS FOR FENDER	2	\$ 365.00	
24	CLOSING ELEMENT - LH		\$ 29.00	
25	CLOSING ELEMENT - RH		\$ 27.00	<i>\$ 36.00</i>
26	BRACKET FOR FENDER - LH		\$ 29.00	
27	BRACKET FOR FENDER - RH		\$ 29.00	
28	BRACKET FOR DEFORMATION ELEMENT - RH		\$ 42.00	<i>\$ 35.60</i>
29	BRACE - FRONT LH		\$ 100.00	
30	BRACE - FRONT RH		\$ 100.00	
31	WHEEL HOUSING LINER - LH		\$ 208.00	
32	WHEEL HOUSING LINER - RH		\$ 202.00	
33	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	2	\$ 152.00	
34	WHEEL SPOILER - LH		\$ 61.00	
35	WHEEL SPOILER - LH		\$ 66.00	
36	STONE CHIP GUARD		\$ 46.00	<i>\$ 36.64</i>
37	BONNET		\$ 2,001.00	<i>\$ 1,600.80</i>
38	ATTACHMENT PARTS FOR BONNET		\$ 103.00	
39	LID HINGE - LH		\$ 257.00	
40	LID HINGE - RH		\$ 257.00	
SUB TOTAL SPARE PARTS		:	<u>\$ 5,360.00</u>	<u><i>\$ 4,656.16</i></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/NETT	REMARKS
		<i>c/f</i>	<i>\$ 4,656.16</i>
41	IMPACT PROTECTION - CENTER	\$ 23.00	<i>\$ 19.76</i>
42	IMPACT PROTECTION - LH	\$ 23.00	
43	IMPACT PROTECTION - RH	\$ 23.00	<i>\$ 19.76</i>
44	COVER - LH	\$ 28.00	
45	COVER - RH	\$ 28.00	<i>\$ 22.24</i>
46	COVER FOR IMPACT PROTECTION - LH	\$ 19.00	
47	COVER FOR IMPACT PROTECTION - RH	\$ 19.00	<i>\$ 16.16</i>
48	GAS FILLED STRUT	2 \$ 196.00	
49	STRIKER - LH	\$ 43.00	
50	STRIKER - RH	\$ 43.00	
51	LID LOCK	2 \$ 360.00	
52	BOWDEN CABLE - CENTER	\$ 49.00	
53	COVER	\$ 9.00	
54	BOWDEN CABLE	\$ 49.00	<i>\$ 41.68</i>
55	RELEASE LEVER	\$ 12.00	<i>\$ 9.60</i>
56	LID LOCK CABLE	\$ 67.00	
57	SOUND ABS FOR ENGINE BONNET	\$ 311.00	
58	FAN FARE HIGH TONE - LH	\$ 35.00	
59	FAN FARE LOW TONE - RH	\$ 248.00	
60	SPRING SHACKLE - LH	\$ 26.00	
SUB TOTAL SPARE PARTS		\$ 1,611.00	<i>\$ 4,785.36</i>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
		<i>c/f</i>	<i>\$</i>	<i>4,785.36</i>
61	SPRING SHACKLE - RH	\$ 26.00		
62	LED HEADLIGHT - LH	\$ 7,861.00	<i>\$</i>	<i>6,288.80</i>
63	LED HEADLIGHT - RH	\$ 7,861.00	<i>\$</i>	<i>6,288.80</i>
64	LIFT CYLINDER - LH	\$ 180.00		
65	LIFT CYLINDER - RH	\$ 180.00		
66	LOCK CARRIER WITH MOUNTING FOR RADIATOR	\$ 878.00		
67	A/C CONDENSER WITH DRYER	\$ 568.00	<i>\$</i>	<i>454.00</i>
68	COOLER FOR COOLANT	\$ 576.00		
69	RUBBER BUSH - LOWER	2 \$ 16.00		
70	RUBBER BUSH	2 \$ 22.00		
71	ADDITIONAL COOLER FOR COOLANT	\$ 444.00		
72	PREMIX COOLANT	4 \$ 81.00	<i>\$</i>	<i>67.20</i>
73	AIR GUIDE - LH	\$ 22.00	<i>\$</i>	<i>19.84</i>
74	AIR GUIDE - RH	\$ 22.00	<i>\$</i>	<i>19.84</i>
75	AIR GUIDE - LH	\$ 10.00	<i>\$</i>	<i>8.32</i>
76	AIR GUIDE - RH	\$ 10.00	<i>\$</i>	<i>8.32</i>
77	AIR GUIDE - UPPER	\$ 13.00		
78	AIR GUIDE - LOWER	\$ 17.00		
79	FAN RING	\$ 222.00		
80	RADIATOR FAN WITH CONTROL UNIT	\$ 2,107.00		
SUB TOTAL SPARE PARTS		:	\$ 21,116.00	<i>\$ 17,940.48</i>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
		<i>c/f</i>	<i>\$ 17,940.48</i>
81	INTAKE AIRDUCT	\$ 17.00	
82	AIR GUIDE	\$ 48.00	
83	SEAL	\$ 12.00	
84	AIR FILTER	\$ 352.00	
85	INTAKE HOSE	\$ 85.00	
86	WINDOW SLOT SEAL WITH TRIM STRIP - LH	\$ 259.00	<i>\$ 207.20</i>
87	WINDOW SLOT SEAL WITH TRIM STRIP - RH	\$ 259.00	<i>\$ 207.20</i>
88	TRIM STRIP FOR WINDOW GUIDE - LH	\$ 217.00	
89	TRIM STRIP FOR WINDOW GUIDE - RH	\$ 217.00	
90	FRONT NUMBER PLATE	\$ 40.00	<i>\$ 40.00</i>
91	SUNDRIES	\$ 1,000.00	<i>\$ 33.44</i>
TOTAL SPARE PARTS		\$ 35,341.00	<i>\$ 18,428.32</i>
TOTAL LABOUR CHARGES		\$ 12,552.00	<i>\$ 7,102.00</i>
GRAND TOTAL		\$ 47,893.00	<i>\$ 25,530.32</i>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant