

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0459/2019/DY
Date : 9-Apr-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lee Zhen Jian
Address : Blk 83 Yishun Avenue 11
#11-28
Singapore 768864
Telephone : HP +65 91896535
Type of Claim : Own Damage Claims
Policy No. : 1700052840-01
Vehicle No : **SLT 8155 L**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Sep-17
Engine No : CVN 041502
Chassis No : WAUZZZF48HA182383
Mileage : 25922
Date In : 9-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Apr-19
Place of Accident : CTE before Ang Mo Kio Ave 5

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 8155 L

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. <i>214.</i>	s/n \$ 360.00 ✓
2	To dismantle both front door panel trim. To remove and reinstall both front wing mirror assy.	s/n \$ 600.00 300 600
3	To remove and renew aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	s/n \$ 1,200.00 ✓
4	To dismantle and renew front bumper, both front fender, both headlights and bonnet. Renew front lock carrier and align to position. Re-organize front crash management components. Reinstall all parts removed.	\$ 5,600.00 ✓ 2000 without lock carrier 3250 with lock carrier.
5	To respray front bumper, bonnet hinges, both front fender, bonnet and both front doors. ✓ ✓ ✓	\$ 4,600.00 2750 5x550=2750
6	To carry out diagnostic check. ✓ <i>211.</i>	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>12,552.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER <i>Distorted</i>	\$ 1,703.00	✓ 1362.40
2	FIXING PARTS FOR FRONT BUMPER <i>new</i>	\$ 240.00	+
3	SECURING STRIP FOR FRONT BUMPER <i>new</i>	2 \$ 57.00	+
4	FRONT CENTER GRILLE <i>new</i>	\$ 163.00	+
5	CLOSING ELEMENT <i>new</i>	\$ 171.00	+
6	AIR GUIDE GRILLE FOR FRONT BUMPER - LH <i>new</i>	\$ 67.00	+
7	AIR GUIDE GRILLE FOR FRONT BUMPER - RH <i>new</i>	\$ 67.00	+
8	RADIATOR GRILLE <i>crushed</i>	\$ 941.00	✓ 752.40
9	AIR GUIDE GRILLE - LH <i>new</i>	\$ 112.00	+
10	AIR GUIDE GRILLE - RH <i>new</i>	\$ 112.00	+
11	FOAM FILLER PIECE <i>crushed.</i>	\$ 101.00	✓ 90.40
12	BUMPER CARRIER <i>new</i>	\$ 674.00	? X
13	GUIDE SECTION - LH <i>new</i>	\$ 29.00	+
14	GUIDE SECTION - RH <i>new</i>	\$ 31.00	+
15	BUMPER COVER <i>crushed</i>	\$ 104.00	✓ 82.80
16	CAUTION SIGN <i>new</i>	\$ 12.00	✓ 9.76
17	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 6.00	✓ 5.12
18	BRACKET FOR LOCK CARRIER <i>crushed</i>	\$ 112.00	✓ 89.20
19	SUPPORT - LH <i>new</i>	\$ 23.00	✓ 20.32
20	SUPPORT - RH <i>new</i>	\$ 23.00	✓ 20.32
SUB TOTAL SPARE PARTS		\$ 4,748.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER - LH <i>Regis</i>	\$	643.00 <i>x</i>
22	FRONT FENDER - RH <i>Buckled</i>	\$	643.00 <i>✓</i> 514.40
23	ATTACHMENT PARTS FOR FENDER <i>Not new</i>	2 \$	365.00 <i>✓ x</i>
24	CLOSING ELEMENT - LH <i>Not new</i>	\$	29.00 <i>x</i>
25	CLOSING ELEMENT - RH <i>Not new - Damaged</i>	\$	27.00 <i>+ ✓ 36</i>
26	BRACKET FOR FENDER - LH <i>Not new</i>	\$	29.00 <i>x</i>
27	BRACKET FOR FENDER - RH <i>Not new</i>	\$	29.00 <i>? x</i>
28	BRACKET FOR DEFORMATION ELEMENT - RH <i>Not new</i>	\$	42.00 <i>✓ 35.60</i>
29	BRACE - FRONT LH <i>Not new</i>	\$	100.00 <i>x</i>
30	BRACE - FRONT RH <i>Not new</i>	\$	100.00 <i>? x</i>
31	WHEEL HOUSING LINER - LH <i>Not new</i>	\$	208.00 <i>x</i>
32	WHEEL HOUSING LINER - RH <i>Not new</i>	\$	202.00 <i>x</i>
33	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>Not new</i>	2 \$	152.00 <i>x</i>
34	WHEEL SPOILER - LH <i>Not new</i>	\$	61.00 <i>x</i>
35	WHEEL SPOILER - LH <i>Not new</i>	\$	66.00 <i>x</i>
36	STONE CHIP GUARD <i>Not new</i>	\$	46.00 <i>✓ 36.64</i>
37	BONNET <i>Dented</i>	\$	2,001.00 <i>✓ 1600.80</i>
38	ATTACHMENT PARTS FOR BONNET <i>Not new</i>	\$	103.00 <i>? x</i>
39	LID HINGE - LH <i>Not new</i>	\$	257.00 <i>? x</i>
40	LID HINGE - RH <i>Not new</i>	\$	257.00 <i>? x</i>
SUB TOTAL SPARE PARTS		:	\$ 5,360.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	IMPACT PROTECTION - CENTER <i>new</i>	\$ 23.00	✓ 19.76
42	IMPACT PROTECTION - LH <i>new</i>	\$ 23.00	✓ X
43	IMPACT PROTECTION - RH <i>new</i>	\$ 23.00	✓ 19.76
44	COVER - LH <i>new</i>	\$ 28.00	+
45	COVER - RH <i>damaged</i>	\$ 28.00	+ ✓ 22.24
46	COVER FOR IMPACT PROTECTION - LH <i>new</i>	\$ 19.00	+
47	COVER FOR IMPACT PROTECTION - RH <i>damaged</i>	\$ 19.00	+ ✓ 16.16
48	GAS FILLED STRUT <i>new</i>	2 \$ 196.00	+
49	STRIKER - LH <i>new</i>	\$ 43.00	+
50	STRIKER - RH	\$ 43.00	+
51	LID LOCK <i>new</i>	2 \$ 360.00	+
52	BOWDEN CABLE - CENTER <i>new and</i>	\$ 49.00	✓ 41.68
53	COVER <i>damaged</i>	\$ 9.00	✓ 9.60
54	BOWDEN CABLE <i>new</i>	\$ 49.00	+
55	RELEASE LEVER <i>new</i>	\$ 12.00	+
56	LID LOCK CABLE <i>new</i>	\$ 67.00	+
57	SOUND ABS FOR ENGINE BONNET <i>new</i>	\$ 311.00	+
58	FAN FARE HIGH TONE - LH <i>new</i>	\$ 35.00	+
59	FAN FARE LOW TONE - RH	\$ 248.00	+
60	SPRING SHACKLE - LH <i>new</i>	\$ 26.00	+
SUB TOTAL SPARE PARTS		\$	1,611.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	SPRING SHACKLE - RH <i>the in</i>	\$ 26.00	X
62	LED HEADLIGHT - LH <i>Combined</i>	\$ 7,861.00	✓ 6288.80
63	LED HEADLIGHT - RH	\$ 7,861.00	✓ 6288.80
64	LIFT CYLINDER - LH <i>the in</i>	\$ 180.00	X
65	LIFT CYLINDER - RH	\$ 180.00	+
66	LOCK CARRIER WITH MOUNTING FOR RADIATOR <i>RH new</i>	\$ 878.00	→ X
67	A/C CONDENSER WITH DRYER Back	\$ 568.00	✓ 454.00 X NN
68	COOLER FOR COOLANT <i>Not Nec</i>	\$ 576.00	? X
69	RUBBER BUSH - LOWER <i>the in</i>	2 \$ 16.00	+
70	RUBBER BUSH <i>the in</i>	2 \$ 22.00	+
71	ADDITIONAL COOLER FOR COOLANT <i>the in</i>	\$ 444.00	X
72	PREMIX COOLANT <i>the in</i>	4 \$ 81.00	✓ 67.20
73	AIR GUIDE - LH <i>the in</i>	\$ 22.00	? ✓ 19.84
74	AIR GUIDE - RH <i>the in</i>	\$ 22.00	? ✓ 19.84
75	AIR GUIDE - LH <i>the in</i>	\$ 10.00	? ✓ 8.52
76	AIR GUIDE - RH <i>the in</i>	\$ 10.00	? ✓ 8.32
77	AIR GUIDE - UPPER <i>the in</i>	\$ 13.00	? X
78	AIR GUIDE - LOWER <i>Not Nec</i>	\$ 17.00	? X
79	FAN RING <i>the in</i>	\$ 222.00	X
80	RADIATOR FAN WITH CONTROL UNIT <i>the in</i>	\$ 2,107.00	X
SUB TOTAL SPARE PARTS		\$ 21,116.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 8155 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	INTAKE AIRDUCT <i>new</i>	\$ 17.00	+
82	AIR GUIDE <i>new</i>	\$ 48.00	+
83	SEAL <i>new</i>	\$ 12.00	+
84	AIR FILTER <i>3 new</i>	\$ 352.00	x
85	INTAKE HOSE	\$ 85.00	+
86	WINDOW SLOT SEAL WITH TRIM STRIP - LH <i>lt</i>	\$ 259.00	✓ 207.20
87	WINDOW SLOT SEAL WITH TRIM STRIP - RH <i>lt</i>	\$ 259.00	✓ 207.20
88	TRIM STRIP FOR WINDOW GUIDE - LH <i>3 new</i>	\$ 217.00	+
89	TRIM STRIP FOR WINDOW GUIDE - RH	\$ 217.00	+
90	FRONT NUMBER PLATE <i>Bent</i>	\$ 40.00	✓
91	SUNDRIES <i>Nec</i>	\$ 1,000.00	? ✓ 33.44
TOTAL SPARE PARTS		\$ 35,341.00	
TOTAL LABOUR CHARGES		\$ 12,552.00	
GRAND TOTAL		\$ 47,893.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Adrian Lim
10/04/19.0

HP Authorised, 07 without Code Corner
days
10 with Code Corner.
days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant