

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 2751 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER-LH <i>Dented</i>	\$ 708.00	✓ 566
2	FRONT FENDER ATTACHMENT PARTS-LH <i>Not Nec</i>	\$ 65.00	? X
3	FRONT DOOR-LH <i>Dented</i>	\$ 2,279.00	✓ 1823.20
4	FRONT OUTER DOOR SEAL-LH <i>new</i>	\$ 131.00	✓ 102.80
5	BONDING AGENT <i>Not Nec</i>	\$ 42.00	? X
6	CLEANING SOLUTION <i>Not Nec</i>	\$ 63.00	? X
7	APPLICATOR <i>Not Nec</i>	\$ 7.00	? X
8	FRONT DOOR ATTACHMENT PARTS-LH ?	\$ 218.00	? 144.08 ✓
9	FRONT DOOR CATCH-LH <i>new</i>	\$ 89.00	+
10	FRONT EXTERIOR MIRROR MOUNTING-LH <i>new</i>	\$ 871.00	+
11	FRONT MIRROR CAP-LH <i>new</i>	\$ 128.00	+
12	FRONT DOOR HANDLE-LH <i>Regis</i>	\$ 176.00	+
13	FRONT DOOR HANDLE HOUSING-LH <i>Regis</i>	\$ 25.00	+
14	FRONT WINDOW REGULATOR WITHOUT MOTOR-LH <i>new</i>	\$ 220.00	+
15	FRONT WINDOW REGULATOR MOTOR-LH <i>new</i>	\$ 209.00	+
16	FRONT DOOR CONTROL UNIT-LH <i>new</i>	\$ 456.00	+
17	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-LH <i>new</i>	\$ 261.00	+
18	REAR DOOR-LH <i>Dented</i>	\$ 2,279.00	✓ 1823.20
19	REAR OUTER DOOR SEAL-LH <i>new</i>	\$ 117.00	✓ 102.80
20	REAR DOOR CATCH-LH <i>new</i>	\$ 79.00	+
SUB TOTAL SPARE PARTS		\$ 8,423.00	