

ASS. REC. BY:

REF: CS/MSG19006446/KVD39

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

merimen

From (Person):

Jasmine Lok Hung Kwai

of

MSIG

Date/Time:

10.4.19 4.49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH2208P

Insured:

GBG 2934G

at Workshop n/s

Guan Motor Works

Tel:

6453611

of

176 sin ming Drive #02-03

Policy No:

28991566 MKC

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7.4.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time:

11.4.19

Person Contacted:

MSTPW

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 2208P -x
	GBG 2934G -x
12/4/19	Send preli revised via merimen
F/S	85235.27 email & confirmed (Ref 3205.32, 3819)

REF: MSIG

ASSIGNMENT

From: Date: 11/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 2208P

at Workshop n/s: Guan Motor

of 176 Sin Ming Drive # 02-03

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res: Yes or No

Lump Sum: 1.81 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBH 2208P Yr Regn: 03 / 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Dyno C.C. 2P82

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 00314 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: K0Y231 8028770

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 70 R15
R: 145 R13 x 8 (0)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 2 mm

L/Bal: 2 mm

D.O.A: 7/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 07 MAY 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 7/5 - typist

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: merimen

Lump Sum / I.B.I: (\$) 5235.27

Survey Fee:

Transportation

G + HS, SA

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2019 16:58		11 Apr 2019 09:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	D & B CONSTRUCTION PTE LTD, Co. Reg. No.: NA		
Main Claimant:	TECHART GLOBAL PTE LTD, Co. Reg. No.: 201008540W		
Vehicle Reg. No.:	GBH2208P	Date of Loss:	07/04/2019 00:00 - :59 [12 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28991566MKC (Comprehensive) Coverage: 17/07/2018 - 16/07/2019
Vehicle Reg. No. (Insured):	GBG2934G	Policy No. (Claimant):	
		Excess:	
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/04/2019]		
Driver/Custodian (Insured):	HASAN KAMRUL (26 / Male), NRIC: G2178414T, Tel: +6581959407 Email:		
Adj Asg. Remarks:	on WP. (MANUAL ASSIGNED) SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (KENNETH KONG) LIABILITY:100% CONTACT: AH HENG 6453 6111		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	Jasmine Lok Kheng Kwei	Date:	12 Apr 2019
-------	------------------------	-------	-------------

Preliminary Advice

Insured Vehicle No	: GBG2934G	Accident Date	: 07/04/2019
TP Vehicle No	: GBH2208P	Assignment Date	: 11/04/2019
Make	: TOYOTA DYNA	Est. Duration of Repair	: 5.00
Date of Inspection	: 11/04/2019		
Inspection At	: GUAN MOTOR WORKS (HQ) 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,440.59
Revised Amount	:S\$	4,419.20
Check Items (Estimated)	:S\$	1,985.57
Total	:S\$	6,404.77

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is economical/not economical for repair.

☒ The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Wednesday, 10 April 2019 4:49 PM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Crystal Lee
Subject: Survey Request - Manual Assigned

TP PRE-REPAIR FOR GBH2208P DOA: 07/04/2019 OUR REF: GBG2934G

Manual Assigned

Dear LKK

Please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Venessa Chan
Sent: Wednesday, 10 April, 2019 3:32 PM
To: Willow Tuang <wtuang@gmail.com>
Cc: Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>
Subject: TP PRE-REPAIR FOR GBH2208P DOA: 07/04/2019 OUR REF: GBG2934G

Dear Sir/Madam,

Thank you for your selection of **LKK Auto Consultants Pte Ltd -Kenneth Kong**.

We will proceed to appoint **LKK Auto Consultants Pte Ltd -Kenneth Kong** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol

Thank you.

Have A Great Week Ahead!

Venessa Chan

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | venessa_chan@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Willow Tuang [<mailto:wtuang@gmail.com>]

Sent: Wednesday, 10 April, 2019 3:26 PM

To: Venessa Chan <venessa_chan@sg.msig-asia.com>

Subject: Re: TP PRE-REPAIR FOR GBH2208P DOA: 07/04/2019 OUR REF: GBG2934G

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir

We refer to your email of even date.

We are agreeable of appointing KENNETH KONG as a Single Joint Expert.

Our client's vehicle is available for pre-repair survey at:

Venue	:	Guan Motor Works
		176 Sin Ming Drive #02-03
		Sin Ming AutoCare
		Singapore 575721
		Tel: 6453 6111 (AH HENG)

Regards

Tuang Willow

CK TEO & CO

Tel: 65354788

Fax: 65354245

On Wed, Apr 10, 2019 at 1:27 PM Venessa Chan <venessa_chan@sg.msig-asia.com> wrote:

Dear Sir/Madam,

We refer to your fax on 10.04.19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors**

This Fast-Lane Settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house survey

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

- 1 Calvin Ang
- 2 Kenneth Kong
- 3 Marcus Chua
- 4 Henry Ng
- 5 Lau Kwok Kwong
- 6 Frankie Pang
- 7 Ng You Han
- 8 Gary Soon
- 9 Chow Bo Xiong
- 10 Axel Lee

NB:

(a) ***Fast-Lane Settlement is not applicable for cases that liability is in dispute***

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Thank you.

Have A Great Week Ahead!

Venessa Chan

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | venessa_chan@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/04/2019 17:07
Date Of Accident	07/04/2019 09:30
Exact Location Of Accident	MANDAI CONNECTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH2208P
Insured/Policyholder	
Name Of Registered Owner	TECHART GLOBAL PTE LTD
Co Reg No	201008540W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA-3.0 D TURBO M/T 2WD (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z19VC05001859
Cover Note Number	
Driver	
Name of Driver	MALLIGA PALRAJ DURAIRAJ
NRIC No	G2512776K
Date Of Birth	08/03/1990
Occupation	OUTDOOR
Date Of Driving Pass	31/01/2018
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98111484
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 32 MANDAI ESTATE #05-09
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBU2934G
Vehicle Make/Model/Colour	FUSO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HASAN KAMRUL
NRIC/Passport Number	
Contact Number	81959407
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report as the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (i) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Receiving Centre Personnel's Signature
Name:
NIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN

Mr. 113

13. **GROUPS OF ORDER 15**

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

07/04/2019 morning, 9:30 Am Stationary whilst waiting,
Car B swerved and ~~hit~~ hit my car front part of car A

Video footage is included.

DECLARATION

Publication's Signature
Date & Time:

Once a signature
of user is on the collection
Once 2 Times



源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBH2208P

No.	Qty	List Items	
1	1	Front bumper	\$ CM 727.10 ✓
2	1	Front bumper inner bracket	\$ R 292.10 X
3	2	Headlamp	d/s \$ 2,290.20 ✓ + 1145.10
4	1	Front grille	\$ CM 673.10 ✓
5	1	Front grille centre "TOYOTA" logo	\$ M 97.10 ✓
6	1	Front LH corner panel	\$ R 258.10 X
7	1	Front wiper panel	\$ B 405.23 ✓
8	1	Front LH wiper arm	\$ L 75.23 X
9	1	Front wiper linkage	\$ L 357.23 X
10	1	Front wiper motor	\$ L 509.00 X
11	1	Front panel	\$ B 1,244.10 ✓
12	1	Front "DYNA" sticker	\$ M 84.10 ✓
13	1	Front windscreen moulding	\$ M 248.20 ✓
			\$ 7,260.79
Less 25%			\$ 1,815.20
Total :			\$ 5,445.59

Special Nett Items

14	1	Front number plate	\$ L 45.00 X
----	---	--------------------	--------------

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,200.00 600
2	To putty and spray Spray Paintings charges.	\$ 1,100.00 750
3	To remove, refit front windscreen glass.	\$ 140.00 60
4	To check wirings and lightings.	\$ 40.00 20
5	To remove, refit dashboard assy	\$ 250.00 220
6	To remove, refit air con blower/evaporator unit, including refill air con gas.	\$ 140.00 100
7	To supply and apply anti rust treatment	\$ 80.00 60
Total :		\$ 2,950.00

Total Parts and Labour : \$ 8,445.59

Signature
15/4/19

Not Authorised

Presurvey Bk repair

5 days

8 5235.27

UK Auto Consultants hence notify the Repainer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repainer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2019 16:58		11 Apr 2019 09:30 Edit Adj Rpt	S\$5,235.27 Edit Estimates	S\$5,235.27 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	D & B CONSTRUCTION PTE LTD , Co. Reg. No.: NA								
Main Claimant:	TECHART GLOBAL PTE LTD , Co. Reg. No.: 201008540W								
Vehicle Reg. No.:	GBH2208P	Date of Loss:	07/04/2019 10:00 - :59 [12 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 590608	Policy/Cover Note No.:	A28991566MKC (Comprehensive) Coverage: 17/07/2018 - 16/07/2019						
Vehicle Reg. No. (Insured):	GBG2934G	Policy No. (Claimant):							
		Excess:							
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/05/2019]								
Driver/Custodian (Insured):	HASAN KAMRUL (26 / Male) , NRIC: G2178414T, Tel: +6581959407 Email:								
Adj Asg. Remarks:	on WP. (MANUAL ASSIGNED) SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (KENNETH KONG) LIABILITY:100% CONTACT: AH HENG 6453 6111								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH2208P (590608)
[GBG2934G]
TP
TECHART GLOBAL PTE LTD
Apr 7 2019 10:00AM
[D & B CONSTRUCTION PTE LTD]
Guan Motor Works

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/19 14:16	Adjuster Immediate Advice	Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/05/19 11:33	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/05/19 11:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	07/05/19 11:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	07/05/19 11:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	07/05/19 11:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	07/05/19 11:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	07/05/19 11:35	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/04/19 16:46	E-FILE REPORT (GBG2934G)	Load PDF	
2	10/04/19 16:46	E-FILE REPORT (GBH2208P)	Load PDF	
3	10/04/19 17:01	TP PRI & ACCDT REPORT	Load PDF	
4	11/04/19 08:33	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (KENNETH KONG)	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	11/04/19 09:25	email - manual assign	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-----------------------	----------------------	-----------------------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006446/KVD3Q2

Date: 08/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28991566MKC

Claimant Vehicle No: GBH2208P

Insured Vehicle No: GBG2934G

Date of Loss: 07/04/2019

Nature of Claim: TP

Claim No: 590608

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH2208P

Make & Model: TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)

Engine No: 1KD2697035

Reg. Date: 08/03/2018 (Man. Year: 2017)

Chassis No: KDY2318028770

Colour: Silver

Odometer: 314 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70 R15

Rear Tyre Size: 145 R13X8 (D)

Front Left Side: Bridgestone 2 mm

Rear Left Side: Bridgestone 2/2 mm

Front Right Side: Bridgestone 2 mm

Rear Right Side: Bridgestone 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,490.59	3,425.27	2,065.32	37.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,810.00	1,140.00	38.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	8,440.59	5,235.27	3,205.32	37.98

INSPECTION

Date of Assignment: 11/04/2019

Date Inspected: 11/04/2019 Inspected At:

Guan Motor Works (HQ)
176 Sin Ming Drive #02-03 Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 May 2019)	
Parts:	N/A	TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH2208P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	727.10 FL	*698.10 FL
2	1		*FRONT BUMPER INNER BRACKET	Repair	292.10 FL	*- FL
3	1		*HEADLAMP	Mtg Cracked	2,290.20 FL	*1,145.10 FL
4	1		*FRONT GRILLE	Cracked	673.10 FL	*645.10 FL
5	1		*FRONT GRILLE CENTRE TOYOTA LOGO	Necessary	97.10 FL	*97.10 FL
6	1		*FRONT LH CORNER PANEL	Repair	258.10 FL	*- FL
7	1		*FRONT WIPER PANEL	Bent	405.23 FL	*405.23 FL
8	1		*FRONT LH WIPER ARM	Serviceable	75.23 FL	*- FL
9	1		*FRONT WIPER LINKAGE	Serviceable	357.23 FL	*- FL
10	1		*FRONT WIPER MOTOR	Serviceable	509.00 FL	*- FL
11	1		*FRONT PANEL	Bent	1,244.10 FL	*1,244.10 FL
12	1		*FRONT DYNA STICKER	Necessary	84.10 FL	*84.10 FL
13	1		*FRONT WINDSCREEN MOULDING	Necessary	248.20 FL	*248.20 FL
14	1		*FRONT NUMBER PLATE	Serviceable	45.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	7,305.79	4,567.03
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,815.20	1,141.76
Total Parts (\$\$)	5,490.59	3,425.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES FOR REMOVE/REFIT ,CUTTING ,WELDING AND REPLACEMENT OF DAMAGES	New	1,200.00	600.00
2	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	1,100.00	750.00
3	TO REMOVE,REFIT FRONT WINDSCREEN GLASS	New	140.00	60.00
4	TO CHECK WIRING AND LIGHTINGS	New	40.00	20.00
5	TO REMOVE,REFIT DASHBOARD ASSY	New	250.00	220.00
6	TO REMOVE,REFIT AIR CON BLOWER /EVAPORATOR UNIT,INCLUDING REFILL AIR CON GAS	New	140.00	100.00
7	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	60.00
Gross Labour Cost (\$\$)			2,950.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >