

ASS. REC. BY:

REF: CS/FCI 9006449/TIVd3

n2

Special Instruction:

Surveyor:

Tautik

ASSIGNMENT (Office)

CWS

From (Person):

Hunny KAO

of

FCI

Date/Time: 10.4.19 5.20p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 7187M

Insured:

SHA 9088M

at Workshop m/s

Ding Automotive

Tel:

98912489

of

Blk 10 Sin Ming Industrial Estate Setor C # 01-20

Policy No:

Claim No: D19002368 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A 8.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 11.4.19

Person Contacted:

nelson

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	Blk 31 corporation road Singapore
	SHC 7187M - CS/FCI 18069657 / T1sd 302	649825 D.O.A - 26/5/2018
	SHA 9088M - CS/FCI 18019605 / T1td 302	D.O.A - 24/10/2018
15/4/19	Email preli revised to FCI	
7/5/19	Final fig \$ 4557.36 confirmed by email	(Red 2799.74, 389)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19002368MFSH

Our ref: CS/FCI19006449/T1vd3

Date: 15/4/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SHC 7187M


We thank you for your instruction on 10/4/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/4/2019 at the premises of M/s DING AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,676.44
Revised Estimate Amount	: S\$2,966.70
"Check" Items Amount	: S\$
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	09-04-2019	Our Ref No. D19002368MFSH
Accident Date	08-04-2019	Claim Type. Third Party
Insured Vehicle	SHA9088M	Third Party Vehicle. SHC7187M
Survey Location	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C#01-20	
Contact Person.	NELSON WONG	
Contact No.	62657130/ 98912489	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	DING AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 7 May 2019 12:12 PM
To: taxiscs@stengg.com; SUR
Subject: RE: 50111550-SHC7187M - Finalize Amount & After Repair Photo

Dear Alex,

WITHOUT PREJUDICE

Confirmed finalize amount \$4557.36 @ 5 working days.

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: taxiscs@stengg.com <taxiscs@stengg.com>
Sent: Monday, 6 May 2019 3:56 PM
To: SUR <sur@lkkauto.com>
Subject: Re: 50111550-SHC7187M - Finalize Amount & After Repair Photo

Dear Officer ,

kindly refer attachment .

From: Taxis Customer Service/KAS/CBG/ST Kinetics
To: sur@lkkauto.com
Date: Mon 06 May 2019 03:54 PM
Subject: 50111550-SHC7187M - Finalize Amount & After Repair Photo

Dear Officer ,

Please see below for the finalize according to our conversion to finalize for **SHC7187M**

Please refer below attachment & estimate & after paint for **SHC7187M**

Please refer supplementary form & alignment report .

Total Repair - 5 Days

Part by Part Repair

LABOUR = \$1760

S/N = \$200

PARTS AFTER AAA -25% =\$2597.36

TOTAL (L+S+P) = \$4557.36

FINALIZE AMOUNT = \$4557.36

Thank You

Best Regards
Ding Automotive Pte Ltd
ARC
Alex Khong
Hp : 83039588 / 62657130

[attachment "AF 15.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 14.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 13.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 11.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 10.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 9.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 8.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 7.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 6.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 5.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 4.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 3.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 2.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics] [attachment "AF 1.jpg" deleted by Taxis Customer Service/KAS/CBG/ST Kinetics]

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 15 April 2019 8:42 AM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002368MFSH/1, SHC 7187M
Attachments: SHC 7187M PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 7187M
Date of survey: 11/4/2019
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 12 April 2019 8:31 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002368MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 10 April 2019 5:20 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002368MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SHC7187M		
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1 :	Air-Con (Taxi)		
Vehicle Scheme :	Taxi (Company)		
Vehicle Make :	TOYOTA		
Vehicle Model :	PRIUS HYBRID 1.8 CVT		
Chassis No. :	JTDKB3FU203557540		
Propellant :	Petrol-Electric		
Engine No. :	2ZRS044758		
Motor No. :	1NMS044758		
Engine Capacity :	1798 cc		
Power Rating :	53.0 kW		
Maximum Power Output :	90.0 kW (120 bhp)		
Maximum Laden Weight :	1790 kg		
Unladen Weight :	1375 kg		
Year Of Manufacture :	2017		
Original Registration Date :	31 May 2017		
Lifespan Expiry Date :	30 May 2025		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
PQP Paid :	\$40,532.00		
COE Expiry Date :	30 May 2025		
Road Tax Expiry Date :	31 May 2019		
PARF Eligibility Expiry Date :	30 May 2025		
Inspection Due Date :	31 May 2019		
Intended Transfer Date :	09 Apr 2019		
CO2 Emission :	87.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$27,610.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 31 May 2019. You may renew the road tax from 01 Mar 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 31 May 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 01 Jun 2019 to 30 Nov 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	510.00	-	510.00
Total Amount Payable :			535.00
Message			
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO : MS First Capital Insurance Limited

FAX NO:

ESTIMATE REPORT 1ST Quotation

09/04/2019 18:46

JOB-NO: 50111550

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7187M

TRANS: AUTO

CHASSIS: JTDKB3FU203557540

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZRS044758

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: OD

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REPAIR REAR DOOR LH & REAR BUMPER . STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	600. 650
2 REMOVE & REFIX REAR WINDSCREEN	1.00	150.00	0.00	150.00		Y	X nh
3 REMOVE & REFIX REAR SEAT & SPARE TYRE COMPARTMENT TRIM	1.00	180.00	0.00	180.00		Y	60.
4 TO RUST PROOFING ON ACCIDENT AFFECTED AREAS	1.00	120.00	0.00	120.00		Y	30.
5 TO CONDUCT CHECK WHEEL ALIGNMENT	1.00	100.00	0.00	100.00		Y	60.
6 RESPRAY REAR BUMPER & REAR BUMPER LOWER RH	1.00	500.00	0.00	500.00		Y	300.
7 RESPRAY REAR FENDER RH & REAR DOOR RH	1.00	500.00	0.00	500.00		Y	400.
8 RESPRAY SIDE SKIRT RH	1.00	250.00	0.00	250.00		Y	X nh
9 TO DIAGNOSE CHECK & CLEAR FAULT CODE	1.00	180.00	0.00	180.00		Y	100.
TOTAL:		2,980.00	0.00	2,980.00			
MATERIALS							
1 REAR BUMPER RETAINER RH	1.00	92.30	23.08	69.22	L	Y	X nh
2 REAR BUMPER LOWER COVER RH	1.00	154.60	38.65	115.95	L	Y	RY
3 REAR WHEEL RIM RH	1.00	1,555.60	388.90	1,166.70	L	Y	cut ✓ cut
4 REAR FENDER RH	1.00	899.43	224.86	674.57	L	Y	RY
5 REAR TYRE RH	1.00	320.00	0.00	320.00	S	Y	X nh
6 REAR DOOR BOOKING STICKER RH	1.00	120.00	0.00	120.00	S	Y	new
7 REAR DOOR GOOGLE PLAY STICKER RH	1.00	80.00	0.00	80.00	S	Y	new
8 REAR WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	X nh
9 REAR FENDER SEALANT RH	1.00	50.00	0.00	50.00	S	Y	X
10 REAR FENDER AIR VENT RH	1.00	50.00	0.00	50.00	S	Y	X
TOTAL:		3,371.93	675.49	2,696.44			
TOTAL PARTS & LABOUR :		6,351.93	675.49	5,676.44			

EXCESS/LOADING: S\$ 0.00

7357.10

No. Of Day: 5

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

* Reusing new parts

DATE OF SURVEY: 11 / 4 / 19

[Signature]
15/4/19

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

SURVEYED BY: Tan

CONTACT NO: 97495749 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DING AUTOMOTIVE PTE LTD
 Blk 10 Sin Ming Industrial Estate Sector C
 #01-20

Singapore 575645
 Tel: 6452 1208 Fax: 6452 0614

TO : MS First Capital Insurance Limited

FAX NO:

ESTIMATE REPORT 1ST Quotation

09/04/2019 18:46

JOB-NO: 50111550

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHC7187M

TRANS: AUTO

CHASSIS: JTDKB3FU203657540

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZR5044758

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: OD

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REPAIR REAR DOOR LH & REAR BUMPER . STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00			Y 600 650
2 REMOVE & REFIX REAR WINDSCREEN	1.00	150.00	0.00	150.00			Y X
3 REMOVE & REFIX REAR SEAT & SPARE TYRE COMPARTMENT TRIM	1.00	180.00	0.00	180.00			Y 60
4 TO RUST PROOFING ON ACCIDENT AFFECTED AREAS	1.00	120.00	0.00	120.00			Y 30
5 TO CONDUCT CHECK WHEEL ALIGNMENT	1.00	100.00	0.00	100.00			Y 60
6 RESPRAY REAR BUMPER & REAR BUMPER LOWER RH	1.00	500.00	0.00	500.00			Y 300
7 RESPRAY REAR FENDER RH & REAR DOOR RH	1.00	500.00	0.00	500.00			Y 400
8 RESPRAY SIDE SKIRT RH	1.00	250.00	0.00	250.00			Y X
9 TO DIAGNOSE CHECK & CLEAR FAULT CODE	1.00	180.00	0.00	180.00			Y 100
TOTAL:		2,980.00	0.00	2,980.00			
MATERIALS							
1 REAR BUMPER RETAINER RH	1.00	92.30	23.08	69.22	L		Y X
2 REAR BUMPER LOWER COVER RH	1.00	154.60	38.65	115.95	L		Y Rx
3 REAR WHEEL RIM RH	1.00	1,565.60	388.90	1,166.70	L		Y 1000 ✓
4 REAR FENDER RH	1.00	899.43	224.86	674.57	L		Y Rx
5 REAR TYRE RH	1.00	320.00	0.00	320.00	S		Y X
6 REAR DOOR BOOKING STICKER RH	1.00	120.00	0.00	120.00	S		Y 100 ✓
7 REAR DOOR GOOGLE PLAY STICKER RH	1.00	80.00	0.00	80.00	S		Y 100 ✓
8 REAR WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S		Y X
9 REAR FENDER SEALANT RH	1.00	50.00	0.00	50.00	S		Y X
10 REAR FENDER AIR VENT RH	1.00	50.00	0.00	50.00	S		Y X
TOTAL:		3,371.93	675.49	2,696.44			
TOTAL PARTS & LABOUR:		6,351.93	675.49	5,676.44			

EXCESS/LOADING: S\$ 0.00

No. Of Day: 5

RE-SURVEY: BEFORE/AFTER PAINTING
 PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 11.14.19

**Resuing new parts*

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR DISP	REV PRICE
SURVEYED BY: <u>Tan</u>							
CONTACT NO: <u>97495749</u> FAX NO: _____							

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

DING AUTOMOTIVE PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645
Tel: 6452 1208 Fax: 6452 0614

Labour \$ 1760
SN \$ 200
Parts \$ 2597.36 After 26%
LSP \$ 4557.36 #

Ding Automotive Pte Ltd

Blk 10 Sin Ming Ind Est Sector C #01-20 Singapore 575645
Tel: 6452 1208 Fax: 6452 0614

Parts Supplementary & Quotation Form

Attention: LKK - Tailor
Vehicle Number: SHC 7187M
Make & Model: Toyota Pro
Works Order Number:
Our Reference Number:

S/NO	PART NUMBER	PARTS DESCRIPTION	QTY	UNIT PRICE	SURVEYOR REMARK	W/S REMARK
1	Left Rear upper arm Rts		1	\$ 349.80	Left	
2	Left Rear lower arm Rts		1	\$ 560.90	Left	
3	Left Rear Knuckle arm Rts		1	\$ 600.95	Left	
4	Left Wheel Bearing Rts		1	\$ 395.90	Left	
5	Labour					
6	Labour	Remove & Refit Rear Undercarriage		\$ 250.00	\$ 160.00 ✓	
7		Necessary				
8						
9						
10						
11						
12						
13						
14						
15						

ESTIMATOR: Alvin 8303 Ally auto motor ARC
DING AUTOMOTIVE PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645
Tel: 6452 1208 Fax: 6452 0614
SURVEYOR: Labour \$160.00
Parts \$1907.55 - 25%
= \$1430.65 #

Stamford Tyres International Pte Ltd

19 Lok Yang Way
Singapore 628635

Phone Number: 6262 3355

Fax Number: 6262 1494

Customer:		Date:	4/13/2019 3:12 PM
Company:		VIN	
License No:	SHC7187M	Technician:	LEONG
Odometer:	272028KM	Order No.:	

VEHICLE ALIGNMENT REPORT

TOYOTA, 2016, PRIUS ZVW50R(Custom)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6°39'	5°00'	6°30'	6°39'
		Right	6°21'	5°00'	6°30'	6°22'
	Camber	Left	-0°22'	-0°55'	0°35'	-0°30'
		Right	-0°55'	-0°55'	0°35'	-0°52'
	Toe	Left	-1°17'	0°00'	0°11'	0°05'
		Right	1°17'	0°00'	0°11'	0°06'
Total		0°00'	0°00'	0°22'	0°11'	
Rear	Camber	Left	-1°23'	-2°00'	-1°00'	-1°14'
		Right	-1°05'	-2°00'	-1°00'	-1°27'
	Toe	Left	0°31'	-0°03'	0°14'	0°06'
		Right	-1°21'	-0°03'	0°14'	0°06'
		Total	-0°50'	-0°05'	0°28'	0°12'
	Thrust Angle		-0°56'	----	----	0°00'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	13°33'	12°05'	12°05'	13°33'	
	Right	13°44'	12°05'	12°05'	13°44'	
Included Angle	Left	13°11'	----	----	13°03'	
	Right	12°49'	----	----	12°52'	
Toe Out On Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Maximum Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Toe Curve Change	Left	----	----	----	----	
	Right	----	----	----	----	
Setback	Front	-1mm	----	----	3mm	
	Rear	9mm	----	----	2mm	
Track Width Diff.		4mm			1mm	
Wheel Base Diff.		-9mm			1mm	
Front Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Rear Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Frame Angle						

Stamford Tyres International Pte Ltd

19 Lok Yang Way
Singapore 628635

Phone Number: 6262 3355

Fax Number: 6262 1494

Customer:		Date:	4/13/2019 9:06 AM
Company:		VIN	
License No:	SHC7187M	Technician:	LEONG
Odometer:	272017KM	Order No.:	

VEHICLE ALIGNMENT REPORT

TOYOTA, 2016, PRIUS ZVW50R(Custom)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	6°46'	5°00'	6°30'	6°50'
		Right	6°37'	5°00'	6°30'	6°38'
	Camber	Left	-0°25'	-0°55'	0°35'	-0°25'
		Right	-0°35'	-0°55'	0°35'	-0°32'
	Toe	Left	-1°23'	0°00'	0°11'	-1°18'
		Right	1°23'	0°00'	0°11'	1°21'
Total		0°00'	0°00'	0°22'	0°03'	
Rear	Camber	Left	-1°44'	-2°00'	-1°00'	-1°44'
		Right	-2°47'	-2°00'	-1°00'	-2°49'
	Toe	Left	0°38'	-0°03'	0°14'	0°36'
		Right	-1°29'	-0°03'	0°14'	-1°26'
		Total	-0°51'	-0°05'	0°28'	-0°50'
	Thrust Angle		-1°03'	----	----	-1°01'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		13°32'	12°05'	12°05'	13°32'
	Right		13°42'	12°05'	12°05'	13°42'
Included Angle	Left		13°07'	----	----	13°07'
	Right		13°07'	----	----	13°10'
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		1mm	----	----	1mm
	Rear		10mm	----	----	11mm
Track Width Diff.			0mm			0mm
Wheel Base Diff.			-9mm			-10mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19006449/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9088M	Veh. Inspected	SHC 7187M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002368MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	10/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU203557540	Colour	YELLOW	
Odometer	272012	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	TRIANGLE	6 mm	
L/H Front Tyre	195/65 R15	TRIANGLE	6 mm	
R/H Rear Tyre	195/65 R15	TRIANGLE	6 mm	
L/H Rear Tyre	195/65 R15	TRIANGLE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/04/2019	Inspection Date	11/04/2019	
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7187M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER RETAINER RH	NOT NECESSARY	92.30	-
1	REAR BUMPER LOWER COVER RH	TO REPAIR SEE LABOUR	154.60	-
1	REAR WHEEL RIM RH	CUT	1,555.60	1,555.60
1	REAR FENDER RH	TO REPAIR SEE LABOUR	899.43	-
1	REAR UPPER ARM RHS (ADDITIONAL)	BENT	349.80	349.80
1	REAR LOWER ARM RHS (ADDITIONAL)	BENT	560.90	560.90
1	REAR KNUCKLE ARM RHS (ADDITIONAL)	BENT	600.95	600.95
1	WHEEL BEARING RHS (ADDITIONAL)	BENT	395.90	395.90
	LESS 25% DISCOUNT		-1,152.37	-865.79
			3,457.11	2,597.36
SPECIAL NETT ITEMS				
1	REAR TYRE RH (SN)	NOT NECESSARY	320.00	-
1	REAR DOOR BOOKING STICKER RH (SN)	NECESSARY	120.00	120.00
1	REAR DOOR GOOGLE PLAY STICKER RH (SN)	NECESSARY	80.00	80.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER SEALANT RH (SN)	NOT NECESSARY	50.00	-
1	REAR FENDER AIR VENT RH (SN)	NOT NECESSARY	50.00	-
			670.00	200.00
LABOUR				
	TO REPAIR REAR DOOR LH & REAR BUMPER. STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER COVER RH AND REAR FENDER RH.		1,000.00	650.00
	REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	REMOVE & REFIX REAR SEAT & SPARE TYRE COMPARTMENT TRIM.		180.00	60.00
	TO RUST PROOFING ON ACCIDENT AFFECTED AREAS.		120.00	30.00
	TO CONDUCT CHECK WHEEL ALIGNMENT.		100.00	60.00
	RESPRAY REAR BUMPER & REAR BUMPER LOWER RH.		500.00	300.00
	RESPRAY REAR FENDER RH & REAR DOOR RH.		500.00	400.00

Report Ref No. CS/FCI19006449/T1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY SIDE SKIRT RH.	NOT NECESSARY	250.00	-
	TO DIAGNOSE CHECK & CLEAR FAULT CODE.		180.00	100.00
	REMOVE & REFIT REAR UNDERCARRIAGE NECESSARY (ADDITIONAL).		250.00	160.00
			3,230.00	1,760.00
GRAND TOTAL			7,357.11	4,557.36
RECOMMENDED COST OF REPAIRS				4,557.36

Report Ref No. CS/FCI19006449/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.