

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

10-Apr-19

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1642 A

1 pc	Bonnet ✓
1 pc	Bonnet insulator X
1 pc	Bonnet lock ✓
1 pc	Bonnet lock bracket ✓
1 pc	Bonnet hinge o/s & n/s ✓
1 pc	Bonnet weatherstrip X
1 pc	Support panel X <i>ngp</i>
1 pc	Front no. plate garnish X
1 pc	Front bumper ✓
1 pc	Front bumper grille lower ✓
1 pc	Front bumper lower moulding ✓
1 pc	Front bumper centre grille ✓
1 pc	Front bumper centre grille cover Upper ✓
1 pc	Front bumper Logo "HYUNDAI" ✓
1 pc	Front bumper lip ✓
1 pc	Front bumper cap hook X <i>ngp</i>
1 pc	Front bumper strip ?
1 pc	Front bumper sponge ?
1 pc	Front bumper reinforcement ✓
1 pc	Front bumper reinforcement lower stiffer ✓
2 pcs	Front bumper o/s & n/s side upper bracket ✓
2 pcs	Front bumper o/s & n/s side retainer ✓
1 pc	Front bumper o/s fog lamp ✓
1 pc	Front bumper o/s fog lamp moulding ✓
2 pcs	Front n/s & o/s headlamp ✓
1 pc	Horn high pitch X
1 pc	Horn low pitch X
1 pc	Washer tank ✓
1 pc	Washer tank motor ✓
1 pc	Front n/s air guard ?
1 pc	Pipe & tube assy ?
1 pc	Air con condenser ?
1 pc	Radiator top air guard ?
1 pc	Radiator ?
1 pc	Blower assy 2
1 pc	Washer tank motor ✓

10-Apr-19

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1642 A

1 pc	Washer tank	X
1 pc	Front under cover	X
2 pcs	Front n/s & o/s fenders	/
2 pcs	Front n/s & o/s fender insulator	X
2 pcs	Front n/s & o/s fender inner shield	/
2 pcs	Front n/s & o/s fender logo "Blue Drive"	/
1 pc	Steering Air bag	/
1 pc	Dashboard- Passenger Air bag	/
1 pc	Dashboard- Driver lower knee air bag	/
1 pc	Dashboard	/
1 pc	o/s curtain air bag	/
1 pc	Front driver seat with air bag	/

Less 20%

\$	-
\$	-
\$	-

S/NETT

1 pc	Front no. plate with casing	X	\$	50.00
1 pc	Front bumper clips	/	\$	48.00
2 sets	Front n/s & o/s fender inner shield clips	/	\$	56.00
1 pc	Coolant 6L	X	\$	80.00
2 sets	n/s & o/s door stickers	/	\$	200.00

Sundry	\$	50.00 20
Top up aircon gas		
To dismantle and replace the front dashboard	\$	450.00 150
To lift engine to facilitate repair	\$	450.00 200
To reset jammed seat belt	\$	250.00 100
To computerize airbag system and reset of the same	\$	300.00 100
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50

Towing Fee

\$50 -

10-Apr-19

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1642 A

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s & n/s chassis member, front n/s & o/s door, front n/s & o/s windscreen pillar.

~~1200~~
\$ 1,600.00

To putty and spray painting on bonnet, front bumper, front n/s & o/s fenders, front o/s & n/s chassis member, front n/s & o/s door, front n/s & o/s windscreen pillar

~~1500~~
\$ 1,800.00

To apply rustproofing on the repaired and replaced panels.

~~100~~
\$ 280.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahz (Ukk)

✓

10/4/19

1705 hrs.

14 Days

P'P

Before Paint photo

LKK Auto Consultant's hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CASH SALE/WORK ORDER

No: AE 4089



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 8-4-19

賣號

Messrs:

Premier

車號

Vehicle No:

SHD 1642A

車型

Model No:

~~Optima~~ 10nic

由

From:

Thomson Rd - SHELL

到

To:

Omega

其他

Remark:

(1 key)

時間

Time:

23:27:00:07:00:47

AMOUNT:

\$

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

收貨人

Received by: