

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

11 APR 2019

E S T I M A T E

Estimate No. : b1 50826		Page No. : 1 of 5
Date Estimated : 11/04/2019		
Prepared By : Joseph Yaguel		

- ESTIMATE REPAIR FOR - Chen Tao 1 PASIR RIS LINK #09-01 Singapore 518185	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM9267P	NS36193	24/04/2014	316iA/4	0

DESCRIPTION		VALUE
Replacing rear bumper panel and attachments, rework tailpanel, etc to knock out dents caused by the accident	850	2,550.00
Spray rear bumper, tailpanel	934	1,781.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	?	271.00
To check electrical wiring systems and lightings at the rear section for proper function.	150	177.00
Sundries	?	150.00
Total Labour 1:		4,929.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER BOTTOM REINFORCEMENT	1	69.80	69.80
REAR BUMPER CENTRE GUIDE	1	32.90	32.90
REAR BUMPER CARRIER (ECE)	1	467.95	467.95
DECORATIVE STRIP (LUXURY LINE)	1	81.20	81.20
RR BUMPER TRIM PANEL PRIMED (LINES)	1	1,058.30	1,058.30
REAR BUMPER LH SIDE GUIDE	1	58.50	58.50
REAR BUMPER RH SIDE GUIDE	1	58.50	58.50
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
Total Parts :			1,847.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50826**
Date Estimated : **11/04/2019**
Prepared By : **Joseph Yaguel**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKM9267P	NS36193	24/04/2014	316iA/4	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>22/4/19 10.30 am</u>	Excess S\$ _____
Surveyor's Name <u>Steve</u>	Sign _____
Surveyor's Tel <u>8322 8813</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail <u>stevchen@lkkauto.com</u>	
No. of Working Days Recommend _____	

3 days
w/ Repaire
Ry bef spy
p/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	:	4,929.00
Parts	:	1,847.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	474.34
Grand Total	:	7,250.69

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **