

ASS. REC. BY:

REP: CS3/SPF/19006493/GSD3

Special Instruction:

Surveyor:

Cue Oney

ASSIGNMENT (Office)

From (Person):

Abdul Rehman

of

SPF

Date/Time:

11/4/19 @ 8:16am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MVT / CS

To Inspect Vehicle No:

JSY 9634

Insured:

QX564

at Workshop m/s:

cadre automobile

Tel:

67477618 / 3612 1774

of

1 Kaki Bukit Ave 6 #02-49

Policy No:

Claim No:

AEMD/105/009/2019/026

Sum Insured:

Excess:

Make of Veh:

D.O.A

10/04/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

10:04am @ 11/4/19

Person Contacted:

Ah Lek

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

JSY 9634 - X

QX564 - X

12/4/19 - called vehicle in arranged.

Do Not Finalise

Surveyor

602

REF:

9PF

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Cadre Auto

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt., Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

JSY 9634

Yr Regn:

2018

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Proton Exora C.C. 15971861

Colour

Red

A/C. Insured / Std / NI / NA

Sp. Reading

4827

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PLIF26YDRJF170595

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55 R16

R: 4

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9 mm

R/Bal.

9 mm

L/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

D.O.I.

12-04-19

Survey held at

w/s

5pm

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4250.

Panel of 4000 - \$5000

RECEIVED 1 JUL 2019

Submit PRS HS \$4,250/- @ 6 days / PRS report
(\$ 4,000.20 Red - 49%)

Recommended repair days - 6, weekends : 2 Total Days: 8

Date/Time, File Pass to?

01/07/19



: Preli. Report

1) Typical



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

220

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format :

PRS

Lump Sum / I.B.I: (\$

4,250/- 45

Nivitha (LKK Auto)

From: Abdul Rahman MOHAMAD SALIM (SPF)
<Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Sent: Thursday, 11 April 2019 8:16 AM
To: admin-d@lkkauto.com
Cc: 'Olivia Lau (LKKAuto)'; Rosalyn TAN (SPF); Frankie THAY (SPF); Hafizul Farhan RAHMAT (SPF)
Subject: Assignment for Pre Repair Inspection of Accident Veh JSY9634 (Malaysian Registered)

Your Ref : JSY9634
Our Ref : AEMD/105/009/2019/026

Sir/Madam,

RTA involving police veh QX56U and other veh JSY9634 on 10 Apr 2019

We refer to the above matter.

Please assign a Pre-Repair Inspection for Vehicle **JSY9634** at the following address:

M/s Cadre Automobile
1 Kaki Bukit Ave 6
#02-49 Autobay @ Kaki Bukit
Singapore 417883

For appointment, please contact **Mr Victor at 67477618**.

Thanks.

Abdul Rahman (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



SINGAPORE POLICE FORCE



T/20190410/2140

1 of 3

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

Report No. T/20190410/2140

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/04/2019 15:46		Vide Report No.:		Station Diary No.: 545	
Informant's Particulars					
Name of Informant: OOI AH CHOO			Address: 24 JALAN JERAU 3 TAMAN PELANGI		
ID Type / ID No.: PASSPORT / A50453302L			Contact No.: Home/Office: 0167556156		Mobile: 91475021
Nationality: MALAYSIAN			Email:		
Sex: Female	Age: 67	Date of Birth: 12/11/1951	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Housewife			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 10/04/2019 13:45	Type of Location: Car Park
Location: Along Road 1 WOODLANDS STREET 12 WOODLANDS STADIUM OPEN SPACE CARPARK LOT 129 & 130				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
JSY9634	Car	PROTON	EXORA	Red		0
QX56L	Car	SUBARU		White		3

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190410/2140

2 of 3

Report No. T/20190410/2140

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

CONTINUATION OF REPORT

Driver Name	OOI AH CHOO	ID No.	A50453302L
Related Vehicle	NIL	Contact No.	0167556156
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 10/04/2019 at 12.45pm at Woodlands Sport Stadium Open Carpark Lot 129 & 130, I had parked my car (Red, Proton Exora) in lot 130 and left for lunch at Marsiling Mall.

On the same day at 1.45pm, I came back to retrieve my car and discovered a white police car (QX56L) had crashed on my car's right side and the police car was partially over the kerb. I saw three police officer wearing office attires standing outside the police car.

One of them a Chinese man wearing spectacles asked me and my husband if were the car owners which I told them that I am. He told me that he was the said police car driver and earlier on, he wanted to do a three-point turn by moving into an empty lot beside my car but it crashed onto my car's right side. No one claimed any injuries at the point of time. My car sustained a serious dent and scratches on the right side from the front to the rear.

Afterwhich, Traffic Police came and interviewed us and the said police car driver. I was advised to make a traffic police report to claim.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999



T/20190410/2140

3 of 3

Report No. T/20190410/2140

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
L/
Sgt 2 MUHAMMAD SHAFUDIN SHAH BIN
EFFENDI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / DDGVT /
Sr Staff Sgt MU WEI JUN
Contact No.: 65476225

Authentication Stamp
NP168

Signature Of Informant:

001 AH CHOO

Date/Time:
10/04/2019 15:46

Classification Of Case:



To Whom It May Concern

ACCIDENT INVOLVING SPF VEHICLE AND PRIVATE VEHICLE

If you wish to make any claim against the Singapore Police Force resulting from a motor vehicle accident, you can write to:-

SPF Accident Claims Section
Automotive Engineering & Management Division
Police Logistics Department
1 Mount Pleasant Road
Block 8 Old Police Academy
Singapore 298333

2 Before you send your vehicle for repair, you can have your vehicle inspected by an appraiser appointed by the Singapore Police Force. If you wish to do so, you can contact the Officer-In-Charge of accident matters (Tel No: 64784840, Fax No: 64784848) to make the necessary arrangements.

3 When submitting your claim, please ensure that the following are enclosed:

- a) Police report
- b) Survey report (if any)
- c) Repair Bill
- d) Original Photographs of damage

4 Nothing in this notice shall be treated as acceptance by the Singapore Police Force of any liability whatsoever for any damage sustained as the result of the accident in which your vehicle and the Police vehicle are involved.

5 If your claim relates to personal injuries, please send your claim to:

The Attorney General
Attorney General's Chambers
1 Upper Pickering Street
Singapore 058288

NP 122



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

EFUAS99T

No. Pendaftaran : JSY9634
No. ID : 820502105640
Nama Pemunya Berdaftar : TAN AI MEI
Alamat : NO 24 JALAN JERAU 3 TAMAN PELAN01
80400 JOHOR BAHRU JOHOR

No. Chasis/No. Enjin : PL1FZ6YDRJF170595 / S4PHVP9637
Buatan>Nama Model : PROTON / EXORA FL 1.6L CVT
Keupayaan Enjin : 1561
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR PELBAGAI UTILITI / 2018
Tarikh Pendaftaran : 30/03/2018
B.D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



SIJIL KENDERAAN MOTOR

JABATAN PENGANGKUTAN JALAN 1987 KANDAR KENDERAAN MOTOR (PENDAFTARAN DAN PELESENAN) 1989

Siapa yang mempunyai atau telah mempunyai lesen
untuk memandu kenderaan motor di bawah undang-undang ini

JSY9634

0101011 bnXFnH
VELO2006 RIYA
SEMIANJUNG

2019
29 OGO

30062018-29082019
1561SP AB RM90.00
PERSENDIRIAN



SIJIL KENDERAAN MOTOR
JABATAN PENGANGKUTAN JALAN 1987 KANDAR KENDERAAN MOTOR (PENDAFTARAN DAN PELESENAN) 1989

bnXFnH

**KAD PENGENALAN
MALAYSIA**
511112-07-5168

MyKad

OOI AH CHOO
NO 24
JALAN JERAU 3
TAMAN PELANGI
80400 JOHOR BAHRU
JOHOR

**WARGA NEGARA
PEREMPUAN**

**LESEN MEMANDU
DRIVING LICENCE**
MALAYSIA

OOI AH CHOO

Warganegara / Nationality: **MALAYSIA**
Kategori / Category: **D**
Tempoh / Validity: **02/12/2018 - 12/11/2020**
Alamat / Address: **24 JUN JERAU 3
TAMAN PELANGI
JOHOR BAHRU
80400 JOHOR
JOHOR**

511112075168

CONFIRMATION OF PURCHASE OF INSURANCE

JPJ Code No. : 30
Cover Note No. : KLMA-332866
Issued Date : 30-08-2018
Transaction Type : NEW INSURANCE (REGISTERED)
Insured : TAN AI MEI
New IC/Old IC : 820502-10-5640
Address : NO 24 JALAN JERAU 3 TAMAN PELANGI 80400 JOHOR BAHRU JOHOR
Contact No. :
Nationality : MALAYSIA

Motor Vehicle

Class	: PRIVATE CAR FOR INDIV	Sum Insured	: RM 73000.00 (Agreed Value - Endorsement 87)
Cover Type	: Comprehensive	Basic Premium	: 1959.75
Cover Period	: 30/08/2018 to 29/08/2019	NCD	: 55.00% (1077.86)
Registration No.	: JSY9634	Excess	: 0.00
Engine No.	: S4PHVP9637	Stamp Duty/Goods and Services Tax	: 10.00 / 0.00
Chassis No.	: PL1FZ6YDRJF170595	Additional Coverage	
Logbook No.	: NIL	NAMED PERSONS -	RM 0.00
Named Driver(s)	1) TAN AI MEI (820502-10-5640) 2) OOI AH CHOO (511112-07-5168)	LEGAL LIABILITY TO PASSENGERS (1401-1650 CC) -	RM 33.75
Make and Model	: PROTON - PROTON EXORA 1.6 (A)	LLOP Legal Liability of Passengers -	RM 7.50
Year of Manufactured	: 2018	BREAKAGE OF GLASS IN WINDSCREEN OR WINDOW (RM 1000.00) -	RM 150.00
Capacity	: 1561 CC	Amount Payable	: 1103.15
Hire Purchase	: AFFIN BANK BERHAD		

Your quotation / policy with effective date starting from 01/01/2018 onwards comes with the following benefits with no additional cost: i. Personal Accident (PA) for Policyholder ii. Medical Expenses for Policyholder iii. Key Replacement iv. Child seat

JPJ Status:

Reply Message : ACCEPTED

Agent Information:

Agent Name : SEAKYIN HOLDINGS MALAYSIA (TTAN094)
Address : 145-1, 2ND FLOOR WISMA SEAKYIN, BATU 2 1/4, JALAN SUNGAI BESI, 56000 KUALA LUMPUR WILAYAH PERSEKUTUAN
Telephone : 03-92220331

Note to Policyholder:

If "Reply Message" is "OK", you may proceed to any JPJ or Pos Malaysia branch to purchase/renew the road tax for your vehicle.
If "Reply Message" is "Pending" or "Rejected", please wait until the next working day before proceeding to any JPJ or Pos Malaysia branch to purchase/renew the road tax for your vehicle. If in the mean time, you would like to check on whether the status of the "Reply Message" has been updated to "OK", please call your agent for an update.

Note: The policy Terms and Conditions remain unchanged subject to No Claim made until expiry of period of insurance.

Note: You should receive the Company's policy within 30 days from inception of risk. If not, please refer to the Company's head office or the nearest branch office.

Note: Anda patut menerima polisi syarikat dalam tempoh 30 hari dari tarikh permulaan tempoh risiko. Jika anda tidak menerima polisi, anda perlu merujuk kepada ibu pejabat syarikat atau mana-mana cawangan syarikat yang berdekatan.

This is computer generated document and no signature is required.

Condition (COB)
 (1) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (7) Deformed (8) Stained (9) Blacked (10) Broken (11) Necessary (12) Missing
 (13) In use (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

ACTION (AC)
 (1) Replace (✓) (2) Repair (X) (3) Check (✓)
 (4) Not Consistent (NC)

Vehicle No:

JSY9634

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	Buc	✓	1150
1317	991654	Frt RH Door Protector	Cut	✓	89
1318	991601	Frt RH Door Hinge	BT	✓	2170
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			38
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender	Buc	✓	680
1107	991744	Frt RH Fender Lamp Inner Shield	Re	✓	98
1108	991752	Frt RH Fender Protector Inner Shield	Clips	✓	46
		Frt RH Wheel Rim	Cut	✓	450

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	X	Repair	
1351	993284	Rear RH Door Protector	Cut	✓	
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

1500
92

No of Items: _____

Assessor: _____

4078

10%: 3670.2

8250.20

28/6/2019

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT R/H FENDER QUARTER GLASS	New - 40	120.00	0.00
2	GUM	R-GL New - 20	50.00	0.00
3	TO REMOVE & REFIT FRONT R/H DOOR, GEAR GLASS MOTOR, LOCK, RUBBER & TRIM BOARD	New - 60	280.00	80.00
4	TO CHECK WHEEL ALIGNMENT	New - 60	150.00	80.00
5	TO CHECK WIRING	New - 30	80.00	30.00
6	TUFF KOTE	New - 60	150.00	0.00
7	PANEL BEATING	New - 600	1,200.00	500.00
8	SPRAY PAINTING	New - 800	1,200.00	600.00
Gross Labour Cost (S\$)		1670	3,230.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

5340.2
20%: 4250
6 Days.


28/6/2019



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION
ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333
ATTN: ABDUL RAHMAN

Ref: CS3/SPF19006493/Gsd3s2

Date: 01-07-2019



Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 56L	Veh. Inspected	JSY 9634
Policy No.	-	Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/026	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	11/04/2019

2. Vehicle Particulars & Condition

Make & Model	PROTON EXORA	c.c	1561
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	PL1FZ6YDRJF170595	Colour	RED
Odometer	4827 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	GOODYEAR	9 mm
L/H Front Tyre	205/55R16	GOODYEAR	9 mm
R/H Rear Tyre	205/55R16	GOODYEAR	9 mm
L/H Rear Tyre	205/55R16	GOODYEAR	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/04/2019	Inspect Date / Time	12/04/2019 (05:00 PM)
Survey held at	CADRE AUTOMOBILE 1 KAKI BUKIT AVE 6 #02-49 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. JSY 9634

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRT RH DOOR	BUCKLED	1,150.00
1	FRT RH PROTECTOR	CUT	89.00
2	FRT RH DOOR HINGE	BENT	170.00
1	ROCKER PANEL SIDE SKIRT CLIPS	NECESSARY	39.00
1	ROCKER PANEL SIDE SKIRT RH	CUT	680.00
1	FRT BUMPER	DEFORMED	590.00
1	FRT RH FENDER	BUCKLED	680.00
1	FRT RH FENDER INNER SHIELD	DEFORMED	98.00
1	FRT RH FENDER INNER SHIELD CLIPS	NECESSARY	40.00
1	FRT RH WHEEL RIM	CUT	450.00
1	REAR RH DOOR	TO REPAIR SEE LABOUR	-
1	REAR RH DOOR PROTECTOR	CUT	92.00
	LESS 10% DISCOUNT		-407.80
			3,670.20
	<u>SPECIAL NETT ITEMS</u>		
1	GUM (SN)	NECESSARY	20.00
			20.00
	<u>LABOUR</u>		
	TO REMOVE & REFIT FRONT R/H FENDER QUARTER GLASS.		40.00
	TO REMOVE & REFIT FRONT R/H DOOR, GEAR GLASS MOTOR, LOCK, RUBBER & TRIM BOARD.		60.00
	TO CHECK WHEEL ALIGNMENT.		60.00
	TO CHECK WIRING.		30.00
	TUFF KOTE.		60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR RH DOOR.		600.00
	SPRAY PAINTING.		800.00
			-
			-
			-
			1,650.00
	GRAND TOTAL		5,340.20

Report Ref No. CS3/SPF19006493/Gsd3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	4,250.00
---	----------

Report Ref No. CS3/SPF19006493/Gsd3s2

NOTES: THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF
\$4,000.00 - \$5,000.00

RECOMMENDED REPAIR DAYS : 6
WEEKENDS : 2
TOTAL DAYS : 8

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.