

Surveyor: MARPEUS

DOI: 11/4/19

Date / Time: 11/4/19

Registered in Merimen: 11/4/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SLN 1590 R

Claim No. : _____

Name of insured : ONG PIT LEE, PHOEP

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II :SS _____ D.O.A: 9/4/19

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____
Driver Tel No. : _____ (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability : _____ % Final ? Yes / No

SLN 1658 C → → →



INSRS: _____
WSP: TAN LIM
Tel: _____
Liability: _____
RMKS: 254F



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

| Date/Time | STAGE | DATE / PIC |
|------------------|------------------------------------|------------|
| <u>16/4</u> | <u>SLN 1658 C X ; SLN 1590 R X</u> | |
| <u>16-4-19</u> | <u>EMAIL 250 LARNEY COME.</u> | |
| <u>16-7-19</u> | <u>FILE PASS TO TYPE MANDATE</u> | |
| <u>25/3/2020</u> | <u>File pass to mk to close.</u> | |

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: 45 \$S 12,000 (9 days) Reduction: 612,7970 (% 51%) Email Call

FINAL SETTLEMENT Date/Time: 4/3/2020 Confirm with: Linnie Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28 If NO or B 28, Ass. Lia: 100%

Repair Cost: CW/AST \$S 12,840.00 6 Year CC or 12000

Loss of Rental (LOR) (4/50) \$S 963 (9 days) x 5100

Loss of Use (LOU): \$S 100 (550 x 2 days)

Loss of Income (LOI): \$S - (5 - x - days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$S -

Medical: \$S -

Disbursement: \$S - (e.g. Tow/Independent)

Legal Cost \$S -

Total: \$S 13,903.00 Global Sum \$S: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 13,903.00 Name 1: TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.) \$S _____ Name 2: _____

Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

20/3/2020

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$320

REF: AIG

ASSIGNMENT

From _____ Date: 11/4/19
 Estimated Cost _____
 OD WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SIE 1658C
 at Workshop n/s: Tan Lim Motor
 of: 1 Defu Lane 6
 Insured: SLN 1590R
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLE 1658C Regn: 7.16
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAT
 Make: Honda Verze c.c. 1496
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 68960 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU11114721
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 62k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 9 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS up 3854F
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 9/4/19 D.O.I. 11/4/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & Rf.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 46603
22/4/19
11/4/19 confirmed n/s \$12,000 with william.
(red \$12,279.70 / 51%)
9 days + 2 Sundays + 1 PH (Good Friday) = 12 days

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Days Of Repair:
 Resurvey No. of Trip: _____
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)
 Report Format : _____
 Lump Sum / I.B.I: (\$)
 Survey Fee: _____
 Transporter: _____
 S + RS: _____
 Photos: _____
 Other: _____
 TOTAL: _____



陳林啤味私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLN1590R
Date of Accident : 09 April 2019

Mr Wang Xiaoxu

Date : 10 April 2019

Estimate To Repair SLE1658C - Honda Vezel 1.5 X
Chassis No : RU11114721

| S/No | Quantity | Description | Amount | |
|---------------------------|----------|------------------------------------------------|---------------|--------|
| <u>LIST ITEMS</u> | | | | |
| 40 | 2 ps | rear cargo door rubber stopper @ \$12.00 | \$ 12 24.00 | X |
| 41 | 1 pc | rear cargo door inner opening garnish handle | \$ 17 170.10 | X |
| 42 | 1 pc | rear cargo door opening lever sensor | \$ 128 128.90 | X |
| 43 | 1 pc | rear cargo door inner rubber mount balancer | \$ 89 89.00 | X |
| 44 | 1 pc | rear licence plate garnish | \$ 295 295.40 | X |
| 45 | 1 pc | rear licence plate garnish H badge | \$ 62 62.10 | X |
| 46 | 2 ps | rear licence plate lamp @ \$49.10 | \$ 98 98.20 | X |
| 47 | 2 ps | rear lamps @ \$456.80 | \$ 913 913.60 | ✓ |
| 48 | 4 ps | rear lamp clip holders @ \$5.00 | \$ 20 20.00 | X |
| 49 | 2 ps | rear lamp panels @ \$265.70 | \$ 531 531.40 | X |
| 50 | 1 pc | rear tools sponge | \$ 480 480.30 | ✓ |
| 51 | 1 pc | rear end panel outer | \$ 565 565.50 | Body ✓ |
| 52 | 1 pc | rear end panel inner trim | \$ 179 179.10 | Bar ✓ |
| 53 | 4 ps | rear end panel inner clips @ \$5.20 | \$ 20 20.80 | X |
| 54 | 1 pc | rear end panel - keyless sensor | \$ 821 821.00 | shd ✓ |
| 55 | 1 pc | rear bumper centre | \$ 721 721.70 | pc ✓ |
| 56 | 1 pc | rear bumper lower diffuser | \$ 288 288.60 | fw ✓ |
| 57 | 2 ps | rear bumper top fastener screw @ \$4.80 | \$ 9 9.60 | X |
| 58 | 2 ps | rear bumper top fastener screw spacer @ \$4.80 | \$ 9 9.60 | X |
| 59 | 8 ps | rear bumper fastener clips @ \$4.50 | \$ 36 36.00 | ✓ |
| 60 | 2 ps | rear bumper side @ \$97.50 | \$ 195 195.00 | sd ✓ |
| 61 | 2 ps | rear bumper side fastener screws @ \$4.40 | \$ 8 8.80 | X |
| 62 | 2 ps | rear bumper side retainers @ \$68.30 | \$ 136 136.60 | X |
| 63 | 1 pc | rear buzzle assy | \$ 356 356.00 | ✓ |
| 64 | 1 pc | rear wiper motor | \$ 515 515.80 | X |
| 65 | 1 pc | rear wiper motor bracket | \$ 45 45.00 | X |
| 66 | 1 pc | rear wiper arm | \$ 60 60.10 | X |
| 67 | 1 pc | rear wiper blade | \$ 53 53.00 | X |
| 68 | 1 pc | rear wiper arm cover | \$ 10 10.50 | X |
| 69 | 1 pc | rear wiper shaft rubber mount | \$ 65 65.00 | X |
| 70 | 1 pc | front bumper reinforcement top garnish | \$ 24 24.20 | X |
| 71 | 1 pc | radiator fan cowling | \$ 125 125.00 | X |
| | | | \$ 20,463.87 | |
| | | Less 20 % | \$ 4,092.77 | |
| | | | \$ 16,371.10 | |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 72 | 1 pc | front licence plate | \$ 80 80.00 | 40 |
| 73 | 1 pc | radiator coolant | \$ 48 48.60 | 30 |
| 74 | 1 pc | rear windscreen glass sealant | \$ 180 180.00 | 40 |

137533
1100264



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLN1590R
Date of Accident : 09 April 2019

Mr Wang Xiaoxu

Date : 10 April 2019

Estimate To Repair SLE1658C - Honda Vezel 1.5 X
Chassis No : RU11114721

| S/No | Quantity | Description | Amount |
|-----------------------------------|----------|-------------------------------------------------------------------------------------------------------------------------|--------------|
| SPECIAL NETT ITEMS | | | |
| 75 | 1 pc | rear windscreen glass inner sponge seal | \$ 150.00 |
| 76 | 1 pc | rear licence plate | \$ 80.00 |
| 77 | 1 pc | rear reverse camera len | \$ 380.00 |
| 78 | 1 set | rear bumper parking sensor | \$ 500.00 |
| | | | \$ 1,418.60 |
| LABOUR & MISC. CHARGES | | | |
| 01 | | To remove and refit rear windscreen glass. | \$ 120.00 |
| 02 | | To rust-proofing of the affected areas. | \$ 200.00 |
| 03 | | To reinstall of rear bumper parking sensor. | \$ 120.00 |
| 04 | | To check electrical lighting concerned. | \$ 80.00 |
| 05 | | To transfer of rear cargo door fittings and perform water seepage test. | \$ 200.00 |
| 06 | | To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas. | \$ 250.00 |
| 07 | | To remove and install reverse camera | \$ 120.00 |
| 08 | | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 3,200.00 |
| 09 | | Putty and spray painting of the affected portion. | \$ 2,200.00 |
| | | | \$ 6,490.00 |
| Total | | | \$ 24,279.70 |



Handwritten notes and corrections on the right side of the table:

- 30
- X
- X
- 200
- ✓
- 100
- 50
- 30
- 60
- 100
- 50
- 1400
- 1700
- 1503264
- 12026.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3854F

Vehicle Details

Vehicle No.: SLE1658C
Vehicle to be Exported: No
Intended Deregistration Date: 10 Apr 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X A
Primary Colour: White
Manufacturing Year: 2016
Engine No.: L15B4034730
Chassis No.: RU11114721
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$21,128.00
Original Registration Date: 11 Jul 2016
First Registration Date: 11 Jul 2016
Transfer Count: 0
Actual ARF Paid: \$11,580.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 10 Jul 2026
PARF Rebate Amount: \$8,685.00

Intended COE Rebate Details

COE Expiry Date: 10 Jul 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$52,301.00
COE Rebate Amount: \$37,918.00
Total Rebate Amount: \$46,603.00

The information contained herein is correct as at 10 Apr 2019

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2017 Dec Porsche Cayman 718 \$283283.



Original Sport Exhaust Under
Agent 5 Years Servicing And
Warranty.
Direct Owner StarAd

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

« Back (1 2 3 4) Next »

Sort by Date Posted 20 results/page

68 vehicles

VEZEL

Advanced Search Submit

| Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|----------|--------------|-------------|----------|-----------|----------|-----------|
| Search Selection | VEZEL | Any | Any | 2016 | Any | Any | Any | Available |
| | Honda Vezel 1.5A X | \$68,800 | \$8,510 /yr | 08-Sep-2016 | 1,496 cc | 38,252 km | SUV | Available |
| 1 Owner! 100% Not A PHV. STA Certification For A Peace Of Mind! High Trade In And In House Financing Available! View Today! | | | | | | | | |
| Posted: 11-Apr-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
| | Honda Vezel 1.5A X | \$67,800 | \$8,060 /yr | 21-Oct-2016 | 1,496 cc | - | SUV | Available |
| 5 Pass, EP Or LTV Pass Welcome To Loan! In House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Viewing And Test Drive Availab... | | | | | | | | |
| 88 Motor Trading | | | | | | | | |
| Posted: 10-Apr-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
| | Honda Vezel 1.5A X | \$63,800 | \$8,160 /yr | 26-May-2016 | 1,496 cc | - | SUV | Available |
| Full Loan Monthly \$1100! 5 Pass, EP Or LTV Pass Welcome To Loan! In-House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! View... | | | | | | | | |
| 88 Motor Trading | | | | | | | | |
| Posted: 10-Apr-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
| | Honda Vezel 1.5A X | \$67,000 | \$8,470 /yr | 08-Aug-2016 | 1,496 cc | - | SUV | Available |
| Elegant Black SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Flexible In House Loan Packages Available. | | | | | | | | |
| Prime Motor & Leasing | | | | | | | | |
| Posted: 10-Apr-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
| | Toyota Camry takes on Volkswagen's Passat | | | | | | | |
| The Toyota Camry offers more legroom for rear passengers, is sportier around corners and has more safety systems but the Volkswagen Passat is more affordable and feels more premium overall. | | | | | | | | |
| Find out more! | | | | | | | | |
| | Honda Vezel 1.5A X | \$62,500 | \$8,510 /yr | 28-Jan-2016 | 1,496 cc | 55,000 km | SUV | Available |
| Elegant White SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Flexible In-House Loan Packages Available. | | | | | | | | |
| Prime Motor & Leasing | | | | | | | | |
| Posted: 10-Apr-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
| | Honda Vezel 1.5A X | \$66,800 | \$8,820 /yr | 13-Apr-2016 | 1,496 cc | 39,750 km | SUV | Available |
| 1 Owner Non Uber. Low Mileage Done, Clean Condition And Low Fuel Consumption, No Hidden Cost, No Gimmicks! Bank Loan / In House Loan Available. Call Our Sales Rep For A Test Drive Now! | | | | | | | | |
| Posted: 10-Apr-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda | | | | | | | | |
| Compare | Honda Vezel 1.5A X | \$64,800 | \$8,440 /yr | 16-May-2016 | 1,496 cc | - | SUV | Available |



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLN1590R
Date of Accident : 09 April 2019

*Not Allowed
make
11/4/19
+ / S \$12,000
through other repair
9 day.*

Mr Wang Xiaoxu

Date : 10 April 2019

Estimate To Repair SLE1658C - Honda Vezel 1.5 X
Chassis No : RU11114721

| S/No | Quantity | Description | Amount |
|-------------------|----------|------------------------------------------------|-------------------|
| LIST ITEMS | | | |
| 01 | 1 pc | bonnet | \$ 1 893.30 |
| 02 | 2 ps | bonnet lock @ \$87.70 | \$ 17 175.40 |
| 03 | 1 pc | bonnet lock cable | \$ 11 42.50 |
| 04 | 1 pc | front support panel | \$ 57 576.20 |
| 05 | 1 pc | front support panel top cover | \$ 85 85.00 |
| 06 | 8 ps | front support panel top cover clips @ \$4.50 | \$ 36 36.00 |
| 07 | 1 pc | front bumper | \$ 801 801.00 |
| 08 | 1 pc | front bumper reinforcement | \$ 321 321.00 |
| 09 | 2 ps | front bumper side retainers @ \$22.00 | \$ 44 44.00 |
| 10 | 8 ps | front bumper clips @ \$4.50 | \$ 36 36.00 |
| 11 | 1 pc | front bumper lower centre air grille | \$ 77 77.50 |
| 12 | 1 pc | front bumper lower | \$ 381 381.00 |
| 13 | 2 ps | front bumper air guide @ \$31.60 | \$ 63 63.20 |
| 14 | 1 pc | front bumper lower splashshield cover | \$ 96 96.80 |
| 15 | 1 pc | front bumper lower air dam rubber | \$ 84 84.90 |
| 16 | 1 pc | front bumper tow cover | \$ 23 23.90 |
| 17 | 2 ps | headlamp (DRL) @ \$1784.50 | \$ 3,569 3,569.00 |
| 18 | 2 ps | headlamp lower bracket @ \$35.00 | \$ 70 70.00 |
| 19 | 1 pc | outdoor temperature sensor | \$ 42 42.60 |
| 20 | 1 pc | outdoor temperature sensor bracket | \$ 15 15.00 |
| 21 | 2 ps | horn @ \$48.60 | \$ 97 97.20 |
| 22 | 1 pc | condenser | \$ 1,376 1,376.50 |
| 23 | 1 pc | radiator grille | \$ 351 351.80 |
| 24 | 1 pc | radiator grille outer garnish | \$ 385 385.00 |
| 25 | 1 pc | radiator grille chrome moulding | \$ 95 95.00 |
| 26 | 1 pc | radiator grille centre bracket | \$ 38 38.70 |
| 27 | 2 ps | radiator grille side bracket @ \$196.00 | \$ 392 392.00 |
| 28 | 1 pc | aircon pipe - condenser to compressor | \$ 210 210.00 |
| 29 | 1 pc | rear cargo door | \$ 1,209 1,209.60 |
| 30 | 1 pc | rear cargo door - vezel badge | \$ 65 65.90 |
| 31 | 1 pc | rear cargo door inner lock - striker | \$ 53 53.50 |
| 32 | 1 pc | rear cargo door - high mount spoiler | \$ 337 337.87 |
| 33 | 1 pc | rear cargo door - high mount third brake light | \$ 258 258.20 |
| 34 | 1 pc | rear cargo door inner trimboard | \$ 194 194.30 |
| 35 | 10 ps | rear cargo door inner trimboard clips @ \$5.20 | \$ 52 52.00 |
| 36 | 1 pc | rear cargo door channel weatherstrip | \$ 192 192.50 |
| 37 | 2 ps | rear cargo door inner trim side @ \$75.60 | \$ 151 151.20 |
| 38 | 2 ps | rear cargo door hinges @ \$69.10 | \$ 138 138.20 |
| 39 | 2 ps | rear cargo door absorber stay @ \$185.10 | \$ 370 370.20 |

Handwritten notes and marks:
 - Next to item 04: *10/*
 - Next to item 17: *holder*
 - Next to item 29: *953*
 - Next to item 29: *2.0/1/19*
 - Checkmarks (X) and lines next to various amounts in the right column.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 16 April 2019 11:32 AM
To: Johnson Chua; 'Wei Shong'; 'Caymen'
Subject: Accident Involving SLE 1658C & SLN 1590R on 09/04/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: SLE 1658C
Our Ref: CC6/AIG19006497/Uea3

Dear Sir/Madam,

Accident Involving SLE 1658C & SLN 1590R on 09/04/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051.

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards.

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher@sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>
Sent: Wednesday, 4 March 2020 9:09 AM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: Confirm instructions - Accident between SLE 1658C (TP) & SLN 1590R (AIG) on 09/04/2019

Claim ref: 43106005485G-003

Dear Khanchna,

Thank you and please proceed.

Best regards,
Chan Kian Meng
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1678
KianMeng.Chan1@aig.com | www.aig.sg

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Tuesday, March 3, 2020 6:08 PM
To: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: [EXTERNAL] Confirm instructions - Accident between SLE 1658C (TP) & SLN 1590R (AIG) on 09/04/2019

This message is from an external sender; be cautious with links and attachments.

Dear Mr. Chan,

We refer to the above matter.

As spoken, mandate has been approved via Merimen for \$14,124.00 (all in).

However, Third party is amicable for settlement as follows:-

| | |
|-------------------------------------------|--------------|
| 1. Cost of Repair (w/GST) | \$ 12,840.00 |
| 2. Loss of Rental (9 days x \$100)(w/GST) | \$ 963.00 |
| 3. Loss of Use (2 days x \$50) | \$ 100.00 |
| Total | \$ 13,903.00 |

The reason for loss of use claim is because the Third party's rental vehicle had a breakdown (as per their e-mail attached).

This is to confirm our telephone conversation today that we can proceed to settle at **\$13,903.00(all in)** since it is within the mandate.

Thank you.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SLE1658C (4310600548SG)**
[SLN1590R]
TP
WANG XIAOXU
Apr 9 2019 5:00PM
[ONG PIT LEE,PHILIP]
Tan Lim Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 14/10/2019 18:35 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14124.00) - SLE1658C - Claim Handler: Chan, Kian Meng

Approved:14124.00.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 4 March 2020 11:20 AM
To: Winnie Tan
Cc: Admin A
Subject: RE: Accident involving SLE1658C (TLM) & SLN1590R (AIG) on 09.04.2019
Attachments: AIG DV.pdf

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement for **(\$13,903.00(all in))**.

We attach herewith a copy of the DV for your further action.

Kindly e-mail the DV to us for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Winnie Tan <winnie.tan@tlmotor.com.sg>
Sent: Friday, 7 February 2020 3:11 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Accident involving SLE1658C (TLM) & SLN1590R (AIG) on 09.04.2019

TLM Ref: TP012042019

LKK Ref: CC6/AIG19006497/UEA3

WITHOUT PREJUDICE

Hi Khanchna,

• Refer to the above.

Any news from your Principal?



Winnie Tan
winnie.tan@tlimotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Khanchna (LKK Auto) [<mailto:khanchna@lkkauto.com>]
Sent: 15 January, 2020 10:53 AM
To: Winnie Tan <winnie.tan@tlimotor.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Accident involving SLE1658C (TLM) & SLN1590R (AIG) on 09.04.2019

WITHOUT PREJUDICE

Dear Winnie,

We are pending for mandate approval from our principal.

We will revert upon approval/instructions from them.

Thank you.

Wishing you a Happy and Prosperous Lunar New Year



Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Winnie Tan <winnie.tan@tlimotor.com.sg>
Sent: Wednesday, 15 January 2020 9:39 AM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Accident involving SLE1658C (TLM) & SLN1590R (AIG) on 09.04.2019

TLM Ref: TP012042019

LKK Ref: CC6/AIG19006497/UEA3

WITHOUT PREJUDICE

Hi Khanchna,

We had yet hear from you.

Look forward to your response.



Winnie Tan
winnie.tan@tlimotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Winnie Tan [<mailto:winnie.tan@tlimotor.com.sg>]
Sent: 21 December, 2019 12:33 PM
To: 'Khanchna (LKK Auto)' <khanchna@lkkauto.com>
Cc: 'Admin A' <admin-a@lkkauto.com>
Subject: Accident involving SLE1658C (TLM) & SLN1590R (AIG) on 09.04.2019

TLM Ref: TP012042019

LKK Ref: CC6/AIG19006497/UEA3

WITHOUT PREJUDICE

Hi Khanchna,

Reference is made to the above & our Johnson Chua's email dated 05 November 2019.

As advised in Johnson's earlier email, the client claimed Loss of Use for that 2 days due to the breakdown of the rental vehicle, which we had convinced our client to claim of use instead of additional 2 days of rental since rental will be more expensive).

As such, solely for the sake of an amicable settlement, please let us have the DV of the following: -

COR \$12,840.00 (agreed)
RF \$ 963.00 (agreed) inclusive of 7% GST
LOU \$ 100.00 (\$50.00 x 2 days)

Total \$13,903.00

Thank you and have a good weekend.



Winnie Tan
winnie.tan@tlimotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Johnson Chua [<mailto:johnson.chua@tlimotor.com.sg>]
Sent: 05 November, 2019 12:38 PM
To: 'Khanchna (LKK Auto)'
Cc: 'Admin A'
Subject: Final Reminder - TLM Ref: TP012042019; LKK Ref: CC6/AIG19006497/UEA3; Accident involving SLE1658C (TLM) & SLN1590R (AIG) on 09.04.2019
Importance: High

Dear Khanchna,

Please resolve this case as soon as possible.

Regards,



Johnson Chua
johnson.chua@tlimotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
1 Defu Lane 6
Singapore 539365
<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Khanchna (LKK Auto) [<mailto:khanchna@lkkauto.com>]
Sent: Wednesday, 23 October 2019 10:45 AM
To: Johnson Chua <johnson.chua@tlimotor.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Final Reminder - TLM Ref: TP012042019; LKK Ref: CC6/AIG19006497/UEA3; Accident involving SLE1658C (TLM) & SLN1590R (AIG) on 09.04.2019

Without Prejudice
(save as to costs)

Dear Johnson,

We refer to the above matter.

We are revoking our offer via e-mail dated 17/10/2019.

We will seek mandate from our principal for the LOU claim and will revert promptly.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Johnson Chua <johnson.chua@tlimotor.com.sg>

Sent: Tuesday, 22 October 2019 11:42 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Final Reminder - TLM Ref: TP012042019; LKK Ref: CC6/AIG19006497/UEA3; Accident involving SLE1658C (TLM) & SLN1590R (AIG) on 09.04.2019

Importance: High

Dear Khanchna,

We refer to our tele-conversation moments ago.

As spoken, our client returned the rental vehicle to us due to vehicle breakdown.

Hence, please resolve this matter and forward your Discharge Voucher to us as soon as possible.

Regards,



Johnson Chua

johnson.chua@tlimotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd

1 Defu Lane 6
Singapore 539365

<http://www.tlimotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Khanchna (LKK Auto) [<mailto:khanchna@lkkauto.com>]

Sent: Tuesday, 22 October 2019 9:17 AM

To: Johnson Chua <johnson.chua@tlimotor.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Final Reminder - TLM Ref: TP012042019; LKK Ref: CC6/AIG19006497/UEA3; Accident involving SLE1658C (TLM) & SLN1590R (AIG) on 09.04.2019

WITHOUT PREJUDICE

Dear Johnson,

The above matter and your e-mail below refers.

Please let us know why rental was not obtained for that 2 days.

Thank you.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-----------------------------------------|---------------|---------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|-------------|-----------------------------------------------------------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 12 Apr 2019 Edit Reg | | 11 Apr 2019 00:00 Edit Adj Rpt | \$512,000.00 Edit Estimates | \$512,000.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | ONG PIT LEE, PHILIP , ID: S1408277H | | | | | | | | |
| Main Claimant: | WANG XIAOXU , ID: S8673854F | | | | | | | | |
| Vehicle Reg. No.: | SLE1658C | Date of Loss: | 09/04/2019 17:00 - :59 [32 Months and 29 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 43106005485G | Policy/Cover Note No.: | 2100506684 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SLN1590R | Policy No. (Claimant): | 5082166297-02 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com | | | | | | | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/04/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG_EXPRESS (14/10/2019): Alert - Adj Mandate Approved (\$514124.00) - SLE1658C - Claim Handler: Chan, Kian... AIG_SG (12/04/2019): Request To Upload TP GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

***SLE1658C (43106005485G)**
[SLN1590R]
 TP
WANG XIAOXU
Apr 9 2019 5:00PM
[ONG PIT LEE,PHILIP]
Tan Lim Motor Pte Ltd

| Upload Documents | | Upload Photos | | Compose New Letter | | Upload Video | | Upload Audio | | View <input type="button" value="View in Browser"/> | |
|--------------------------------|-----------------|-----------------------------------------------------------|--|--------------------|--|--------------|--|--------------|----------|-----------------------------------------------------|-------------------------------------|
| Letters/Correspondences | | | | | | | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | | | | | Thumbnail | Print | | |
| 1 | (Draft) | Third Party Express Settlement - Payment Breakdown | | | | | | | Edit | | |
| Photos/Images | | | | | | | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | Thumbnail | Print | | |
| 1 | 11/04/19 17:48 | Odometer Reading | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 2 | 11/04/19 17:48 | Chassis Number | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 3 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 4 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 5 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 6 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 7 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 8 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 9 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 10 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 11 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 12 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 13 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 14 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 15 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 16 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 17 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 18 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 19 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 20 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 21 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 22 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 23 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 24 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 25 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 26 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 27 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 28 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 29 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 30 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 31 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 32 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 33 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 34 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 35 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 36 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 37 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 38 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 39 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |
| 40 | 11/04/19 17:53 | General View | | | | | | | Load JPG | <input checked="" type="checkbox"/> | |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| | | | | <input checked="" type="checkbox"/> |
| 41 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 84 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 11/04/19 17:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 11/04/19 17:54 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 11/04/19 17:54 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 11/04/19 17:54 | General View |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 96 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 97 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 98 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 99 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 100 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 101 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 102 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 103 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 104 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 105 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 106 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 107 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 108 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 109 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 110 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 111 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 112 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 113 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 114 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 115 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 116 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 117 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 118 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 119 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 120 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 121 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 122 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 123 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 124 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 125 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 126 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 127 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 128 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 129 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 130 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 131 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 132 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 133 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 134 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 135 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 136 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 137 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 138 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 139 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 140 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 141 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 142 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 143 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 144 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 145 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 146 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 147 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 148 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 149 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 150 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 151 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|------------|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 152 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 153 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 154 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 155 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |
| 156 | 11/04/19 17:54 | General View | | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 13/04/19 14:07 | TP ESTIMATE - MARKED | | <input type="checkbox"/> |
| 2 | 15/04/19 11:06 | TP GIA REPORT | | <input type="checkbox"/> |
| 3 | 16/04/19 11:33 | LETTER TO OI | | <input type="checkbox"/> |
| 4 | 06/09/19 13:35 | RENTAL RECEIPT | | <input type="checkbox"/> |
| 5 | 06/09/19 13:35 | LOD | | <input type="checkbox"/> |
| 6 | 03/03/20 17:10 | LKK Survey Report | | <input type="checkbox"/> |
| 7 | 03/03/20 17:20 | Email from TP reason on LOR | | <input type="checkbox"/> |
| 8 | 27/03/20 09:12 | WORKSHOP INVOICE | | <input type="checkbox"/> |
| 9 | 27/03/20 09:12 | AUTHORISATION TO ACT FORM | | <input type="checkbox"/> |
| 10 | 27/03/20 09:12 | Release Voucher | | <input type="checkbox"/> |

| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
|----|----------------|-------------------------------------------|-----------|--------------------------|
| 1 | 12/04/19 13:29 | OI GIA REPORT | | <input type="checkbox"/> |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|----------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 30px; width: 100%;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

| | | | |
|-------------------|---------------------|--------|-----------------------|
| Vehicle No: | SLN1590R (Insd veh) | Model: | HONDA VEZEL 1.5 X (A) |
| | SLE1658C (TP veh) | | |
| Date of Accident: | 09/04/2019 | | |

| | | | | |
|-----------------------|---|------------------------------|----------------------------------------|------------------------------|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No | |
| Repair Estimate | : | \$ | 25,979.28 | |
| Final Repair Cost | : | \$ | 12,840.00 | |
| Loss of Use | : | \$ | 100.00 | 2.00 days at \$50.00 per day |
| Rental (if any) | : | \$ | 963.00 | 9 days |
| LTA / GIA Search Fee | : | \$ | 0.00 | |
| Others: | : | \$ | 0.00 | |
| | : | \$ | | |
| Final Settlement Sum | : | \$ | 13,903.00 | |

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ___100___(%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): ___100___(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

| Payment Instruction: Payee's Breakdown | | |
|----------------------------------------|-----------------------|--------------|
| 1) | Tan Lim Motor Pte Ltd | \$ 13,903.00 |
| 2) | | \$ |
| 3) | | \$ |

JOANNE LEE KHANG MIN

27 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19006497/UKA3Q2
Date: 27/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100506684
Claimant
Vehicle No : SLE1658C **Insured Vehicle No :** SLN1590R
Date of Loss: 09/04/2019 Nature of Claim: TP Claim No: 4310600548SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE1658C**
Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B4034730
Reg. Date: 11/07/2016 (Man. Year: 2016) Chassis No: RU11114721
Colour: White Odometer: 68960 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 17,789.70 | 11,342.64 | 6,447.06 | 36.24 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,490.00 | 3,690.00 | 2,800.00 | 43.14 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 24,279.70 | 15,032.64 | 9,247.06 | 38.09 |
| Approved Total (Overridden) (S\$) | | 12,000.00 | | |
| (S\$) | 24,279.70 | 12,000.00 | 12,279.70 | 50.58 |
| + GST 7.00/7.00% (S\$) | 1,699.58 | 840.00 | 859.58 | 50.58 |
| Nett Amount (S\$) | 25,979.28 | 12,840.00 | 13,139.28 | 50.58 |
| + Loss of Use (2.0 x S\$50.00/day) (S\$) | | 100.00 | | |
| + Car Rental (9.0 x S\$100.00/day + 7.00% GST) (S\$) | | 963.00 | | |
| Nett Liability (S\$) | | 13,903.00 | | |

INSPECTION

Date of Assignment: 11/04/2019
Date Inspected: 11/04/2019 Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365
Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------------------|--------------------|-------------|--------------|
| 1 | 1 | | *BONNET | Repair | 893.30 FL | *- FL |
| 2 | 2 | | *BONNET LOCK | Not Necessary | 175.40 FL | *- FL |
| 3 | 1 | | *BONNET LOCK CABLE | Not Necessary | 42.50 FL | *- FL |
| 4 | 1 | | *FRONT SUPPORT PANEL | Dented / Bent | 576.20 FL | *576.20 FL |
| 5 | 1 | | *FRONT SUPPORT PANEL TOP COVER | Torn | 85.00 FL | *85.00 FL |
| 6 | 8 | | *FRONT SUPPORT PANEL TOP COVER CLIPS | Necessary | 36.00 FL | *36.00 FL |
| 7 | 1 | | *FRONT BUMPER | Torn | 801.00 FL | *801.00 FL |
| 8 | 1 | | *FRONT BUMPER REINFORCEMENT | Bent | 321.00 FL | *321.00 FL |
| 9 | 2 | | *FRONT BUMPER SIDE RETAINERS | Not Necessary | 44.00 FL | *- FL |
| 10 | 8 | | *FRONT BUMPER CLIPS | Necessary | 36.00 FL | *36.00 FL |
| 11 | 1 | | *FRONT BUMPER LOWER CENTRE AIR GRILLE | Torn | 77.50 FL | *77.50 FL |
| 12 | 1 | | *FRONT BUMPER LOWER | Torn | 381.00 FL | *381.00 FL |
| 13 | 2 | | *FRONT BUMPER AIR GUIDE | Not Necessary | 63.20 FL | *- FL |
| 14 | 1 | | *FRONT BUMPER LOWER SPLASHIELD COVER | Torn | 96.80 FL | *96.80 FL |
| 15 | 1 | | *FRONT BUMPER LOWER AIR DAM RUBBER | Not Necessary | 84.90 FL | *- FL |
| 16 | 1 | | *FRONT BUMPER TOW COVER | Not Necessary | 23.90 FL | *- FL |
| 17 | 2 | | *HEADLAMP (DRL) | Holder Cracked | 3,569.00 FL | *3,569.00 FL |
| 18 | 2 | | *HEADLAMP LOWER BRACKET | Cracked | 70.00 FL | *70.00 FL |
| 19 | 1 | | *OUTDOOR TEMPERATURE SENSOR | Not Necessary | 42.60 FL | *- FL |
| 20 | 1 | | *OUTDOOR TEMPERATURE SENSOR BRACKET | Not Necessary | 15.00 FL | *- FL |
| 21 | 2 | | *HORN | Not Necessary | 97.20 FL | *- FL |
| 22 | 1 | | *CONDESER | Punctured | 1,376.50 FL | *1,376.50 FL |
| 23 | 1 | | *RADIATOR GRILLE | Cracked | 351.80 FL | *351.80 FL |
| 24 | 1 | | *RADIATOR GRILLE OUTER GARNISH | Cracked | 385.00 FL | *385.00 FL |
| 25 | 1 | | *RADIATOR GRILLE CHROME MOULDING | Necessary | 95.00 FL | *95.00 FL |
| 26 | 1 | | *RADIATOR GRILLE CENTRE BRACKET | Not Necessary | 38.70 FL | *- FL |
| 27 | 2 | | *RADIATOR GRILLE SIDE BRACKET | Not Necessary | 392.00 FL | *- FL |
| 28 | 1 | | *AIRCON PIPE -CONDENSER TO COMPRESSOR | Not Necessary | 210.00 FL | *- FL |
| 29 | 1 | | *REAR CARGO DOOR | Badly Dented | 1,209.60 FL | *953.00 FL |
| 30 | 1 | | *REAR CARGO DOOR -VEZEL BADGE | Necessary | 65.90 FL | *65.90 FL |
| 31 | 1 | | *REAR CARGO DOOR INNER LOCK -STRIKER | Twisted | 53.50 FL | *53.50 FL |
| 32 | 1 | | *REAR CARGO DOOR -HIGH MOUNT SPOILER | Not Necessary | 337.87 FL | *- FL |
| 33 | 1 | | *REAR CARGO DOOR -HIGH MOUNT THIRD BRAKE LIGHT | Not Necessary | 258.20 FL | *- FL |
| 34 | 1 | | *REAR CARGO DOOR INNER TRIMBOARD | Deformed / Cracked | 194.30 FL | *194.30 FL |
| 35 | 10 | | *REAR CARGO DOOR INNER TRIMBOARD CLIPS | Necessary | 52.00 FL | *52.00 FL |
| 36 | 1 | | *REAR CARGO DOOR WEATHERSTRIP | Twisted | 192.50 FL | *192.50 FL |
| 37 | 2 | | *REAR CARGO DOOR INNER TRIM SIDE | Not Necessary | 151.20 FL | *- FL |
| 38 | 2 | | *REAR CARGO DOOR HINGES | Not Necessary | 138.20 FL | *- FL |
| 39 | 2 | | *REAR CARGO DOOR ABSORBER ASSY | Not Necessary | 370.20 FL | *- FL |
| 40 | 2 | | *REAR CARGO DOOR RUBBER STOPPER | Not Necessary | 24.00 FL | *- FL |
| 41 | 1 | | *REAR CARGO DOOR INNER OPENING GARNISH HANDLE | Not Necessary | 170.10 FL | *- FL |
| 42 | 1 | | *REAR CARGO DOOR OPENING LEVER SENSOR | Not Necessary | 128.90 FL | *- FL |
| 43 | 1 | | *REAR CARGO DOOR INNER RUBBER MOUNT BALANCER | Not Necessary | 89.00 FL | *- FL |
| 44 | 1 | | *REAR LICENCE PLATE GARNISH | Not Necessary | 295.40 FL | *- FL |
| 45 | 1 | | *REAR LICENCE PLATE GARNISH H BADGE | Not Necessary | 62.10 FL | *- FL |
| 46 | 2 | | *REAR LICENCE PLATE LAMP | Not Necessary | 98.20 FL | *- FL |
| 47 | 2 | | *REAR LAMPS | Cracked | 913.60 FL | *913.60 FL |
| 48 | 4 | | *REAR LAMP CLIP HOLDERS | Not Necessary | 20.00 FL | *- FL |

| |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------------|-------------------|------------|------------|
| 49 | 2 | | *REAR LAMP PANELS | Repair | 531.40 FL | *- FL |
| 50 | 1 | | *REAR TOOLS SPONGE | Torn | 480.30 FL | *480.30 FL |
| 51 | 1 | | *REAR END PANEL OUTER | Badly Dented | 565.50 FL | *565.50 FL |
| 52 | 1 | | *REAR END PANEL INNER TRIM | Buckled | 179.10 FL | *179.10 FL |
| 53 | 4 | | *REAR END PANEL INNER CLIPS | Not Necessary | 20.80 FL | *- FL |
| 54 | 1 | | *REAR END PANEL -KEYLESS SENSOR | Shorted | 821.00 FL | *248.50 FL |
| 55 | 1 | | *REAR BUMPER CENTRE | Deformed | 721.70 FL | *721.70 FL |
| 56 | 1 | | *REAR BUMPER LOWER DIFFUSER | Twisted | 288.60 FL | *288.60 FL |
| 57 | 2 | | *REAR BUMPER TOP FASTENER SCREW | Not Necessary | 9.60 FL | *- FL |
| 58 | 2 | | *REAR BUMPER TOP FASTENER SCREW SPACER | Not Necessary | 9.60 FL | *- FL |
| 59 | 8 | | *REAR BUMPER FASTENER CLIPS | Necessary | 38.00 FL | *38.00 FL |
| 60 | 2 | | *REAR BUMPER SIDE | Dented / Deformed | 195.00 FL | *195.00 FL |
| 61 | 2 | | *REAR BUMPER SIDE FASTENER SCREWS | Not Necessary | 8.80 FL | *- FL |
| 62 | 2 | | *REAR BUMPER SIDE RETAINERS | Not Necessary | 136.60 FL | *- FL |
| 63 | 1 | | *REAR BUZZLER ASSY | Cracked | 356.00 FL | *356.00 FL |
| 64 | 1 | | *REAR WIPER MOTOR | Not Necessary | 515.80 FL | *- FL |
| 65 | 1 | | *REAR WIPER MOTOR BRACKET | Not Necessary | 45.00 FL | *- FL |
| 66 | 1 | | *REAR WIPER ARM | Not Necessary | 60.10 FL | *- FL |
| 67 | 1 | | *REAR WIPER BLADE | Not Necessary | 53.00 FL | *- FL |
| 68 | 1 | | *REAR WIPER ARM COVER | Not Necessary | 10.50 FL | *- FL |
| 69 | 1 | | *REAR WIPER SHAFT RUBBER MOUNT | Not Necessary | 65.00 FL | *- FL |
| 70 | 1 | | *FRONT BUMPER REINFORCEMENT TOP GARNISH | Not Necessary | 24.20 FL | *- FL |
| 71 | 1 | | *RADIATOR FAN COWLING | Not Necessary | 125.00 FL | *- FL |
| 72 | 1 | | *FRONT LICENCE PLATE | Cracked | 80.00 FS | *40.00 FS |
| 73 | 1 | | *RADIATOR COOLANT | Necessary | 48.60 FS | *30.00 FS |
| 74 | 1 | | *REAR WINDSCREEN GLASS SEALANT | Necessary | 180.00 FS | *40.00 FS |
| 75 | 1 | | *REAR WINDSCREEN GLASS INNER SPONGE SEAL | Necessary | 150.00 FS | *30.00 FS |
| 76 | 1 | | *REAR LICENCE PLATE | Not Necessary | 80.00 FS | *- FS |
| 77 | 1 | | *REAR REVERSE CAMERA LEN | Not Necessary | 380.00 FS | *- FS |
| 78 | 1 | | *SET REAR BUMPER PARKING SENSOR | Shorted | 500.00 FS | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|------------------------------------------------------------|------------------|------------------|
| Sub Total (\$\$) | 21,882.47 | 14,093.30 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 4,092.77 | 2,750.66 |
| Total Parts (\$\$) | 17,789.70 | 11,342.64 |

| |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND REFIT REAR WINDSCREEN GLASS | New | 120.00 | 120.00 |
| 2 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 200.00 | 100.00 |
| 3 | TO REINSTALL OF REAR BUMPER PARKING SENSOR | New | 120.00 | 50.00 |
| 4 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 80.00 | 30.00 |
| 5 | TO TRANSFER OF REAR CARGO DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST | New | 200.00 | 60.00 |
| 6 | TO DISMANTLE AIR-CON ASSY ,REMOVE AND RENEWAL OF PARTS ,VACUUM AND CHARGE-IN GAS | New | 250.00 | 100.00 |
| 7 | TO REMOVE AND INSTALL REVERSE CAMERA | New | 120.00 | 50.00 |
| 8 | PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 3,200.00 | 1,400.00 |
| 9 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 2,200.00 | 1,780.00 |
| Gross Labour Cost (S\$) | | | 6,490.00 | 3,690.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >