





陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLN1590R  
Date of Accident : 09 April 2019

Mr Wang Xiaoxu

Date : 10 April 2019

Estimate To Repair SLE1658C - Honda Vezel 1.5 X  
Chassis No : RU11114721

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	2 ps	rear cargo door rubber stopper @ \$12.00	\$ 11 24.00
41	1 pc	rear cargo door inner opening garnish handle	\$ 11 170.10
42	1 pc	rear cargo door opening lever sensor	\$ 11 128.90
43	1 pc	rear cargo door inner rubber mount balancer	\$ 11 89.00
44	1 pc	rear licence plate garnish	\$ 11 295.40
45	1 pc	rear licence plate garnish H badge	\$ 11 62.10
46	2 ps	rear licence plate lamp @ \$49.10	\$ 11 98.20
47	2 ps	rear lamps @ \$456.80	\$ 12 913.60
48	4 ps	rear lamp clip holders @ \$5.00	\$ 11 20.00
49	2 ps	rear lamp panels @ \$265.70	\$ 2 531.40
50	1 pc	rear tools sponge	\$ 2 480.30
51	1 pc	rear end panel outer	\$ 3 565.50
52	1 pc	rear end panel inner trim	\$ 3 179.10
53	4 ps	rear end panel inner clips @ \$5.20	\$ 11 20.80
54	1 pc	rear end panel - keyless sensor	\$ 248.50 821.00
55	1 pc	rear bumper centre	\$ 2 721.70
56	1 pc	rear bumper lower Diffuser	\$ 1 288.60
57	2 ps	rear bumper top fastener screw @ \$4.80	\$ 11 9.60
58	2 ps	rear bumper top fastener screw spacer @ \$4.80	\$ 11 9.60
59	8 ps	rear bumper fastener clips @ \$4.50	\$ 2 36.00
60	2 ps	rear bumper side @ \$97.50	\$ 2 195.00
61	2 ps	rear bumper side fastener screws @ \$4.40	\$ 11 8.80
62	2 ps	rear bumper side retainers @ \$68.30	\$ 11 136.60
63	1 pc	rear buzzle assy	\$ 2 356.00
64	1 pc	rear wiper motor	\$ 11 515.80
65	1 pc	rear wiper motor bracket	\$ 11 45.00
66	1 pc	rear wiper arm	\$ 11 60.10
67	1 pc	rear wiper blade	\$ 11 53.00
68	1 pc	rear wiper arm cover	\$ 11 10.50
69	1 pc	rear wiper shaft rubber mount	\$ 11 65.00
70	1 pc	front bumper reinforcement top garnish	\$ 2 24.20
71	1 pc	radiator fan cowling	\$ 11 125.00
		Less 20 %	\$ 20,463.87 \$ 4,092.77
			\$ 16,371.10
<u>SPECIAL NETT ITEMS</u>			
72	1 pc	front licence plate	\$ 1 80.00
73	1 pc	radiator coolant	\$ 2 48.60
74	1 pc	rear windscreen glass sealant	\$ 2 180.00

13753-3  
110026

40  
30  
40



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLN1590R  
Date of Accident : 09 April 2019

Mr Wang Xiaoxu

Date : 10 April 2019

Estimate To Repair SLE1658C - Honda Vezel 1.5 X  
Chassis No : RU11114721

S/No	Quantity	Description	Amount
<b>SPECIAL NETT ITEMS</b>			
75	1 pc	rear windscreen glass inner sponge seal	\$ 150.00
76	1 pc	rear licence plate	\$ 80.00
77	1 pc	rear reverse camera len	\$ 380.00
78	1 set	rear bumper parking sensor	\$ 500.00
			\$ 1,418.60
<b>LABOUR &amp; MISC. CHARGES</b>			
01		To remove and refit rear windscreen glass.	\$ 120.00
02		To rust-proofing of the affected areas.	\$ 200.00
03		To reinstall of rear bumper parking sensor.	\$ 120.00
04		To check electrical lighting concerned.	\$ 80.00
05		To transfer of rear cargo door fittings and perform water seepage test.	\$ 200.00
06		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 250.00
07		To remove and install reverse camera	\$ 120.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 3,200.00
09		Putty and spray painting of the affected portion.	\$ 2,200.00
			\$ 6,490.00
<b>Total</b>			\$ 24,279.70

LTK Auto Consultants hence notify the Repairer of the following:

- To re-survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

30  
X  
X  
200  
✓  
100  
50  
30  
60  
100  
50  
1400  
1700  
15032.64  
12026.