

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

UNIQUE TOURIST SERVICE PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Date: 28/03/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA ALTIS / SGX 6848 Y		
1 pc	front bumper <i>OD ✓</i>	567.40
1 pc	front bumper side retainer <i>NEC</i>	56.80
1 pc	front bumper fog lamp <i>8 MIS ✓</i>	246.70
1 pc	front bumper reinforcement	341.20
1 pc	front fender RH <i>OD ✓</i>	477.70
1 pc	front fender dust cover <i>OD ✓</i>	192.60
8 pcs	front fender dust cover clip <i>NEC ✓</i> @ 2.60	20.80
1 pc	front head lamp assy <i>LOT ✓</i>	765.70
1 pc	front wiper washer tank <i>38</i>	267.40
1 pc	front shock absorber <i>38</i>	567.70
1 pc	front lower arm RH <i>38</i>	576.40
	sub-total	4,080.40
	less 25%	1,020.10
	sub-total	3,060.30
1 pc	alloy rim <i>LOT ✓</i>	480.00
1 pc	tyre - michelin 195/65/R15 <i>NN X</i> s.nett	160.00
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	500.00 1,000.00
	To check wiring system.	20.00 40.00
	To apply rust proofing on affected areas.	NN X 120.00
	To apply waterproof sealant on affected areas.	NN X 120.00
	sub-total	4,980.30

balance brought forward	4,980.30
To remove and install front undercarriage parts to enable repair.	8 220.00
To perform 4 wheels computerised alignment.	60.00 85.00
To apply putty and spray painting on affected areas.	400.00 1,200.00
To replace alloy rims and perform wheel balancing.	NN X 60.00
Towing charges.	NN X 60.00
Total	6,605.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

? photo
Repair days 4
TCGim
hi
28/3/19 1300hrs
97361577