

Co. Reg. No: 201416720C  
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883  
Tel: 6636 9100 Fax: 6636 8113

Date: 10/04/2019

TO: AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way, #07-16  
Singapore 079120

Asher.

Our Customer: Pan GuoHua

Vehicle No: SFN2885

Model: BMW 640i Gran Coupe 4DR

Manufacture Year: 2013 (22/7/2014)

Date of Accident: 10/04/2019

Total Estimate Repair Days: 14

Total Pages: 2

Attn: Motor Claims Department  
Fax: 6415 3727

WBAG A02060DZ12254

Re: Repair Estimate For Third Party Claim against SMJ3328D

| No. | Item Descriptions                                  | Qty | Unit Price | Amount                    | Remarks From Surveyor |
|-----|----------------------------------------------------|-----|------------|---------------------------|-----------------------|
| A.  | Spare Parts                                        |     |            |                           |                       |
| 1   | Front fender LH <i>Painted</i>                     | 1   |            | <del>2081.00</del> \$0.00 | ✓ 956                 |
| 2   | Front fender chrome LH (signal lamp) <i>new</i>    | 1   |            | <del>144.90</del> \$0.00  | ✓ 280                 |
| 3   | Front door LH <i>Painted</i>                       | 1   |            | <del>259.00</del> \$0.00  | ✓ 211                 |
| 4   | Front door outer chrome LH <i>new</i>              | 1   |            | 150.00 \$0.00             | x.                    |
| 5   | Front door inner lock LH <i>new</i>                | 1   |            | 750.00 \$0.00             | x                     |
| 6   | Front door regulator LH <i>Painted</i>             | 1   |            | <del>448.00</del> \$0.00  | ✓ 548                 |
| 7   | Front door regulator motor LH <i>new</i>           | 1   |            | 680.00 \$0.00             | x.                    |
| 8   | Front door trimboard LH <i>new</i>                 | 1   |            | 575.00 \$0.00             | x                     |
| 9   | Front door weatherstrip LH <i>new</i>              | 1   |            | <del>600.00</del> \$0.00  | ✓ 163                 |
| 10  | Front door channel LH <i>new</i>                   | 1   |            | 303.50 \$0.00             | x                     |
| 11  | Front door hinges LH <i>new</i>                    | 2   | 161.80     | 323.60 \$0.00             | x                     |
| 12  | Front door striker LH <i>new</i>                   | 1   |            | 261.80 \$0.00             | x                     |
| 13  | Front door center pillar LH <i>Repair</i>          | 1   |            | Repair \$0.00             | x                     |
| 14  | Front door black sash pillar sticker LH <i>new</i> | 1   |            | <del>248.00</del> \$0.00  | ✓ 105                 |
| 15  | Rocker panel LH <i>Painted</i>                     | 1   |            | <del>1450.00</del> \$0.00 | ✓ 953                 |
| 16  | Rear door LH <i>Painted</i>                        | 1   |            | <del>2119.00</del> \$0.00 | ✓ 2258                |
| 17  | Rear door outer chrome LH <i>new</i>               | 1   |            | 150.00 \$0.00             | x                     |
| 18  | Rear door inner lock LH <i>new</i>                 | 1   |            | 750.00 \$0.00             | x                     |
| 19  | Rear door regulator LH <i>new</i>                  | 1   |            | 748.00 \$0.00             | x                     |
| 20  | Rear door regulator motor LH <i>new</i>            | 1   |            | 680.00 \$0.00             | x                     |
| 21  | Rear door trimboard LH <i>new</i>                  | 1   |            | 475.00 \$0.00             | x                     |
| 22  | Rear door weatherstrip LH <i>new</i>               | 1   |            | <del>600.00</del> \$0.00  | ✓ 173                 |
| 23  | Rear door channel LH <i>new</i>                    | 1   |            | 303.50 \$0.00             | x                     |
| 24  | Rear door hinges LH <i>new</i>                     | 2   | 161.80     | 323.60 \$0.00             | x                     |
| 25  | Rear door striker LH <i>new</i>                    | 1   |            | 261.80 \$0.00             | x                     |
| 26  | Rear door quarter glass moulding LH <i>new</i>     | 1   |            | \$0.00                    | x                     |
| 27  | Rear fender LH <i>Repair</i>                       | 1   |            | Repair \$0.00             | x                     |
| 28  | Rear sports rim LH <i>new</i>                      | 1   |            | 2086.50 \$0.00            | ✓ 1000 (SW)           |
| 29  | Rear absorber LH <i>new</i>                        | 1   |            | \$0.00                    | x                     |
| 30  | Rear control arm LH <i>new</i>                     | 1   |            | \$0.00                    | x                     |
| 31  | Rear upper arm LH <i>new</i>                       | 1   |            | \$0.00                    | x                     |
| 32  | Rear lower arm LH <i>new</i>                       | 1   |            | 518.40 \$0.00             | x                     |
| 33  | Rear knuckle arm LH <i>new</i>                     | 1   |            | 576.80 \$0.00             | x                     |
| 34  | Rear knuckle arm bearing LH <i>new</i>             | 1   |            | 612.40 \$0.00             | x                     |
| 35  | Rear bumper <i>Repair</i>                          | 1   |            | 1890.00 \$0.00            | x                     |
| 36  | Rear bumper side retainer LH <i>new</i>            | 1   |            | 150.00 \$0.00             | x                     |
|     | Total                                              |     |            | \$0.00                    |                       |
|     | Less 10%                                           |     |            |                           |                       |
|     | Sub-Total 1                                        |     |            |                           |                       |

7549  
6784.10 S.N: 1000

Co. Reg. No.: 201416720C  
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883  
 Tel : 6836 9100 Fax : 6636 9113

| No. | Item Descriptions                                                                                         | Qty | Unit Price | Amount     | Remarks From Surveyor |
|-----|-----------------------------------------------------------------------------------------------------------|-----|------------|------------|-----------------------|
| B.  | Spare Parts (S/Nett)                                                                                      |     |            |            |                       |
| 1   | Front door trimboard clip LH <i>piece</i>                                                                 | 10  | \$9.00     | \$90.00    | ✓                     |
| 2   | Rear door trimboard clip LH                                                                               | 10  | \$9.00     | \$90.00    | ✓                     |
| 3   | Rear bumper clip <i>piece</i>                                                                             | 10  | \$9.00     | \$90.00    | ✓                     |
| 4   | Rear tyre LH <i>all on</i>                                                                                | 1   | \$650.00   | \$650.00   | ✓                     |
|     | Sub Total 2                                                                                               |     |            | \$920.00   |                       |
|     | Total for Parts                                                                                           |     |            | \$920.00   |                       |
| C.  | Labour                                                                                                    |     |            |            |                       |
| 1   | To check wiring.                                                                                          |     |            | \$100.00   | 30                    |
| 2   | Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas. |     |            | \$1,400.00 | 1000                  |
| 3   | Spray painting all affected parts & areas.                                                                |     |            | \$2,000.00 | 1200                  |
| 4   | To remove and refit front door glass LH.                                                                  |     |            | \$100.00   | 80                    |
| 5   | To remove and refit rear door glass LH.                                                                   |     |            | \$100.00   | 80                    |
| 6   | To remove and replace rear undercarriage LH.                                                              |     |            | \$350.00   | ✓                     |
| 7   | To check and realign wheels with computerized wheel alignment.                                            |     |            | \$200.00   | 80                    |
| 8   | To spray anti-rust undercoating.                                                                          |     |            | \$100.00   | ✓                     |
|     | Total Labour                                                                                              |     |            | \$4,350.00 |                       |
|     | Total Repair Cost                                                                                         |     |            | \$5,270.00 |                       |

2470.

Yours faithfully,

Aun Teng  
 f Premium Carz Services Pte Ltd

| Surveyor's Details |                           |
|--------------------|---------------------------|
| Name               |                           |
| Contact            |                           |
| Survey Date        |                           |
| Recommender        | Authorize / Not Authorize |
| Before Paint       | Yes / No                  |

Adrian Lim  
 1/3 12/04/19.

07 Days.

total: 10264.10  
 1/5: 8.2k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: