

Date : 10/04/2019

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Xiao Tony

Our Customer : Ling Teck Leng
Vehicle No : SMF6458M
Model : Subaru Forester 2.0I-L
Manufacture Year : 2018
Date of Accident : 9/4/2019
Total Estimate Repair Days : 7
Total Pages : 2

Attn : Motor Claims Department
Email : motor.survey@axa.com.sg

JFISJSKCSJG111752

Re: Repair Estimate For Third Party Claim against GW4405K

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Tail gate <i>Dented</i>	1	\$1,172.80	\$1,272.00	✓
2	Tail gate trimboard <i>new</i>	1	\$280.70	\$280.70	✓
3	Tail gate weatherstrip <i>new</i>	1	\$180.80	\$180.80	✓
4	Tail gate lock <i>new</i>	1	\$178.40	\$178.40	✓
5	Tail gate lower catch <i>new</i>	1	\$54.20	\$54.20	✓
6	Tail gate "Subaru" logo <i>new</i>	1	\$89.20	\$89.20	✓
7	Tail gate "Subaru w/AWD" emblem <i>new</i>	1	\$72.30	\$72.30	✓
8	Tail gate "Forester" emblem <i>new</i>	1	\$72.30	\$72.30	✓
9	Rear bumper w/lower pad <i>Dented</i>	1	\$680.20	\$680.20	✓
10	Rear bumper reinforcement <i>Bent</i>	1	\$370.80	\$370.80	✓
11	Rear bumper side retainer RH <i>new</i>	1	\$36.30	\$36.30	✓
12	Rear bumper side retainer LH <i>new</i>	1	\$36.30	\$36.30	✓
13	Rear bumper tow hook cover <i>new</i>	1	\$24.30	\$24.30	✓
14	Rear bumper lower pad cover LH <i>Dented</i>	1	\$34.30	\$34.30	✓
15	Rear bumper reflector RH <i>new</i>	1	\$52.80	\$52.80	✓
16	Rear bumper reflector LH <i>new</i>	1	\$52.80	\$52.80	✓
17	Rear windscreen moulding <i>new</i>	1	\$84.30	\$84.30	✓
18	Tail lamp RH <i>new</i>	1	\$432.20	\$432.20	✓
19	Tail lamp LH <i>new</i>	1	\$432.20	\$432.20	✓
20	Rear end panel <i>new</i>	1	\$388.90	\$388.90	✓
21	Rear end panel garnish <i>new</i>	1	\$80.30	\$80.30	✓
22	Spare tyre panel <i>new</i>	1	\$532.20	\$532.20	✓
23	Spare tyre board <i>new</i>	1	\$380.80	\$380.80	✓
			Total	\$5,719.40	
			Less 20%	\$1,143.88	
			Sub Total 1	\$4,575.52	
A.	Spare Parts (S/Nett)				
1	Rear bumper clip <i>new</i>	10	\$5.00	\$50.00	30
2	Tail gate trimboard clip <i>new</i>	10	\$5.00	\$50.00	✓
3	Rear end panel garnish clip <i>new</i>	8	\$5.00	\$40.00	✓
4	Reverse sensor set <i>new</i>	1	\$250.00	\$250.00	220
5	Sealant <i>new</i>	1	\$60.00	\$60.00	✓
6	Rear number plate w/casing <i>new</i>	1	\$70.00	\$70.00	✓
			Sub-Total 2	\$520.00	
			Total for Parts	\$5,095.52	

230

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
B.	Labour				
1	To check wiring.			\$100.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,000.00	60
3	Spray painting all affected parts & areas.			\$1,000.00	600
4	To spray anti-rust undercoat.			\$100.00	X
5	To remove and refit rear windscreen glass.			\$120.00	
	Total Labour			\$2,320.00	
	Total Repair Cost			\$7,415.52	

1350

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Adrian Ling
P/P 11/04/19

No of days ??

Total: 3864.96 ✓

(P/P)

04 Days