

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM19006510/Apa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Date: 10-11-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PC 1557Z	Veh. Inspected	SKK 3156B	
	Policy No.	GA448533	Coverage (\$)	0.00	
	Claim No.	S9M01JV8	Excess (\$)	0.00	
	Assign From		Assign Date	11/04/2019	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ B 200	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	WDD2462432J135420	Colour	RED	
	Odometer	131545	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
	L/H Front Tyre	225/45 R17	GOODYEAR	6 mm	
	R/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
	L/H Rear Tyre	225/45 R17	GOODYEAR	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/04/2019	Inspection Date	11/04/2019	
	Survey held at HO BENG TRADING				
		BLK 3020A, UBI ROAD 1 #01-33 SINGAPORE 408714			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				