

Sheet1

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714
 Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526
 Email : chris_chanbebe@hotmail.com

11th APRIL 2019

CHEW RENA
 BLOCK 3020A UBI ROAD 1
 # 01-33
 Singapore 408714

TPAXA
 Xiao Tong

WDD2462432J135420

Accident date: 9th APRIL 2019

Estimated repair cost for vehicle no: SKK3156B MERCEDES BENZ -B CLASS 200 '13

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear boot lid Emble logo		\$60.00 X
2	3	Rear boot lid Emble logo clips	\$3.50	\$10.50 X
3	1	Rear boot lid CNC logo		\$55.00 X
4	1	Rear boot lid lamp-RH		\$525.00 X
5	1	Rear bumper <i>torn</i>		<u>\$1,748.00</u> X <i>1/458</i>
6	1	Rear reverse sensor-SET <i>New</i>		\$500.00 X
7	1	Rear bumper side bracket <i>New</i>		\$118.00 ✓
8	1	Rear bumper side moulding-RH <i>wt</i>		\$138.00 ✓
9	1	Rear fender -RH <i>Dented</i>		\$1,770.00 ✓
10	1	Rear fender inner panel <i>Repair</i>		\$855.00 X
11	1	Rear tail lamp-RH <i>New</i>		\$825.00 X
12	1	Rear R/H wheel bearing hup <i>Best</i>		\$366.00 ✓
13	1	Rear R/H lower arm <i>Best</i>		\$472.00 ✓
14	1	Rear shock absorber-RH <i>New</i>		\$588.00 X
15	1	Rear R/H wheel bearing <i>New</i>		\$385.00 ✓
16	1	rear R/H control arm <i>New</i>		\$747.00 X
17	1	Rear tyre -RH <i>Punctured</i>		\$800.00 <i>250(SN)</i>
18	1	Rear rim-RH <i>wt</i>		<u>\$900.00</u> <i>600(SN)</i>
19	1	Rear R/H door <i>Dented</i>		<u>\$2,150.00</u> <i>1682</i>
20	1	Rear R/H door top moulding		\$225.00 X
21	1	Rear R/H door top moulding rubber <i>New</i>		\$155.00 X
22	1	Rear R/H door top inner rubber		\$128.00 X
23	1	Rear Exhaust <i>New</i>		\$1,523.00 X
24	1	Rear Exhaust chome pipe		\$277.00 X

Door Mirror G/L 608 X *New*
 Door Mirror Cover 255 ✓ *Dented*
 Door Mirror Housing 882 ✓ *Dented*

Subtotal :- \$15,318.60

7534 SN: 850
 6780.60

Labour charges

To remove & re-fix rear undercarriage

To reset computer

To remove rear reverse sensor

To Check Wiring System

Towing charges

Tuff kote

Panel beating

Spray painting

~~\$450.00~~ 220

~~\$200.00~~ x

~~\$120.00~~ 60

~~\$60.00~~ 30

~~\$100.00~~ ✓

2070 ~~\$120.00~~ 60

~~\$1,000.00~~ 8w

~~\$1,000.00~~ 8w

Subtotal :- \$3,050.00

Total:- \$18,368.50

total 9700.60

L/S: 7-7/12

07 Dnp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

3849F

Vehicle Details

Vehicle No.:

SKK3156B

Vehicle to be Exported:

Yes

Intended Deregistration Date:

10 Apr 2019

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

B 200 AT ABS AIRBAGS HID 2WD 5DR 2TPSR

Primary Colour:

Red

Manufacturing Year:

2012

Engine No.:

27091030111809

Chassis No.:

WDD2462432J135420

Maximum Power Output:

115.0 kW (154 bhp)

Open Market Value:

\$28,777.00

Original Registration Date:

28 Jun 2013

First Registration Date:

28 Jun 2013

Transfer Count:

0

Actual ARF Paid:

\$27,288.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Jun 2023

PARF Rebate Amount:

\$19,101.00

Intended COE Rebate Details

COE Expiry Date:

27 Jun 2023

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

QP Paid:

\$67,301.00

COE Rebate Amount:

\$28,359.00

Total Rebate Amount:**\$47,460.00**

The information contained herein is correct as at 10 Apr 2019

OK