

VEHICLE NO. SLV 8202Z

HONDA CIVIC

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Bonnet / <i>one</i>		1072.50	658.8
1	Bonnet inner lock X		121.80	X
1	Bonnet insulator X	REFIX	0.00	X
1	Bonnet inner lock catch X		92.00	X
1	Front centre radiator grille (lower) <i>RR</i>		295.00	188
1	Front centre grille chrome (upper) <i>RR</i>		498.00	150.4
1	Front centre grille chrome badge <i>RR</i>		72.00	45.6
1	Front centre upper panel X <i>NN</i>		482.00	X
1	Front bumper / <i>2e</i>		969.50	597.9
2	Front bumper side retainers X		98.00	X
1	Front bumper centre lower grille X <i>NN</i>		157.50	7
1	Front bumper fog lamp garnish RHS <i>SCR</i>		224.80	65.8
1	RHS Front fender X <i>Repair</i>		671.80	X
1	RHS Front fender inner splash shield X	REFIX	0.00	X
1	RHS Front fender signal lamp X <i>NN</i>		192.00	X
1	RHS Headlamp / <i>SCR</i>		985.20	725.7
1	RHS Headlamp top chrome garnish X <i>NN</i>		219.00	X
			6151.10	
		less 20%	1230.22	20%
			4920.88	
SPECIAL NETT ITEMS				
1set	Front bumper clips / <i>MC</i>		60.00	20
1	Front license plate w/holder X <i>NN</i>		75.00	X
1set	Front centre radiator grille clips / <i>MC</i>		60.00	20
1set	Front fender inner shield clips X <i>NN</i>		60.00	X
1set	Bonnet insulator clips / <i>MC</i>		80.00	10
TOTAL PARTS			5255.88	

VEHICLE NO. SLV 8202Z HONDA CIVIC

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	750.00	600
3	To remove, check/refix wiring system at accident damaged areas and focus headlamp beam	150.00	30
4	To perform anti-rust treatment on affected areas	180.00	X NW
	Labour Total :	2280.00	
	TOTAL (PARTS & LABOUR):	7235.88	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

4 Days.

Unsprung repair.

After repair photos.

Gino Qian - 82880282

12/4/19.

3015.76

net: 2400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: