

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0444/2019/DY
Date : 6-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Sen Sukanti
Address : 5 Rhu Cross
#11-11
Singapore 437434
Telephone : HP +65 91721605
Type of Claim : Own Damage Claims
Policy No. : 2100441770-03
Vehicle No : **SJB 9768 E**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : 23/12/2015
Engine No : CZC 504756
Chassis No : WAUZZZ8V5G1050542
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Apr-19
Place of Accident : Blk 5 Costa Rhu Basement

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJB 9768 E

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To install solar film.		TBC	?
2	To remove and reinstall rear parking aid. Check function.	s/n	\$ 280.00	✓
3	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	s/n	\$ 280.00	✓
4	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	s/n	\$ 600.00	✓
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	s/n	\$1,400.00	✓
SUB-TOTAL LABOUR CHARGES		:	\$ 2,560.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJB 9768 E

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	s/n \$ 1,400.00	✓
7	To dismantle rear bumper, lhs rear door and rear lid. Cut out and weld lhs rear fender and lhs rear outer wheel housing. To renew rear bumper and lhs rear door. Re-organize crash management components. Reinstall all parts removed.	\$ 7,200.00	3500
8	To respray rear bumper, lhs rear door, lhs rear fender, lhs sill panel, lhs rear outer wheel housing, door entrances, roof channel, door handle, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,600.00	3500. 5x550 = 3300 Handle = 100
9	To renew lhs rear rim and carry out wheel alignment.	s/n \$ 280.00	✓
10	To carry out diagnostic check.	s/n \$192.00	✓
TOTAL LABOUR CHARGES		: \$ 17,232.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 9768 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Repair</i>	\$ 1,708.00	X
2	REAR BUMPER FIXING PARTS	\$ 175.00	X
3	REAR BUMPER GUIDE SECTION-LH } <i>men</i>	\$ 60.00	X
4	REAR FENDER-LH <i>Dented</i>	\$ 2,110.00	✓
5	REAR WHEEL HOUSING LINER-LH <i>men</i>	\$ 561.00	X
6	REAR WINDOW ?	\$ 742.00	?
7	REAR SIDE WINDOW ?	\$ 520.00	?
8	REAR DOOR-LH <i>Dented</i>	\$ 2,279.00	✓
9	REAR OUTER DOOR SEAL-LH <i>men</i>	\$ 146.00	✓
10	BONDING AGENT ?	\$ 45.00	?
11	CLEANING SOLUTION ?	\$ 65.00	?
12	APPLICATOR ?	\$ 7.00	?
13	REAR DOOR ATTACHEMENT PARTS ?	\$ 117.00	?
14	REAR DOOR CATCH-LH <i>men</i>	\$ 85.00	X
15	REAR DOOR HANDLE-LH <i>Repair</i>	\$ 331.00	X
16	REAR DOOR HANDLE HOUSING-LH <i>men</i>	\$ 47.00	X
17	REAR ALUMINIUM RIM-LH <i>lit</i>	\$ 651.00	✓
18	RUBBER VALVE <i>men</i>	4 \$ 13.00	X
19	ACRYLIC SEALANT } <i>men</i>	S/N \$ 180.00	✓
20	CAVITY WAX	S/N \$ 140.00	✓
TOTAL SPARE PARTS		\$ 9,982.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No.SJB 9768 E**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
21	STONE CHIP <i>mc</i>	S/N \$ 180.00	✓
22	METAL FILLER POWDER <i>mc</i>	S/N \$ 280.00	✓
23	REAR WINDSCREEN SEALANT <i>mc</i>	S/N \$ 200.00	✓
24	1/4 GLASS SEALANT <i>mc</i>	S/N \$ 100.00	✓
25	SUNDRIES ?	\$ 800.00	
TOTAL SPARE PARTS		\$ 11,542.00	
TOTAL LABOUR CHARGES		\$ 17,232.00	
GRAND TOTAL		\$ 28,774.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 11/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 14 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant