

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Yap, Weijoe

Date: 09 May 2019

**Preliminary Advice**

Vehicle No	: SMD6885Z	Accident Date	: 09/04/2019
Make	: AUDI Q2	Policy No.	: 1800103386
Assignment Date	: 12/04/2019	Excess	: S\$0.00
Date of Inspection	: 11/04/2019	Est. Duration of Repair	: 6 - 8 days
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,853.00 (Inclusive supp 1 + 2)
Revised Amount	:S\$	20,320.00 (Inclusive supp 1 + 2)
Check Items (Estimated)	:S\$	14,665.00 (Inclusive supp 1 )
Total	:S\$	34,985.00

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	52,609.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,391.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Supplementary amount 1 is \$ 9,485.00.  
Supplementary amount 2 is \$ 3,308.00.