

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 15 Apr 2019

Preliminary Advice

Insured Vehicle No : GBD4747H

TP Vehicle No : SJH8405C

Make : HONDA STREAM

Date of Inspection : 11/04/2019

Inspection At : Em Auto Solution Pte Ltd (HQ)
160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722

Accident Date : 09/04/2019

Assignment Date : 11/04/2019

Est. Duration of Repair : 16 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion, o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,499.16
Revised Amount	:S\$	15,554.44
Check Items (Estimated)	:S\$	5,404.40
Total	:S\$	20,958.84

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP