

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19006527/USD3S2**Date:** 26/04/2019REFERENCE

Insured/Claimant: CHAN SUI JUAN Policy No: DMPCSN3089521801
Date of Loss: 09/04/2019 Nature of Claim: OD Claim No: SNM19D201581C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB7935R**
Make & Model: AUDI A4, 1.8 TFSI MU (B8) (A) Engine No: CDH135624
Reg. Date: 28/06/2011 (Man. Year: 2011) Chassis No: WAUZZZ8K6BA172342
Colour: White Odometer: 150610 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$41,500.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	100.00	0.00	100.00	100.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	100.00	0.00	100.00	100.00
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	-1,400.00	-1,500.00	100.00	-7.14
+ GST 7.00/7.00% (S\$)	-98.00	-105.00	7.00	-7.14
Nett Amount (S\$)	-1,498.00	-1,605.00	107.00	-7.14

INSPECTION

Date of Assignment: 12/04/2019 Present Location: Car City Auto Centre Pte Ltd (HQ)
Date Inspected: 12/04/2019 Inspected At: Car City Auto Centre Pte Ltd (HQ)
Estimated Period of Repair: 0.0 days Blk 9006 #01-198, Tampines Street 93
Singapore 528840

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$41,500.00
OMV :	\$31,670.00
PARF Rebate (1) :	\$19,002.00
Quota Premium Paid :	\$63,000.00
COE Rebate (2) :	\$13,860.00
Total Rebate (1) + (2) = :	\$32,862.00

The total amount incurred will be Market Value \$41,500.00 minus Total Rebate \$32,862.00 = \$8,638.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2019)
Parts:	143	AUDI A4 1.8 TFSI MU (B8) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB7935R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	TOWING FROM CAR PARK TO WORKSHOP	100.00	0.00
Sub Total (\$\$)			100.00	0.00

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >