## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Elaine Cheong Date: 15 Apr 2019

# **Preliminary Advice**

Vehicle No : SKB7935R **Accident Date** : 09/04/2019

Make : AUDI A4 Policy No. : DMPCSN3089521801

: 12/04/2019 **Excess** : S\$1,500.00 **Assignment Date** 

Date of Inspection : 12/04/2019 Est. Duration of Repair : -

: Car City Auto Centre Pte Ltd (HQ) Inspection At

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear, n/s rear, front n/s portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	20,000.00 - 25,000.00
Revised Amount	:S\$	TOTAL LOSS

Check Items (Estimated) :S\$

:S\$ **TOTAL LOSS** 

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
TYCW IOI OIG VAIGO	.Οψ

Pre-Accident Value	:S\$	41,500.00
COE / PARF Rebate	:S\$	32,862.00

Salvage Value :S\$

Margin for Repair :S\$ 8,638.00

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage
		Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. ( X )

( X ) Other comments: Rear o/s tyre burst.