



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC6/AXA14021304/Gza3q2

8 SHENTON WAY #27-01 SINGAPORE 068811

Date : 18-08-2016



ATTN:ERNEST TAY

Code : AXA2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBA 9848H	<b>Veh. Inspected</b>	SJT 2942U
<b>Policy No.</b>	P1517953	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>		<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	12/11/2014

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA ESTIME	<b>c.c</b>	2362
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	ACR500094389	<b>Colour</b>	SILVER
<b>Odometer</b>	142236	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/65 R16	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	205/65 R16	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	205/65 R16	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	205/65 R16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	07/11/2014	<b>Inspection Date</b>	12/11/2014
<b>Survey held at</b>	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD Blk C, 3rd Floor SINGAPORE 579701.		

### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**